





### General information

Make	PEUGEOT
Model	206 S
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg





## Internet history

Entry 1		
Date	2021-02-03	
Pictures	10	
Listing price	View report	









source: autoonline.co.uk



### MOT history

MOT #29	2022-12-23 12:41
MOT test number	559828719389
Result	✓ Passed
Next expiry date	2023-12-22
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #28		2021-11-30 12:40
MOT test	number	357434612827
Result		✓ Passed
Advice	Offside Play in steering rack inner joint(s)	
<b>Advice</b> (a) (i))	Front Suspension arm pin or bush worn but not resulting in excessive moveme	ent both sides (5.3.4
Advice	Central Fuel tank slightly loose support strap corroded and broken (6.1.3 (a) (i	))
<b>Minor</b> (6.1.7 (g)	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorate (i))	ed leaking grease
Advice	Coolant leak	
Advice	Items removed from driver's view prior to test	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice floor/stiffe	Offside Vehicle structure is corroded but structural rigidity is not significantly r ning rib (6.1.1 (c) (i))	reduced
Advice	Both rear shock cover gaiters deteriorated	





MOT #27	2021-11-30 12:40
MOT test number	526440292392
Result	🗙 Failed
Advice (a) (i)) Front Suspension arm pin or bush worn but not resulting in excessive movement	it both sides (5.3.4
Advice Central Fuel tank slightly loose support strap corroded and broken (6.1.3 (a) (i))	)
Advice Both rear shock cover gaiters deteriorated	
Advice Offside Play in steering rack inner joint(s)	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
<b>Advice</b> Offside Vehicle structure is corroded but structural rigidity is not significantly refloor/stiffening rib (6.1.1 (c) (i))	duced
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	leaking grease
Advice Coolant leak	
<b>Pass with rectification</b> Headlamp aim too high both sides (4.1.2 (a))	
Advice Items removed from driver's view prior to test	

MOT #26	2020-12-07 15:08
MOT test number	648365492942
Result	✓ Passed
Advice Front and rear passenger head restraints removed	
Advice Front Suspension arm pin or bush worn but not resulting in excessive move (a) (i))	ement both sides (5.3.4
Advice Rear Brakes imbalanced requirements only just met. It would appear that the requires adjustment or repair. 28% (1.2.1 (b) (i))	he braking system
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps of (b) (i))	or light sources (4.7.1
Advice RBT: service brake only 58%	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but p dirt (2.1.3 (g) (i))	reventing the ingress of



MOT #25	2020-12-07 15:08
MOT test number	441173274733
Result	🗙 Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Front and rear passenger head restraints removed	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light s (b) (i))	sources (4.7.1
Advice Front Suspension arm pin or bush worn but not resulting in excessive movement b (a) (i))	ooth sides (5.3.4
Advice RBT: service brake only 58%	
<b>Advice</b> Rear Brakes imbalanced requirements only just met. It would appear that the brak requires adjustment or repair. 28% (1.2.1 (b) (i))	king system
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but prevention dirt (2.1.3 (g) (i))	ng the ingress of
Pass with rectification Offside Headlamp aim projected beam image is obviously income	ect (4.1.2 (c))

MOT #24	2019-12-20 15:04
MOT test	<b>number</b> 255847389955
Result	✓ Passed
Minor dirt (2.1.3	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of (g) (i))
Advice	Play in steering rack inner joint(s) both sides
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b> (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Front Coil spring corroded both sides (5.3.1 (b) (i))

**SL04HFM** 

report date: 2024-03-29





MOT #23 2019-12-	-20 12:42
MOT test number 67129	2901872
Result	🗙 Failed
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (a) (i))	(5.3.4
<b>Fail</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevent ingress of dirt (6.1.7 (g) (ii))	ts the
Advice Nearside Rear Direction indicator slightly affected by the operation of another lamp (4.4.3	(b))
<b>Minor</b> Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingr dirt (2.1.3 (g) (i))	ress of
Advice General under body corrosion	
Advice Front Coil spring corroded both sides (5.3.1 (b) (i))	
Advice Play in steering rack inner joint(s) both sides	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
<b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
<b>Fail</b> Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources ((b) (i))	4.7.1

MOT #22	2019-02-19 15:00
MOT test number	684844199274
Result	✓ Passed

MOT #2	21	2019-02-19 09:51
MOT te	st number	805556303571
Result		🗙 Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail reduced	Offside Front Vehicle structure corroded to the extent that the rigidity of the as d $(6.1.1 (c) (i))$	sembly is significantly





MOT #20		2018-02-22 13:31
MOT test	number	219181958749
Result		✓ Passed
Advice	Offside Rear position lamp(s) slightly affected by the operation of another lan	np (1.1.A.3f)
Advice	Offside Front coil spring corroded (2.4.C.1b)	
Advice	Nearside Rear position lamp(s) slightly affected by the operation of another la	amp (1.1.A.3f)
Advice	Nearside Front coil spring corroded (2.4.C.1b)	

MOT #19	2018-02-22 08:46
MOT test number	438755892731
Result	🗙 Failed
Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Nearside Rear position lamp(s) slightly affected by the operation of a	another lamp (1.1.A.3f)
<b>Fail</b> Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice Nearside Front coil spring corroded (2.4.C.1b)	
Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Rear position lamp(s) slightly affected by the operation of an	other lamp (1.1.A.3f)
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front coil spring corroded (2.4.C.1b)	

MOT #18	2016-05-04 09:21
MOT test number	819460551164
Result	✓ Passed





MOT #17		2016-05-04 09:21
MOT test number		356804498766
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Pass with rectification	Centre Exhaust system not adequately supported (7.1.1)	

MOT #16		2015-05-27 14:46
MOT test	number	208627845411
Result		✓ Passed
Advice	Vehicle structure has slight corrosion (6.1.B.2)	
Notice	Oil leak	

MOT #15	2015-05-15 14:11
MOT test number	267975435424
Result	🗙 Failed
Notice Oil leak	
Fail Rear Torsion bar excessive play at an end fixing (2.4.E.2)	
Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c)	
FailBrake pipe excessively corroded (3.6.B.2c)	
Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive	e movement (2.4.G.2)
Advice Vehicle structure has slight corrosion (6.1.B.2)	
Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)	
Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excession	ve movement (2.4.G.2)





MOT #14		2015-04-24 16:13
MOT test	number	595734415160
Result		🗙 Failed
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not result	ing in excessive movement
<b>Advice</b> (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resultin	g in excessive movement
Fail O	ffside Front Brake pipe excessively corroded (3.6.B.2c)	
Advice	Brake pipe slightly corroded (3.6.B.2c)	
Notice	Advise offside front suspension strut top mounting rough	
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not result	ing in excessive movement
<b>Advice</b> (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resultin	g in excessive movement
Fail O	ffside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail O	ffside Rear Suspension has inadequate clearance with the bump stop (2.4	4.A.1a)

MOT #13	2014-04-25 13:06
MOT test number	727655214157
Result	✓ Passed
Notice Items removed from driver's view prior to test	

MOT #12	2013-04-05 15:50
MOT test number	947195193011
Result	✓ Passed
<b>Notice</b> Items removed from driver's view prior to test	





MOT #11		2013-04-05 15:50
MOT test number		759645793056
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Notice Items removed from driver's view prior to test		
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	

MOT #10		2012-04-09 17:01
MOT test	number	917090302126
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Items removed from driver's view prior to test	
Notice	Advise slight brake bind offside front	

MOT #9	2012-04-09 15:11
MOT test number	525070102116
Result	🗙 Failed
<b>Pass with rectification</b> Offside Headlamp aim too low (1.8)	
<b>Fail</b> Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.	.D.3)
<b>Notice</b> Items removed from driver's view prior to test	
Notice Advise slight brake bind offside front	
<b>Pass with rectification</b> Nearside Headlamp aim too low (1.8)	
Fail Centre Exhaust has a major leak of exhaust gases (7.1.2)	
Notice Child seat fitted not allowing full inspection of adult belt	





MOT #8		2011-04-06 13:55
MOT test	number	139846191402
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in exc	essive movement

MOT #7	2010-04-22 15:22	2
MOT test	number 76006271017	,
Result	✓ Passed	ł
Notice	Slight play at o/s/f wheel	
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	





МОТ #6		2010-04-22 15:22
MOT test number		492282710106
Result		🗙 Failed
Pass with rectification	Centre Rear fog lamp not working (1.3.2b)	
Pass with rectification	Offside Headlamp aim too high (1.8)	
Advice Exhaust has a m	inor leak of exhaust gases (7.1.2)	
Pass with rectification	Offside Side repeater incorrect colour (1.4.A.2f)	
Notice Slight play at o/s	/f wheel	
Advice Nearside Front S (2.4.G.2)	Suspension arm rubber bush deteriorated but not resultir	ng in excessive movement
Advice Exhaust has par	t of the system slightly deteriorated (7.1.1a)	

MOT #5		2009-04-29 16:19
MOT test	number	461629219123
Result		✓ Passed
Notice	Very slight play at o/s/f of steering rack	
Notice	Back box starting to corroded	

MOT #4		2009-04-29 09:51
MOT test	number	740289019110
Result		🗙 Failed
Notice	Back box starting to corroded	
Notice	Very slight play at o/s/f of steering rack	
<b>Fail</b> B	rakes imbalanced across an axle (3.7.B.5b)	

MOT #3	2008-04-25 09:39
MOT test number	120366518169
Result	✓ Passed





MOT #2	2008-04-25 09:39
MOT test number	623706818100
Result	🗙 Failed
<b>Pass with rectification</b> Windscreen washer provides insufficient washer liquid (8.2.3)	
MOT #1	2007-04-20 10:42
MOT #1 MOT test number	2007-04-20 10:42 660400517168
MOT test number	660400517168





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-03-19
Last registration	2022-12-23
Complete history	<u>See info</u>



Registration #1	2004-03-19	15 mi
Registration #2	2007-04-20	12.686 mi
Registration #3	2008-04-25	15.553 mi
Registration #4	2009-04-29	18.572 mi
Registration #5	2009-04-29	18.572 mi
Registration #6	2010-04-22	23.559 mi
Registration #7	2011-04-06	26.988 mi
Registration #8	2012-04-09	30.276 mi
Registration #9	2012-04-09	30.276 mi
Registration #10	2013-04-05	33.501 mi
Registration #11	2014-04-25	36.817 mi
Registration #12	2015-04-24	39.591 mi
Registration #13	2015-05-15	39.673 mi
Registration #14	2015-05-27	39.673 mi
Registration #15		11.117 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 esi
Registration #20		11.777 esi
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 mi
Registration #24		11.117 esi
Registration #25		11.777 esi
Registration #26		11.117 est
CarCheck.co.uk		page 18/19

Registration #28

-----

7000.00.00

-

11.777 mi

More info >





#### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1673 mm
Height	1460 mm
Length	4028 mm
Wheel base	2442 mm
Kerb weight	1074 kg
Max. allowed weight	1499 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 19/19

Number of axles	2
Engine number	FSR94787589