



report date: 2024-03-28

General information

Make	FIAT
Model	MULTIPLA JTD ELEGANZA
Colour	Grey
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	203 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	51.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-08
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-07-02
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	53
Total items failed	29

MOT #22 2021-06-17 08:08

MOT test number 343759504772

Result ✓ Passed

Next expiry date 2022-07-02

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner rim (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner rim (1.1.14 (a) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #21**

2021-06-16 15:05

MOT test number

415904357958

Result**✗ Failed**

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner rim (1.1.14 (a) (ii))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Brake performance not tested brake pipe leaking (1.2.1 (g))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner rim (1.1.14 (a) (ii))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Brake pipe leaking on a hydraulic braking system pipe across rear axle (1.1.11 (b) (ii))

MOT #20

2020-06-24 16:00

MOT test number

741860384708

Result**✓ Passed**

**MOT #19**

2019-07-03 11:57

MOT test number

672658102964

Result

✓ Passed

- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))

MOT #18

2019-06-11 16:22

MOT test number

128444369353

Result

✗ Failed

- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced inner body sill (7.1.1 (a) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner body sill (5.3.6 (a) (i))
- Fail** Nearside Front Headlamp aim not tested dipped beam inoperative (4.1.2 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced inner body sill (7.1.1 (a) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner body sill (5.3.6 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Fail** Offside Front Headlamp aim not tested dipped beam inoperative (4.1.2 (b))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #17** 2018-04-25 10:35**MOT test number** 415687187098**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear inner body sill corroded near suspension mounting prescribed area**MOT #16** 2017-05-08 13:08**MOT test number** 822639768977**Result** ✓ Passed**MOT #15** 2016-12-01 16:52**MOT test number** 295847760727**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**MOT #14** 2016-12-01 13:19**MOT test number** 951735274490**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #13** 2015-12-04 13:24**MOT test number** 374958046389**Result** ✓ Passed

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #12 2014-12-01 12:02**MOT test number** 829265634359**Result** ✓ Passed**MOT #11** 2013-11-08 10:59**MOT test number** 897392913355**Result** ✓ Passed**MOT #10** 2013-10-29 15:56**MOT test number** 439052303405**Result** ✗ Failed

Fail Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Fail Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**MOT #9**

2013-09-09 10:51

MOT test number

317042353428

Result

✗ Failed

Fail Nearside Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Notice Passenger seat(s) missing at time of test

Fail Offside Rear Sub-frame corroded and seriously weakened (2.4.G.1)

Fail Offside Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Notice N/s inner sill corroed

Fail Offside Seat belt anchorage prescribed area is excessively corroded (5.2.6)

MOT #8

2013-09-04 10:28

MOT test number

748337643265

Result

✗ Failed

Fail Offside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)

Fail Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Fail Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #7

2012-08-29 11:03

MOT test number

328192742457

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-08-26 09:23**MOT test number** 758028231220**Result** ✓ Passed**MOT #5** 2010-08-24 14:25**MOT test number** 953856930262**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs worn and slightly pitted**MOT #4** 2010-08-24 09:43**MOT test number** 940796630299**Result** ✗ Failed**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Notice** Front brake discs worn and slightly pitted**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #3** 2009-09-01 09:50**MOT test number** 503344849206**Result** ✓ Passed**Notice** Suspension joint nearside lower dust cover split/missing**Advice** Front brake disc slightly pitted (3.5.1h)



MOT #2	2008-09-10 11:00
MOT test number	593414258214
Result	✓ Passed

MOT #1	2008-09-08 09:58
MOT test number	724222658284
Result	✗ Failed

Fail

Nearside Rear Shock absorber has a serious fluid leak (2.7.3)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-07
Last registration	2021-06-17
Complete history	See info



Registration #1	2005-09-07	26 mi
Registration #2	2008-09-08	9.843 mi
Registration #3	2008-09-10	9.843 mi
Registration #4	2009-09-01	11.656 mi
Registration #5	2010-08-24	13.733 mi
Registration #6	2010-08-24	13.733 mi
Registration #7	2011-08-26	15.759 mi
Registration #8	2012-08-29	17.400 mi
Registration #9	2013-09-04	18.788 mi
Registration #10	2013-09-09	18.866 mi
Registration #11	2013-10-29	18.877 mi
Registration #12	2013-11-08	18.878 mi
Registration #13	2013-11-08	18.878 mi
Registration #14	2013-11-08	18.878 mi
Registration #15	2013-11-08	18.878 mi
Registration #16	2013-11-08	18.878 mi
Registration #17	2013-11-08	18.878 mi
Registration #18	2013-11-08	18.878 mi
Registration #19	2013-11-08	18.878 mi
Registration #20	2013-11-08	18.878 mi
Registration #21	2013-11-08	18.878 mi
Registration #22	2013-11-08	18.878 mi
Registration #23	2013-11-08	18.878 mi
Registration #24	2013-11-08	18.878 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Dimensions & weight

Width	1871 mm
Height	1670 mm
Length	3994 mm
Wheel base	2666 mm
Max. allowed weight	3350 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2

