





report date: 2024-03-29

General information

Make	MAZDA
Model	RX-8 RX-8 192PS
Colour	Red
Year of manufacture	-
Top speed	139 mph
0 - 60 mph	7.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	220 Nm at 5.000 rpm
Cylinders	2
Fuel type	Petrol
Consumption city	18.7 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.2 mpg



CarCheck.co.uk page 1/15




report date: 2024-03-29


Internet history


Entry 1

Date 2021-12-09
Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT #23	2021-	-05-28 09:26
MOT test	number 56	1426753432
Result		✓ Passed
Next expi	iry date	2022-05-27
Advice	General corrosion under side of vehicle	
Advice	Offside sill been painted	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.	3.6 (a) (i))
Advice	Nearside sill been painted	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3	3.6 (a) (i))

MOT #22	2021-05-26 13:53
MOT test	
Result	X Failed
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	General corrosion under side of vehicle
Fail Of	ffside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside sill been painted
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside sill been painted
	ffside Front Suspension component mounting prescribed area excessively corroded significantly structural strength (5.3.6 (a) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #21 2021-01-15 16:23 **MOT** test number 662730013576 Result × Failed **Advice** Offside Rear Nail in tyre Offside Front Tyre worn close to legal limit/worn on edge Worn To Legal Limit On Edges (5.2.3 (e)) **Advice** Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) **Advice** Items removed from driver's view prior to test Air Freshener Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) Fail

MOT #20		2018-11-28 09:03
MOT test	number	329835874904
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both edges worn and cut	(5.2.3 (e))
Advice	Rear suspension components corroded	
Advice	Offside Rear Nail in tyre	

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #19		2018-01-09 09:21
MOT test	number	822790397407
Result		✓ Passed
Advice	Front tyres worn on edges	
Advice	Engine light on	
Advice	Rear suspension components rusty	
Advice	Nearside Rear outer sill corroded	
Advice	Nearside Rear tyre on 2mm	
Advice	Offside Rear tyre worn on inner edge	

CarCheck.co.uk page 5/15



report date: 2024-03-29

× Failed

MOT #18 2018-01-08 12:05

MOT test number 483551408446

Result

Fail Offside Rear Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)

Advice Nearside Rear outer sill corroded

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear tyre on 2mm

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear tyre worn on inner edge

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Front tyres worn on edges

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Engine light on

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Rear suspension components rusty

CarCheck.co.uk page 6/15



Advice

NH54WGZ

report date: 2024-03-29

MOT #17 2017-11-15 11:29 **MOT** test number 328028497885 Result × Failed Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) Fail Offside Registration plate lamp not working (1.1.C.1d) **Advice** Nearside Rear door sill corroded Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Both front tyres worn on edges Advice Rear suspension parts corroded Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Nearside Front position lamp(s) not working (1.1.A.3b) **Advice** Offside Rear tyre worn on inner edge Fail Offside Rear Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)**Advice** Rear inner sills corroded

MOT #16 2016-12-13 09:23

MOT test number 537795282161

Result ✓ Passed

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #15
 2016-12-12 15:37

 MOT test number
 460967264855

Result X Failed

Fail Offside Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 7/15



Fail

NH54WGZ

report date: 2024-03-29

MOT #14 2015-11-06 17:42 **MOT** test number 627605283337 Result ✓ Passed **MOT #13** 2015-11-05 13:05 **MOT test number** 910353281820 Result × Failed Offside Registration plate lamp not working (1.1.C.1d) Fail Fail Front registration plate missing (6.3.1a) Fail Nearside Registration plate lamp not working (1.1.C.1d) Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #12

MOT test number

769047034163

Result

Notice Closing sills corroding

Notice Headlamps set on upper limit

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11

2014-05-17 10:48

MOT test number

229027234164

Result

Notice Closing sills corroding

Pass with rectification Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Notice Headlamps set on upper limit

Pass with rectification Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

CarCheck.co.uk page 8/15



report date: 2024-03-29

MOT #10 2013-06-03 12:12

MOT test number 247654353155

MOT #9 2012-09-11 12:43

MOT test number 368975052401

Notice Under-trays fitted obscuring some underside components

MOT #8 2012-09-10 12:12

MOT test number 987254452277

Result X Failed

Fail Rear rear brake binding (3.7.B.1)

Notice Under-trays fitted obscuring some underside components

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #7 2011-09-08 09:47

MOT test number 266601951233

Result \(\sqrt{Passed} \)

MOT #6 2010-08-25 09:42

MOT test number 564567230233

Result
✓ Passed

MOT #5 2009-09-07 13:41

MOT test number 794040359272

Result \rightarrow Passed

Notice Exhaust corroded

CarCheck.co.uk page 9/15



report date: 2024-03-29

MOT #4

MOT test number

132320959219

Result

Fail Offside Front Torque/reaction arm attachment bracket/mounting insecure (2.4.G.1)

Notice Exhaust corroded

MOT #3

MOT test number

980376548288

Result

Advice Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)

Notice Offside rear brake binding very slightly

MOT test number

Result

Pass with rectification

Offside Headlamp aim too low (1.8)

Pass with rectification

Nearside Headlamp aim too low (1.8)

Notice

Both front wiper blades split on edges

MOT #1

MOT test number

Result

Notice Both front wiper blades split on edges

2007-09-14 13:59

313477357420

✓ Passed

CarCheck.co.uk page 10/15



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-04
Last registration	2021-05-28
Complete history	See info



Registration #1	2004-09-04	23 mi
Registration #2	2007-09-14	6.653 mi
Registration #3	2008-09-02	8.417 mi
Registration #4	2009-09-07	10.324 mi
Registration #5	2009-09-07	10.324 mi
Registration #6	2010-08-25	12.143 mi
Registration #7	2011-09-08	14.077 mi
Registration #8	2012-09-10	15.800 mi
Registration #9	2012-09-11	15.800 mi
Registration #10	2013-06-03	16.817 mi
Registration #11	2014-05-17	27.065 mi
Registration #11		
Registration #12	2015-11-05	31.659 mi
		31.659 mi
Registration #12	2015-11-05	31.659 mi
Registration #12 Registration #13	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14 Registration #15	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2015-11-05	31.659 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2015-11-05	31.659 mi

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Dimensions & weight

Width	1770 mm
Height	1340 mm
Length	4425 mm
Wheel base	2700 mm
Kerb weight	1345 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	61
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B 449253

CarCheck.co.uk page 15/15