



RJ59JNL

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT GL
Colour	Silver
Year of manufacture	-
Top speed	108 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	116 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-09
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #15** 2022-06-24 13:20**MOT test number** 542613980202**Result** ✓ Passed**Next expiry date** 2023-06-23**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2021-06-24 10:34**MOT test number** 362588504056**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))**MOT #13** 2020-12-11 11:18**MOT test number** 445152022823**Result** ✓ Passed

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Oil leak, but not excessive From Transmission (8.4.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #12**

2020-12-09 15:31

MOT test number

486188866933

Result**✗ Failed**

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Offside Rear Brake linkage has restricted free movement Brakes binding (1.1.15 (e))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Oil leak, but not excessive From Transmission (8.4.1 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11

2019-12-13 10:27

MOT test number

147323337829

Result**✓ Passed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear (Slight Bind)

**MOT #10**

2019-12-13 10:27

MOT test number

304379615314

Result

✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear (Slight Bind)

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9

2018-12-14 12:31

MOT test number

674969079412

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement end round bush (5.3.4 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement end round bush (5.3.4 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8

2017-12-08 15:56

MOT test number

795099204326

Result

✓ Passed

Advice Nearside Front top mount has slight play

Advice Offside Rear Inner tyre out of shape

Advice Offside Front top mount has slight play



MOT #7	2017-12-08 13:37
MOT test number	928043685586
Result	✗ Failed
Advice	Offside Rear Inner tyre out of shape
Advice	Offside Front top mount has slight play
Advice	Nearside Front top mount has slight play
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6	2016-12-09 11:33
MOT test number	607440755057
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Unable to open boot
Advice	Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
Advice	Both front wipers smeary

MOT #5	2015-12-11 10:24
MOT test number	724324794334
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
Advice	Gearbox oil leak
Advice	Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2014-11-28 11:05**MOT test number** 755292234313**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-11-29 15:25**MOT test number** 387603933390**Result** ✓ Passed**Notice** Slight oil leak from gearbox.**MOT #2** 2012-11-30 15:50**MOT test number** 478005332350**Result** ✓ Passed**MOT #1** 2012-11-29 15:28**MOT test number** 739764932303**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-11
Last registration	2022-06-24
Complete history	See info



Registration #1	2009-12-11	29 mi
Registration #2	2012-11-29	35.050 mi
Registration #3	2012-11-30	35.050 mi
Registration #4	2013-11-29	43.374 mi
Registration #5	2014-11-28	53.993 mi
Registration #6	2015-12-11	63.375 mi
Registration #7	2016-12-09	72.716 mi
Registration #8	2017-12-08	80.707 mi
Registration #9	2017-12-08	80.708 mi
Registration #10	2018-06-20	85.377 mi
Registration #11	2018-06-20	85.377 mi
Registration #12	2018-06-20	85.377 mi
Registration #13	2018-06-20	85.377 mi
Registration #14	2018-06-20	85.377 mi
Registration #15	2018-06-20	85.377 mi
Registration #16	2018-06-20	85.377 mi
Registration #17	2018-06-20	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3880 mm
Wheel base	2380 mm
Kerb weight	1045 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2169787