





report date: 2024-03-28

#### General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Red
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg



CarCheck.co.uk page 1/13




## Internet history

#### Entry 1

Date 2021-06-17

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



**MOT** history

**MOT #14** 2022-06-14 15:25

MOT test number 733981082216

**Result** 
✓ Passed

Next expiry date 2023-06-14

**Advice** Play in steering rack inner joint(s)

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #13** 2022-06-10 12:27

MOT test number 659364501957

Result X Failed

**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**Advice** Play in steering rack inner joint(s)

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/13



YK110MT

report date: 2024-03-28

**MOT #12** 2021-06-15 14:51

**MOT test number** 272959988223

**MOT #11** 2021-06-14 12:54

**MOT test number** 607563028540

**Result** X Failed

Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2021-01-22 13:37

MOT test number 299160704471

**Result** ✓ Passed

MOT #9 2019-07-09 10:52

**MOT test number** 409019167335

**Result** ✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face deteriorated & ribbed (1.1.14 (a) (ii))

**Advice** Offside Front Service brake fluctuating, but not excessively 10kl (1.2.1 (e))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face deteriorated & ribbed (1.1.14 (a) (ii))

**Advice** Nearside Front Service brake fluctuating, but not excessively 10kl (1.2.1 (e))

CarCheck.co.uk page 4/13



MOT #8 2019-07-08 08:03

MOT test number 336681553880

Result X Failed

Advice Offside Front Service brake fluctuating, but not excessively 10kl (1.2.1 (e))

**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face deteriorated & ribbed (1.1.14 (a) (ii))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Service brake fluctuating, but not excessively 10kl (1.2.1 (e))

**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face deteriorated & ribbed (1.1.14 (a) (ii))

Fail Rear Exhaust has a major leak of exhaust gases flange corroded (6.1.2 (a))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing starting to split no cords showing (5.2.3 (d) (ii))

MOT #7 2018-07-06 14:31

**MOT test number** 305255223939

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Registration plate insecure but not likely to fall off (0.1 (a))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened lip on (1.1.14 (a) (ii))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Rear Exhaust has a minor leak of exhaust gases joint (6.1.2 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened lip on (1.1.14 (a) (ii))

**Advice** Nearside Rear tyre perishing

CarCheck.co.uk page 5/13



YK110MT

report date: 2024-03-28

**MOT #6** 2018-07-06 10:10 265642988604 **MOT** test number Result × Failed **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened lip on (1.1.14 (a) (ii)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Rear Exhaust has a minor leak of exhaust gases joint (6.1.2 (a)) Advice **Advice** Nearside Rear tyre perishing Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened lip on (1.1.14 (a) (ii)) **Advice** Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Front Registration plate insecure but not likely to fall off (0.1 (a)) Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

MOT #5	2017-07-25 12:32
MOT test number	978142026216
Result	✓ Passed

MOT #4	2017-03-07 09:44
MOT test number	495393260748

MOT #3 2016-03-08 09:04

**MOT test number** 778238659504

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit 185/55/16 (4.1.E.1)

CarCheck.co.uk page 6/13



MOT #2	2015-02-12 16:31
MOT test number	807363445013
Result	<b>✓</b> Passed
MOT #1	2014-03-03 15:21
MOT test number	906852064059
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
manage of the same	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-07
Last registration	2022-06-14
Complete history	See info



Registration #1	2011-03-07	24 mi
Registration #2	2014-03-03	33.573 mi
Registration #3	2015-02-12	41.478 mi
Registration #4	2016-03-08	48.397 mi
Registration #5	2017-03-07	53.166 mi
Registration #6	2017-07-25	53.555 mi
Registration #7	2018-07-06	58.043 mi
Registration #8	2018-07-06	58.043 mi
_		
Registration #9		77.777 es
Registration #9 Registration #10		1.77 4
-		11.777 ea 11.777 ea 11.777 ea
Registration #10		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12 Registration #13		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 12/13



### Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

### Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225

CarCheck.co.uk page 13/13