



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Blue
Year of manufacture	2007
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	130 g/km
CO2 label	D





MOT history

MOT expiry date	2021-02-17
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	42
Total items failed	11

MOT #13 2020-01-31 09:35

MOT test number 927873233886

Result ✓ Passed

Next expiry date 2021-02-17

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))
- Advice** Coolant level below min
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2020-01-10 15:43

MOT test number

289242663691

Result**✗ Failed**

Advice Rear Brake pipe corroded, covered in grease or other material Pipe corroded in bracket on rear axle (1.1.11 (c))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres wearing on edges (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Driver's view of the road through the swept area of the windscreen materially affected by an obstruction Wipers parking on screen (3.1 (a) (ii))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

Fail Electrical wiring insecure and connectors likely to become disconnected Battery earth (4.11 (a) (ii))

MOT #11

2019-02-18 15:33

MOT test number

359316469347

Result**✓ Passed**

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2018-02-07 14:16

MOT test number

450193051424

Result**✓ Passed****MOT #9**

2017-01-25 10:41

MOT test number

916100156098

Result**✓ Passed**

Advice Both front tyres wearing on the inner edges



MOT #8	2015-12-01 11:36
MOT test number	765406281261
Result	✓ Passed

MOT #7	2014-11-28 14:54
MOT test number	465612734372
Result	✓ Passed

MOT #6	2013-11-25 15:48
MOT test number	645679823394
Result	✓ Passed

- Notice** Clutch pedal rubber missing
- Notice** Scratches on nearside front headlight not effecting image
- Notice** Offside rear quarter damaged/bumper damaged
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Misting of oil around power steering pump
- Notice** Front scuttle damaged
- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #5** 2013-11-25 11:53**MOT test number** 308099823385**Result** ✗ Failed

- Notice** Scratches on nearside front headlight not effecting image
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Offside rear quarter damaged/bumper damaged
- Notice** Misting of oil around power steering pump
- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Front scuttle damaged
- Notice** Clutch pedal rubber missing
- Fail** Parking brake lever has no reserve travel (3.1.6b)

MOT #4 2013-10-12 11:29**MOT test number** 536685583249**Result** ✗ Failed

- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Notice** Rear bump stop deteirating
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Notice** Eml light on
- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Power steering fluid level low, but not below minimum (2.3.1)

**MOT #3** 2012-10-12 14:39**MOT test number** 839706682243**Result** ✓ Passed**Notice** Engine warning light on**Notice** Both front wiper smearing on screen**MOT #2** 2012-10-12 11:08**MOT test number** 448046782205**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Headlamp aim too low (1.8)**Notice** Engine warning light on**Fail** Nearside Stop lamp has less than 50% of the light sources illuminating (1.2.1b)**Fail** Offside Headlamp aim too low (1.8)**Notice** Both front wiper smearing on screen**MOT #1** 2011-10-14 16:31**MOT test number** 305537981209**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 May 2021

X

MOT

Expired:
17 February 2021

Tax status	Expired at 1 May 2021
Days left	1094 days too late
MOT expiry date	17 February 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-12-31
Last registration	2020-01-31
Complete history	See info



Registration #1	2007-12-31	15 mi
Registration #2	2011-10-14	44.648 mi
Registration #3	2012-10-12	23.981 mi
Registration #4	2012-10-12	23.981 mi
Registration #5	2013-10-12	33.769 mi
Registration #6	2013-11-25	34.740 mi
Registration #7	2013-11-25	34.740 mi
Registration #8	2019-05-29	35.277 mi
Registration #9	2019-05-29	35.277 mi
Registration #10	2019-05-29	35.277 mi
Registration #11	2019-05-29	35.277 mi
Registration #12	2019-05-29	35.277 mi
Registration #13	2019-05-29	35.277 mi
Registration #14	2019-05-29	35.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG7289668