





## General information

Make	HYUNDAI
Model	COUPE SE
Colour	Yellow
Year of manufacture	2004
Top speed	128 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	136 BHP	0 < 101 A
Max. torque	181 Nm at 4.500 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	1.975 cc	121 - 140
Cylinders	4	141 - 165 F
Fuel type	Petrol	166 - 185
Consumption city	24.8 mpg	186 - 225
Consumption extra urban	42.8 mpg	225+
Consumption combined	33.6 mpg	
CO2 emission	193 g/km	
CO2 label	J	





# Internet history

Entry 5	
Date	2023-01-22
Pictures	17
Listing price	View report




source: autotrader.co.uk

Entry 4	
Date	2023-01-17
Pictures	17
Listing price	<u>View report</u>



source: autotrader.co.uk

Entry 3	
Date	2023-01-11
Pictures	10
Listing price	View report



source: autotrader.co.uk

**Entry 2** Date CarCheck.co.uk


2022-12-30

### Pictures

Listing price


10

View report



#### source: autotrader.co.uk


Entry 1	
Date	2022-02-02
Pictures	10
Listing price	View report



source: autotrader.co.uk











# MOT history

MOT expiry date	2020-11-23
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	42
Total items failed	27

MOT #19	2019-05-24 13:27
MOT test number	813946125678
Result	✓ Passed
Next expiry date	2020-11-23

MOT #18		2019-05-23 12:57
MOT test	number	962154046409
Result		🗙 Failed
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice	Sill covers fitted	
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	





MOT #17	2019-05-22 10:36
MOT test number	629434209762
Result	🗙 Failed
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm inside ed	ge (5.2.3 (e))
Advice Sill covers fitted	
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
<b>DANGEROUS</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii	))
Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

MOT #16	2018-05-11 09:42
MOT test number	737768737478
Result	✓ Passed
Advice Supplementary Restraint System warning lamp does not illuminate (5.4.2)	





MOT #15	2018-05-01 09:36
MOT test number	941744912113
Result	🗙 Failed
Fail       Battery insecure (1.9.1)	
<b>Fail</b> Offside Outer Front constant velocity joint gaiter deteriorated to the extent the the ingress of dirt etc (2.5.C.1a)	at it no longer prevents
<b>Fail</b> Rear Exhaust has a major leak of exhaust gases Joint (7.1.2)	
Fail       Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail       Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
<b>Fail</b> Nearside Outer Front constant velocity joint gaiter deteriorated to the extent to prevents the ingress of dirt etc (2.5.C.1a)	that it no longer
<b>Fail</b> Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Fail       Emissions not tested (7.3.A.1)	
<b>Fail</b> Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
MOT #14	2017-04-21 08:20

MOT #14	2017-04-21 08:20
MOT test number	262084629197
Result	✓ Passed





MOT #13 2017-04-14 12:49
<b>MOT test number</b> 353534493106
Result X Failed
Fail       Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice Exhaust downpipe support bracket loose
Fail       Offside rear brake binding (3.7.B.1)
Fail Battery insecure (1.9.1)
Advice Suspension components and brake pipes under vehicle heavily corroded but not excessive
<b>Fail</b> Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b> Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Fail       Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Air filter insecure
Fail       Parking brake: efficiency below requirements (3.7.B.7)
Fail       Nearside Registration plate lamp insecure (1.1.C.1c)
Advice Slight front brake imbalance





MOT #12	2017-04-10 13:46
MOT test number	826117986031
Result	🗙 Failed
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
<b>Fail</b> Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)	
Fail       Parking brake: efficiency below requirements (3.7.B.7)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Fail</b> Offside Front Registration plate lamp not working (1.1.C.1d)	
Advice Offside rear parking (secondary) brake grabbing slightly (3.7.B.6b)	
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Front and rear suspension components rusty	
Fail       Nearside Registration plate lamp not working (1.1.C.1d)	
<b>Fail</b> Offside rear brake recording little or no effort parking brake (3.7.B.5a)	

MOT #11	2016-03-22 15:04
MOT test number	595449922221
Result	✓ Passed

MOT #10	2016-03-22 14:15
MOT test number	312883417441
Result	× Failed
<b>Fail</b> Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.	lf)
FailOffside Front Wheel nut(s) missing (4.2.A.1e)	
<b>Fail</b> Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1	.f)





MOT #9	2015-02-25 15:10
MOT test	number 609506255080
Result	✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b> (2.4.A.3)	Nearside Front Subframe mounting prescribed area is corroded but not considered excessive
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b> (2.4.A.3)	Offside Front Subframe mounting prescribed area is corroded but not considered excessive

МОТ #8	2015-02-16 13:01
MOT test number	108727245053
Result	🗙 Failed
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (	(3.5.1i)
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice Offside Front Subframe mounting prescribed area is corroded but not consider (2.4.A.3)	ed excessive
<b>Fail</b> Exhaust has a major leak of exhaust gases (7.1.2)	
Advice Exhaust noisy (7.1.4)	
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Advice Nearside Front Subframe mounting prescribed area is corroded but not consid (2.4.A.3)	ered excessive
<b>Fail</b> Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3	3.D.3)

MOT #7	2014-01-08 11:12
MOT test number	199748304010
Result	✓ Passed





MOT #6		2012-06-14 13:01
MOT test	number	977776262179
Result		✓ Passed
Notice	Front tyres wearing on edges.	
MOT #5		2012-04-05 11:55
MOT test	number	679666992084
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Items removed from driver's view prior to test	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

МОТ #4	2011-04-06 15:12
MOT test number	585196891037
Result	✓ Passed
NoticeBoth front brake discs wornAdviceRear Brake pad(s) wearing thin (3.5.1g)	

MOT #3	2010-03-26 14:17
MOT test number	113785080076
Result	✓ Passed
MOT #2	2009-04-07 08:28

MOT test number	361297199072
Result	✓ Passed





MOT #1	2007-09-19 11:29
MOT test number	951012967280
Result	✓ Passed





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lame
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

A CONTRACTOR OF A CONTRACTOR OFTA CONT	
**********	
******	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Correct registration	
Plate since	
Current registration	
Reduction of the second	





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-09-04
Last registration	2019-05-24
Complete history	See info



Registration #1	2004-09-04	23 mi
Registration #2	2007-09-19	29.330 mi
Registration #3	2009-04-07	34.462 mi
Registration #4	2010-03-26	40.981 mi
Registration #5	2011-04-06	50.459 mi
Registration #6	2012-04-05	59.617 mi
Registration #7	2012-06-14	61.024 mi
Registration #8	2014-01-08	70.495 mi
Registration #9	2015-02-16	74.163 mi
Registration #10	2015-02-25	74.727 mi
Registration #11	2016-03-22	77.188 mi
Registration #12	2016-03-22	77.188 mi
Registration #13	2017-04-10	83.842 mi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		
Registration #17		11.177 mi
Registration #17 Registration #18		10.000 est
		0.000 es
Registration #18		0.100 es 0.100 es 0.100 es 0.100 es
Registration #18 Registration #19		0.107 es 0.107 es 0.107 es 0.107 es 0.107 es
Registration #18 Registration #19 Registration #20		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est
Registration #18 Registration #19 Registration #20 Registration #21		10.000 es 10.000 es 10.000 es 10.000 es 10.000 es 10.000 es 10.000 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		10.000 es 10.000 es 10.000 es 10.000 es 10.000 es 10.000 es 10.000 es 10.000 es 10.000 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23		10.000 es 10.000 es





### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
50566	
\$0567	
S0569	

# Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1280 kg
Max. allowed weight	1740 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC4990995