



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY GHIA TDDI
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-12
Pictures	24
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #24** 2022-10-03 14:03**MOT test number** 820871472225**Result** ✓ Passed**Next expiry date** 2023-10-10**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #23** 2021-10-11 09:12**MOT test number** 385532460802**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front jacking point is corroded**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front caliper spring clip missing



MOT #22

2021-05-26 07:52

MOT test number

314744421659

Result

✓ Passed

- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Offside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice

Nearside Front caliper spring clip missing
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #21**

2021-05-26 07:52

MOT test number

319274724474

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front caliper spring clip missing
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #20

2020-05-27 09:07

MOT test number

981963596897

Result**✓ Passed**

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2020-05-26 07:49

MOT test number

144927955608

Result

✗ Failed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #18**

2019-04-08 08:14

MOT test number

465101977376

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge also perished (5.2.3 (e))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17**

2018-04-09 08:16

MOT test number

960570290549

Result

✓ Passed

Advice Offside Rear tyre starting to perish**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #16**

2017-04-10 12:45

MOT test number

561298765795

Result

✓ Passed

Advice Rear brake pipes showing signs of corrosion**Advice** N/s/r wheel rim has damage**Advice** Front brake discs in poor condition**Advice** Rear shock absorbers leaking slightly**MOT #15**

2017-04-10 08:41

MOT test number

703723464334

Result

✗ Failed

Advice Rear brake pipes showing signs of corrosion**Advice** N/s/r wheel rim has damage**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Front brake discs in poor condition**Advice** Rear shock absorbers leaking slightly**Fail** Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc both front inner gaiters (2.5.C.1a)**MOT #14**

2016-04-11 12:26

MOT test number

199368788704

Result

✓ Passed

**MOT #13** 2016-04-11 09:46**MOT test number** 906617232275**Result** ✗ Failed

Fail Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Temp fuel cap fitted

Fail Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #12 2015-04-08 10:20**MOT test number** 567708995099**Result** ✓ Passed**MOT #11** 2014-04-10 11:35**MOT test number** 345030504129**Result** ✓ Passed

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice O/S/R tyre has damage to the outer sidewall but not deep enough to reach the ply/cords

MOT #10 2013-04-03 13:41**MOT test number** 446603893065**Result** ✓ Passed

Notice Both front tyres wearing on inner edges

**MOT #9** 2013-04-03 10:38**MOT test number** 456703893010**Result** ✗ Failed**Notice** Both front tyres wearing on inner edges**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2012-03-16 14:16**MOT test number** 875616572014**Result** ✓ Passed**Advice** Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-03-16 11:38**MOT test number** 746886572098**Result** ✗ Failed**Advice** Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2011-04-05 10:04**MOT test number** 978515791086**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front disc and pads warn
- Notice** Rear tyre warn inner edge
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #5 2010-03-26 16:14**MOT test number** 573565180082**Result** ✓ Passed**MOT #4** 2010-03-26 11:49**MOT test number** 502445580043**Result** ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3 2009-03-14 08:15**MOT test number** 320033979044**Result** ✗ Failed

- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2009-03-14 08:15**MOT test number** 924142879068**Result** ✓ Passed



MOT #1	2008-04-08 11:00
MOT test number	464709598079
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-28
Current registration	*****
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-04-11
Last registration	2022-10-03
Complete history	See info



Registration #1	2005-04-11	23 mi
Registration #2	2008-04-08	27.449 mi
Registration #3	2009-03-14	34.786 mi
Registration #4	2010-03-26	44.567 mi
Registration #5	2010-03-26	44.567 mi
Registration #6	2011-04-05	50.206 mi
Registration #7	2012-03-16	56.333 mi
Registration #8	2012-03-16	56.334 mi
Registration #9	2013-04-03	61.143 mi
Registration #10	2013-04-03	61.144 mi
Registration #11	2014-04-10	65.732 mi
Registration #12	2015-04-08	69.014 mi
Registration #13	2016-04-11	72.933 mi
Registration #14	2016-04-11	72.933 mi
Registration #15	2016-04-11	72.933 mi
Registration #16	2016-04-11	72.933 mi
Registration #17	2016-04-11	72.933 mi
Registration #18	2016-04-11	72.933 mi
Registration #19	2016-04-11	72.933 mi
Registration #20	2016-04-11	72.933 mi
Registration #21	2016-04-11	72.933 mi
Registration #22	2016-04-11	72.933 mi
Registration #23	2016-04-11	72.933 mi
Registration #24	2016-04-11	72.933 mi
Registration #25	2016-04-11	72.933 mi



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4641 mm
Wheel base	2835 mm
Kerb weight	1694 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	5A18422