





report date: 2024-03-29

General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | I30 COMFORT |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 116 mph |
| 0 - 60 mph | 11.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 108 BHP |
|-------------------------|---------------------|
| Max. torque | 137 Nm at 5.000 rpm |
| Engine capacity | 1.396 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 142 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/15



Internet history

Entry 2

Date 2021-02-01

Pictures 3

Listing price <u>View report</u>







source: yesauto.com

Entry 1

Date 2021-01-31

Pictures 3

Listing price <u>View report</u>







source: yesauto.com

CarCheck.co.uk page 2/15



MOT history

| MOT expiry date | 2025-02-17 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 10 |
| Failed MOT tests | 5 |
| Total advice items | 56 |
| Total items failed | 12 |

| MOT #15 | 2024-02-13 09:59 |
|---|------------------|
| MOT test number | 545709212090 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-17 |
| Advice Front Flexi Pipe Deteriorated | |
| Advice Rear Service brake binding but not excessively Nearside & Offside (1.2.1 (f | 7)) |
| Advice Nearside Front Slight Water Contamination In Headlamp Unit | |
| Advice Rear Brake pad(s) wearing thin Nearside & Offside (1.1.13 (a) (ii)) | |
| Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice Rear Fuel Filler Pipe Corroded | |
| Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (| 6.1.7 (g) (i)) |
| Advice Rear Coil spring corroded Nearside & Offside (5.3.1 (b) (i)) | |
| Advice Rear Suspension arm pin or bush worn but not resulting in excessive move Offside (5.3.4 (a) (i)) | ment Nearside & |
| Advice Rear Axle Corroded | |

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #14 2023-02-06 14:22 **MOT** test number 847855363256 Result ✓ Passed **Advice** Fuel Pipe/s corroded Advice Rear Coil spring corroded Nearside And Offside (5.3.1 (b) (i)) Advice Front Registration Plate Cracked Advice Nearside Front Slight Water Contamination In Headlamp Unit Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Front Exhaust Flexi deteriorated Advice

MOT #13 2023-02-03 16:47 **MOT** test number 841000169324 Result × Failed Fail Offside Front Inner Suspension arm pin or bush excessively worn Bush Split (5.3.4 (a) (i)) **Advice** Nearside Front Slight Water Contamination In Headlamp Unit **Advice** Front Exhaust Flexi deteriorated Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Front Registration Plate Cracked Advice Advice Fuel Pipe/s corroded Advice Rear Coil spring corroded Nearside And Offside (5.3.1 (b) (i)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #12 2023-02-01 15:39

MOT test number 553047976909

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Condensation in n/s/f headlight

Advice Front no plate cracked slightly

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Handbrake lever high travel

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Front exhaust flexi deteriorated

Advice Fuel pipes corroded

MOT #11 2023-01-30 11:39

MOT test number 954372476717

Result × Failed

Advice Front exhaust flexi deteriorated

Advice Fuel pipes corroded

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Position lamp not working inner edge (4.2.1 (a) (ii))

Advice Condensation in n/s/f headlight

Advice Front no plate cracked slightly

Advice Handbrake lever high travel

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Fail Reversing lamp inoperative (4.6.1 (a))

CarCheck.co.uk page 5/15



MOT #10 2022-02-03 14:58

MOT test number 107801872347

Result ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread cracked slightly (0.1 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))

MOT #9 2022-01-31 12:51

MOT test number 520007897303

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread cracked slightly (0.1 (b))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Rear Windscreen wiper blade defective (3.4 (b) (i))

MOT #8 2021-02-18 17:07

MOT test number 192392734028

Result ✓ Passed

CarCheck.co.uk page 6/15



Result

EN11DZY report date: 2024-03-29

Passed

MOT #7 2020-08-24 08:56

MOT test number 563960143210

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2019-05-22 15:38

MOT test number 758144896587

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #5 2018-03-21 10:12

MOT test number 594175442377

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2017-03-18 10:45

MOT test number 105232251991

Result ✓ Passed

Advice N/s/r tyre worn on inside edge

MOT #3 2016-02-15 12:02

MOT test number 186213245976

Result

✓ Passed

Advice Child seat;s fitted preventing full inspection of seat belts

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #2 2015-02-03 10:46 **MOT test number** 146854635093 ✓ Passed Result MOT #1 2015-02-02 17:09 357343835012 **MOT test number X** Failed Result Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

CarCheck.co.uk page 8/15



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 17 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

| e when motorly | | |
|---|-----------|------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively. | | NDAI |
| | | |
| | | |
| *************************************** | | |
| | | |
| ******* | | |
| | | |
| *************************************** | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this HYUNDAI had different number plates. | | |
| Number of plates | | 9 |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2011-06-28 |
| Last registration | 2024-02-13 |
| Complete history | See info |



| Registration #1 | 2011-06-28 | 26 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-02-02 | 33.734 mi |
| Registration #3 | 2015-02-03 | 33.734 mi |
| Registration #4 | 2016-02-15 | 39.564 mi |
| Registration #5 | 2017-03-18 | 44.174 mi |
| Registration #6 | 2018-03-21 | 48.971 mi |
| Registration #7 | 2019-05-22 | 55.337 mi |
| Registration #8 | 2020-08-24 | 60.752 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |

More info >

CarCheck.co.uk page 14/15



Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1775 mm |
|---------------------|---------|
| Height | 1480 mm |
| Length | 4280 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1293 kg |
| Max. allowed weight | 1720 kg |

Additional information

| Fuel delivery | Multi-Point Injection |
|-----------------------------------|-----------------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 15/15 |