



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V VTEC SE
Colour	Blue
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	154 Nm at 4.800 rpm
Engine capacity	1.668 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-08-01
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-30
Pictures	34
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-29
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	89
Total items failed	12

MOT #232023-11-03 11:49

MOT test number451587692131

Result✔ Passed

Next expiry date2024-11-29

- Advice
- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Oil leak, but not excessive (8.4.1 (a) (i))
- Advice
- Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22**

2022-11-25 11:59

MOT test number

583667834617

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Nearside and offside outer sills corroded

MOT #21

2021-11-11 12:27

MOT test number

453731998858

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Corrosion around rear subframe mounting points but not excessive

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front and rear suspension components corroded but not seriously weakened

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #20**

2021-11-08 12:28

MOT test number

704329610613

Result**✗ Failed****Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))**MAJOR** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))**Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive Chassis leg (5.3.6 (a) (i))**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))**MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))**Advice** Nearside Rear Nail in tyre**MAJOR** Offside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #19**

2020-11-08 12:03

MOT test number

256054871488

Result**✓ Passed****Advice** Front Lower Suspension arm corroded but not seriously weakened both side (5.3.3 (b) (i))**Advice** Throughout under body corroded**Advice** Rear Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #18**

2019-11-28 11:07

MOT test number

500326627117

Result

✓ Passed

Advice Rear rear has surface corrosion on underside**Advice** Front Brake hose has slight corrosion to ferrule both front pipes (1.1.12 (f) (i))**MOT #17**

2019-11-28 11:07

MOT test number

474883747419

Result

✗ Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear rear has surface corrosion on underside**Advice** Front Brake hose has slight corrosion to ferrule both front pipes (1.1.12 (f) (i))**MOT #16**

2018-11-30 12:27

MOT test number

726049553627

Result

✓ Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Coil spring corroded all front and rear (5.3.1 (b) (i))**Advice** Rear Suspension arm corroded but not seriously weakened all nearside and offside (5.3.3 (b) (i))**Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced boot/spare wheel area (6.1.1 (c) (i))**Advice** Fuel hose corroded (6.1.3 (c) (ii))



MOT #15

2018-11-29 17:38

MOT test number

838311534563

Result

✗ Failed

- Advice** Coil spring corroded all front and rear (5.3.1 (b) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened all nearside and offside (5.3.3 (b) (i))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced boot/spare wheel area (6.1.1 (c) (i))
- MAJOR** Exhaust silencer insecure (8.1.1 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- MAJOR** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Fuel hose corroded (6.1.3 (c) (ii))
- Advice** Rear exhaust heatsheild insecure

**MOT #14**

2018-10-11 11:36

MOT test number

802249565704

Result**✗ Failed****Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**DANGEROUS** Exhaust shield missing where fitted as original equipment creating a risk of fire corroded (6.1.3 (e))**Advice** Suspension arm corroded but not seriously weakened all rear nearside and offside (5.3.3 (b) (i))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced boot/spare wheel area (6.1.1 (c) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MAJOR** Rear Exhaust silencer insecure (8.1.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2017-11-03 17:59

MOT test number

291995613957

Result**✓ Passed****Advice** Nearside Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #12**

2017-11-02 11:14

MOT test number

796334554075

Result**✗ Failed**

Advice Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Offside Rear Outer Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings sill (6.1.B.2)

Advice Rear rear brake fluctuating, but not excessively (3.7.B.3)

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Central Stop lamp not working (1.2.1b)

Fail Nearside Rear Outer Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings sill (6.1.B.2)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Child Seat fitted not allowing full inspection of adult belt

MOT #11

2016-09-26 13:12

MOT test number

823030753856

Result**✓ Passed****MOT #10**

2016-09-26 13:12

MOT test number

358838086962

Result**✗ Failed**

Pass with rectification Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification Front Brake lining(s) less than 1.5 mm thick (3.5.1g)

**MOT #9** 2015-10-12 15:38**MOT test number** 987149367756**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement both sides (2.4.G.2)**MOT #8** 2014-10-10 17:34**MOT test number** 628573584202**Result** ✓ Passed**MOT #7** 2013-10-28 11:38**MOT test number** 118891403317**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #6** 2012-10-18 14:30**MOT test number** 257182592278**Result** ✓ Passed**MOT #5** 2011-10-28 09:37**MOT test number** 528121101399**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2010-10-27 14:30**MOT test number** 482780800391**Result** ✓ Passed**MOT #3** 2009-10-31 15:49**MOT test number** 441204809444**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-10-31 10:54**MOT test number** 713974909348**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #1** 2008-10-10 12:52**MOT test number** 271284888226**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-09-29
Last registration	2023-11-03
Complete history	See info



Registration #1	2005-09-29	23 mi
Registration #2	2008-10-10	31.021 mi
Registration #3	2009-10-31	43.900 mi
Registration #4	2009-10-31	43.900 mi
Registration #5	2010-10-27	57.118 mi
Registration #6	2011-10-28	65.719 mi
Registration #7	2012-10-18	79.823 mi
Registration #8	2013-10-28	93.371 mi
Registration #9	2014-10-10	104.590 mi
Registration #10	2015-10-12	113.935 mi
Registration #11	2016-09-26	122.540 mi
Registration #12	2016-09-26	122.540 mi
Registration #13	2017-11-02	132.745 mi
Registration #14	2018-05-22	141.277 mi
Registration #15	2018-05-22	141.277 mi
Registration #16	2018-05-22	141.277 mi
Registration #17	2018-05-22	141.277 mi
Registration #18	2018-05-22	141.277 mi
Registration #19	2018-05-22	141.277 mi
Registration #20	2018-05-22	141.277 mi
Registration #21	2018-05-22	141.277 mi
Registration #22	2018-05-22	141.277 mi
Registration #23	2018-05-22	141.277 mi
Registration #24	2018-05-22	141.277 mi
Registration #25	2018-05-22	141.277 mi
Registration #26	2018-05-22	141.277 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1397 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	D17A24301120