



HYUNDAI

**P218JHK**


report date: 2024-03-29

General information

Make	HYUNDAI
Model	ACCENT GLS
Colour	Silver
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	176 Nm at 4.700 rpm
Cylinders	4
Fuel type	Petrol




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-28
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #23</b>	2021-11-17 16:52
<b>MOT test number</b>	470210079343
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-11-16
<b>Advice</b>	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #22</b>	2021-11-16 15:49
<b>MOT test number</b>	579664337097
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))
<b>Advice</b>	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #21</b>	2020-11-04 14:14
<b>MOT test number</b>	793792262005
<b>Result</b>	✓ Passed

<b>MOT #20</b>	2020-11-03 12:59
<b>MOT test number</b>	395910561366
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Fail</b>	Offside Windscreen washer not working (3.5 (a))
<b>Fail</b>	Front Exhaust has a major leak of exhaust gases flexi pipe (6.1.2 (a))
<b>Fail</b>	Nearside Windscreen washer not working (3.5 (a))

<b>MOT #19</b>	2019-10-30 15:01
<b>MOT test number</b>	312893451097
<b>Result</b>	✓ Passed

**MOT #18** 2019-10-30 14:08**MOT test number** 170149722285**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #17** 2018-10-15 11:14**MOT test number** 241488578856**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16** 2017-10-31 15:48**MOT test number** 727275404804**Result** ✓ Passed**Advice** Oil leak**MOT #15** 2017-10-30 11:52**MOT test number** 118273879611**Result** ✗ Failed**Fail** Nearside rear brake recording little or no effort (3.7.B.5a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Oil leak**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)**Fail** Offside Headlamp aim too high (1.8)**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #14** 2016-11-01 13:09**MOT test number** 510323415765**Result** ✓ Passed**MOT #13** 2016-11-01 11:47**MOT test number** 277044998657**Result** ✗ Failed**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #12** 2015-10-14 12:34**MOT test number** 233055178909**Result** ✓ Passed**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #11** 2015-10-14 11:44**MOT test number** 575932161209**Result** ✗ Failed**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #10** 2014-10-10 15:10**MOT test number** 948523684272**Result** ✓ Passed

**MOT #9** 2013-10-31 12:06**MOT test number** 875464603395**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-10-31 12:04**MOT test number** 357214303338**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #7** 2012-10-30 12:15**MOT test number** 817284702384**Result** ✓ Passed**MOT #6** 2011-10-03 11:35**MOT test number** 449636371232**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-10-27 10:53**MOT test number** 460210600322**Result** ✓ Passed**MOT #4** 2009-10-21 11:46**MOT test number** 282084699284**Result** ✓ Passed**Notice** Both front tyres wearing low.



MOT #3 2008-10-08 10:54

MOT test number 983882888233

Result ✓ Passed

**Notice** Nearside front tyre is near tread limit

MOT #2 2007-10-18 13:11

MOT test number 151641397223

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2006-09-28 12:10

MOT test number 394211076418

Result ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1996-08-12
Last registration	2021-11-17
Complete history	<a href="#">See info</a>



Registration #1	1996-08-12	6 mi
Registration #2	2006-09-28	47.074 mi
Registration #3	2007-10-18	48.979 mi
Registration #4	2008-10-08	50.222 mi
Registration #5	2009-10-21	51.548 mi
Registration #6	2010-10-27	52.275 mi
Registration #7	2011-10-03	53.512 mi
Registration #8	2012-10-30	54.345 mi
Registration #9	2013-10-31	55.358 mi
Registration #10	2013-10-31	55.358 mi
Registration #11	2014-10-10	56.420 mi
Registration #12	2015-10-14	57.194 mi
Registration #13	2015-10-14	57.194 mi
Registration #14	2016-10-14	58.194 mi
Registration #15	2017-10-14	59.194 mi
Registration #16	2018-10-14	60.194 mi
Registration #17	2019-10-14	61.194 mi
Registration #18	2020-10-14	62.194 mi
Registration #19	2021-10-14	63.194 mi
Registration #20	2022-10-14	64.194 mi
Registration #21	2023-10-14	65.194 mi
Registration #22	2024-10-14	66.194 mi
Registration #23	2025-10-14	67.194 mi
Registration #24	2026-10-14	68.194 mi
Registration #25	2027-10-14	69.194 mi



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4EKT822036