





report date: 2024-03-29

#### General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Blue
Year of manufacture	2006
Top speed	141 mph
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	205 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date 2021-11-07

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



LG56LGD

report date: 2024-03-29

## MOT history

MOT expiry date	2024-04-05
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #16		2023-04-06 12:44
MOT test	number	133794080489
Result		✓ Passed
Next expi	ry date	2024-04-05
Advice	Nearside Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Offside Front Anti-roll bar linkage corroded but not seriously weakened (5.3.3 (b)	) (i))
Advice	Offside Rear Exhaust mounting defective (6.1.2 (a))	

MOT #15	2022-01-28 11:0
MOT test	number 96143723031
Result	✓ Passed
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



Advice

LG56LGD

report date: 2024-03-29

**MOT #14** 2022-01-19 12:40 **MOT** test number 795621065599 Result × Failed **MAJOR** Front Position lamp not working both sides (4.2.1 (a) (ii)) **MAJOR** Horn not working (7.7 (a)) Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) MAJOR

MOT #13

MOT test number

277234087101

Result

Advice Offside Rear light lens broken

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #12
 2019-05-09 17:51

 MOT test number
 907911726507

 Result
 X Failed

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MAJOR** Nearside Headlamp aim not tested (4.1.2 (b))

**Advice** Offside Rear light lens broken

 MOT #11
 2018-06-30 15:35

 MOT test number
 109727046864

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



LG56LGD

report date: 2024-03-29

MOT #10		2017-04-28 14:57
<b>MOT</b> test	number	834152573899
Result		<b>✓</b> Passed
Advice	Front tyres x 2 edges worn	
Advice	Emissions too clean to be detected	

MOT #9		2016-02-02 09:31
MOT test	number	142164766395
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2015-02-10 12:44
MOT test number	545171645026
Result	✓ Passed
MOT #7	2014-02-06 09:58
MOT test number	518717234028
Result	<b>✓</b> Passed
MOT #6	2013-02-09 11:56
MOT test number	619990443078
Result	✓ Passed
MOT #5	2012-02-14 10:48
MOT test number	445925042032
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



LG56LGD

report date: 2024-03-29

MOT #4 2012-02-13 11:22

**MOT test number** 445424942071

**Result** X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2011-02-17 16:02

**MOT test number** 339738141076

**Result** ✓ Passed

MOT #2 2010-09-13 09:28

MOT test number 681756050206

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #1** 2009-09-16 16:43

**MOT test number** 223189559277

Result 

Passed

Advice Centre Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A'

(8.3.1a)

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	MK MIN
Plate since	
	Mana info
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-09-16
Last registration	2023-04-06
Complete history	See info



Registration #1	2006-09-16	28 mi
Registration #2	2010-09-13	37.536 mi
Registration #3	2011-02-17	42.919 mi
Registration #4	2012-02-13	55.412 mi
Registration #5	2012-02-14	55.427 mi
Registration #6	2013-02-09	66.226 mi
Registration #7	2014-02-06	71.209 mi
Registration #8	2015-02-10	74.366 mi
Registration #9	2016-02-02	76.741 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 44
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1818 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Kerb weight	1790 kg
Max. allowed weight	2255 kg

## Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	01426837G

CarCheck.co.uk page 12/12