



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Black
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-19
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	50
Total items failed	24

MOT #19	2024-01-16 15:39
---------	------------------

MOT test number	927163185208
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-19
------------------	------------

- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #18**

2024-01-15 14:55

**MOT test number**

740972527821

**Result****✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2023-01-17 15:25

**MOT test number**

238523688391

**Result****✓ Passed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear [ back end ] (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to nearside rear [ back end ] (1.1.11 (c))

**MOT #16**

2023-01-12 11:50

**MOT test number**

500331709493

**Result**

✗ Failed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear [ back end ] (1.1.11 (c))

**Minor** Nearside Front Headlamp lens slightly defective dulling (4.1.1 (b) (i))

**Fail** Front Exhaust has a major leak of exhaust gases cat joint broken away (6.1.2 (a))

**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material to nearside rear [ back end ] (1.1.11 (c))

**Fail** Emissions not tested (8.2.1.2 (d))

**Fail** Offside Front Headlamp light intensity severely reduced lens dull (4.1.4 (a))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15**

2022-01-17 16:58

**MOT test number**

114062435466

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing hard on outer edge just off cords (5.2.3 (e))

**Advice** Nearside Rear Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))

**Advice** Offside Front tyre wearing on outer edge

**MOT #14**

2022-01-14 12:59

**MOT test number**

276166961859

**Result****✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Headlamp lens slightly defective dulling (4.1.1 (b) (i))**Fail** Front Exhaust has a major leak of exhaust gases cat (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing hard on outer edge just off cords (5.2.3 (e))**Fail** Nearside Front Windscreen washer not working (3.5 (a))**Advice** Offside Front tyre wearing on outer edge**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Front Exhaust emissions likely to be affected by an exhaust leak cat leaking (8.2.1.1 (b))**Advice** Nearside Rear Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))**Minor** Offside Front Headlamp lens slightly defective dulling (4.1.1 (b) (i))**Fail** Offside Front Position lamp not working side light (4.2.1 (a) (ii))**MOT #13**

2021-01-06 10:52

**MOT test number**

406348874424

**Result****✓ Passed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12** 2021-01-06 10:52**MOT test number** 293252243668**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2020-01-20 16:37**MOT test number** 719523107508**Result** ✓ Passed**Advice** Offside Front discs backing plate corroded**MOT #10** 2019-03-26 15:50**MOT test number** 251396042329**Result** ✓ Passed**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9** 2019-03-26 10:58**MOT test number** 657324473302**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #8** 2018-03-08 11:21**MOT test number** 442365884499**Result** ✓ Passed**MOT #7** 2017-04-03 13:58**MOT test number** 218539473428**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #6** 2017-03-30 09:00**MOT test number** 539128560218**Result** ✗ Failed

**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Advice** Screen wash jets partially blocked

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #5** 2016-03-23 10:31**MOT test number** 166299049365**Result** ✓ Passed

**Advice** Wipers smeary.

**Advice** Slight play in both front top mounts.

**Advice** Front springs corroded.







<b>MOT #4</b>	2015-03-30 16:07
---------------	------------------

<b>MOT test number</b>	508659085082
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2014-03-15 12:23
---------------	------------------

<b>MOT test number</b>	528354874000
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Notice</b>	Offside front tyre punctured
---------------	------------------------------

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #2</b>	2013-03-27 14:16
---------------	------------------

<b>MOT test number</b>	905556483083
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-03-24 13:23
---------------	------------------

<b>MOT test number</b>	576204382052
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
19 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	19 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history


Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>GY09EUB</b>
Plate since	2019-09-29
Current registration	<b>GY09EUB</b>
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-28
Last registration	2024-01-16
Complete history	<a href="#">See info</a>



Registration #1	2009-03-28	10 mi
Registration #2	2012-03-24	22.680 mi
Registration #3	2013-03-27	26.475 mi
Registration #4	2014-03-15	29.674 mi
Registration #5	2015-03-30	36.195 mi
Registration #6	2016-03-23	44.292 mi
Registration #7	2017-03-30	54.352 mi
Registration #8	2017-04-03	54.420 mi
Registration #9	2018-03-08	63.271 mi
Registration #10	2019-03-26	74.422 mi
Registration #11	2019-03-26	74.422 mi
Registration #12	2019-03-26	74.422 mi
Registration #13	2019-03-26	74.422 mi
Registration #14	2019-03-26	74.422 mi
Registration #15	2019-03-26	74.422 mi
Registration #16	2019-03-26	74.422 mi
Registration #17	2019-03-26	74.422 mi
Registration #18	2019-03-26	74.422 mi
Registration #19	2019-03-26	74.422 mi
Registration #20	2019-03-26	74.422 mi
Registration #21	2019-03-26	74.422 mi

More info >





Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612