





### General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	172 g/km
CO2 label	Н







# Internet history

Entry 1	
Date	2022-05-05
Pictures	11
Listing price	View report









source: cargurus.co.uk



# MOT history

MOT expiry date	2024-06-16
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	76
Total items failed	4

<b>MOT #20</b> 2023	3-06-08 12:27
MOT test number 90	04904859697
Result	🗸 Passed
Next expiry date	2024-06-16
<b>Advice</b> Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive mov (5.3.4 (a) (i))	vement
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Slight play in steering rack	
Advice Nearside Headlamp has a product on the lens but not seriously reducing light output f (b))	aded (4.1.4
Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (i))	(5.3.4 (a)
Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive move (a) (i))	ment (5.3.4
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Front Headlamp has a product on the lens but not seriously reducing light outp (b))	out (4.1.4



mx58ztd report date: 2024-03-29

MOT #19	2023-06-07 08:39
MOT test	number 710687488258
Result	× Failed
MAJOR	Nearside Front Outer Suspension component ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4
MAJOR	Central Exhaust system insecure mount (6.1.2 (a))
MAJOR	Front Brakes imbalanced across an axle (1.2.1 (b) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b> (a) (i))	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice (b))	Nearside Headlamp has a product on the lens but not seriously reducing light output faded (4.1.4
Advice	Slight play in steering rack
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice (i))	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a)
<b>Advice</b> (5.3.4 (a)	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (i))

MOT #18		2022-06-17 08:28
MOT test	number	168356273625
Result		✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play Rear (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Parking brake lever defective but can be satisfactorily operated Release handle (1.1.6 (d))		(1.1.6 (d))



MX58ZTD report date: 2024-03-29

MOT #17		2022-06-01 08:40
MOT test	number	859992065290
Result		🗙 Failed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1)	L (c))
Advice	Parking brake lever defective but can be satisfactorily operated Release handle	(1.1.6 (d))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
MAJOR	Fuel cap/sealing device ineffective (6.1.3 (b) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Lower Suspension arm ball joint has slight play Rear (5.3.4 (a) (i))	
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (	(c))
MAJOR	Windscreen washer not working (3.5 (a))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	c))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #16		2021-09-13 08:21
MOT test	number	893216378113
Result		Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



MOT #15	2020-09-07 11:54
MOT test number	265679454123
Result	✓ Passed
Advice Items removed from driver's view prior to test	
Advice Offside Front Play in steering rack inner joint(s)	
<b>Advice</b> Headlamp has a product on the lens but not seriously reducing light replaced (4.1.4 (b))	output and bulb defective,
Advice Child Seat fitted not allowing full inspection of adult belt	
MOT #14	2020-09-07 11:54
MOT test number	863295698415
Dis suit	to Della d

Result	× Failed
Advice Child Seat fitted not allowing full inspection of adult belt	
Pass with rectificationFuel cap/sealing device ineffective (6.1.3 (b) (i))	
Advice Items removed from driver's view prior to test	
Advice Headlamp has a product on the lens but not seriously reducing light output and bulb def replaced (4.1.4 (b))	ective,
Advice Offside Front Play in steering rack inner joint(s)	

MX58ZTD

report date: 2024-03-29





MOT #13	2019-03-20 11:55
MOT test number	144921533211
Result	✓ Passed
Advice Nearside Rear tyre 4mm	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Front Outer Anti-roll bar linkage ball joint dust cover severely dete split (5.3.4 (b) (i))	riorated boot slightly
Advice Offside Rear tyre 3.5mm	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	boot slightly split
Advice Offside Front Nail in tyre inner edge	

#### MOT #12 2019-03-15 17:34 **MOT test number** 887353275246 Result × Failed Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Offside Front Nail in tyre inner edge DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Minor Nearside Front Outer Anti-roll bar linkage ball joint dust cover severely deteriorated boot slightly split (5.3.4 (b) (i)) Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated boot slightly split (5.3.4 (b) (i)) DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11	2018-03-17 12:13
MOT test number	689065389543
Result	✓ Passed
Advice Temporary fuel cap fitted	



MX58ZTD
report date: 2024-03-29

MOT #10	2018-03-16 11:13
MOT test number	470118648003
Result	🗙 Failed
Advice Temporary fuel cap fitted	
Fail Nearside Front Lower Front suspension has excessive play in a lower suspe	ension ball joint (2.5.B.1a)

MOT #9		2017-03-25 12:30
MOT test	number	106152459139
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	
Advice	Offside Front Front wheel bearing has slight play (2.5.A.3c)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Front wheel bearing has slight play (2.5.A.3c)	

MOT #8	2017-03-25 09:53
MOT test number	269984729330
Result	🗙 Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	
Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
FailOffside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Nearside Front Front wheel bearing has slight play (2.5.A.3c)	





MOT #7	2016-03-17 12:51
MOT test number	145096433027
Result	✓ Passed
MOT #6	2015-04-01 15:45
MOT test number	188881395029
Result	✓ Passed
MOT #5	2015-04-01 14:43
MOT test number	177261895077
Result	× Failed
<b>Fail</b> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #4	2014-03-21 10:01
MOT test number	947150384090
Result	✓ Passed

MOT #3	2013-03-26 12:50
MOT test number	969315083064
Result	✓ Passed

MOT #2	2012-03-05 16:42
MOT test number	967725362041
Result	✓ Passed

MOT #1	2011-08-22 14:22
MOT test number	809984031284
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 16 June 2024
Tax status	Valid until 1 January
Days left	246
MOT expiry date	16 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Date	Le la
Category	AMPL
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
And a second s	
and the second sec	
***********	
And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-01
Last registration	2023-06-08
Complete history	<u>See info</u>



Registration #1	2008-09-01	14 mi
Registration #2	2011-08-22	25.867 mi
Registration #3	2012-03-05	26.953 mi
Registration #4	2013-03-26	40.621 mi
Registration #5	2014-03-21	51.945 mi
Registration #6	2015-04-01	60.767 mi
Registration #7	2015-04-01	60.770 mi
Registration #8	2016-03-17	71.711 mi
Registration #9	2017-03-25	79.087 mi
Registration #10	2017-03-25	79.087 mi
Registration #11	2018-03-16	90.360 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi
Registration #22		11.777 mi





# Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1575 kg

## Additional information

Fuel tank capacity	62
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630632066