



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRTD CDX PLUS
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	335 Nm at 1.800 rpm
Engine capacity	2.188 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	218 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-01-31
Pictures	3
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2023-05-22
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	49
Total items failed	20

MOT #21	2022-05-23 11:25
MOT test number	439935846409
Result	✓ Passed
Next expiry date	2023-05-22

MOT #20	2021-09-16 15:58
MOT test number	797744402468
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19**

2021-09-16 15:58

MOT test number

606424825913

Result**✗ Failed****Advice** Play in steering rack inner joint(s)**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #18**

2020-05-20 09:26

MOT test number

219253907138

Result**✓ Passed****Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #17**

2019-05-17 10:36

MOT test number

893730574354

Result**✓ Passed****Advice** Brake pad(s) wearing thin front and rear (1.1.13 (a) (ii))



MOT #162018-06-07 08:53

MOT test number718133048582

Result✓ Passed

- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge nails in tread (5.2.3 (e))

**MOT #15**

2018-06-01 10:36

MOT test number

222210097337

Result**✗ Failed**

- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge nails in tread (5.2.3 (e))
- Fail** Front Registration plate inscription illegible (0.1 (b))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14

2017-06-17 14:46

MOT test number

331457988576

Result**✓ Passed****MOT #13**

2017-06-17 14:46

MOT test number

989752582890

Result**✗ Failed**

- Pass with rectification** Offside Inner Stop lamp has less than 50% of the light sources illuminating blb380 (1.2.1b)

**MOT #12** 2016-11-15 16:25**MOT test number** 383564253470**Result** ✓ Passed**MOT #11** 2016-11-15 11:19**MOT test number** 385430929436**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced bulb incorrectly fitted (1.7.5a)**MOT #10** 2015-10-30 22:04**MOT test number** 164982060026**Result** ✓ Passed**Advice** Engine covers fitted**Advice** Nearside Rear Tyre worn close to the legal limit 3.0 mm and bald on inner edge 235/65x17 108v (4.1.E.1)

**MOT #9**

2015-10-30 09:21

MOT test number

453746041903

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Engine covers fitted**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit 3.0 mm and bald on inner edge 235/65x17 108v (4.1.E.1)**MOT #8**

2014-11-11 14:48

MOT test number

537075914308

Result**✓ Passed****Notice** Under-trays fitted obscuring some underside components**Notice** Front registration plate cracked**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #7**

2014-11-11 09:21

MOT test number

159335614306

Result**✗ Failed****Notice** Front registration plate cracked**Fail** Nearside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #6** 2013-11-16 10:53**MOT test number** 205570523355**Result** ✓ Passed**MOT #5** 2012-11-16 09:22**MOT test number** 509221622393**Result** ✓ Passed**MOT #4** 2011-11-09 11:07**MOT test number** 536773111318**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-11-09 08:55**MOT test number** 419593011452**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2010-11-17 08:41**MOT test number** 990131020304**Result** ✓ Passed



MOT #1	2010-11-17 08:41
MOT test number	321151620339
Result	✗ Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Headlamp aim too low (1.8)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-21
Last registration	2022-05-23
Complete history	See info



Registration #1	2007-11-21	11 mi
Registration #2	2010-11-17	19.477 mi
Registration #3	2011-11-09	28.602 mi
Registration #4	2011-11-09	28.603 mi
Registration #5	2012-11-16	37.712 mi
Registration #6	2013-11-16	46.597 mi
Registration #7	2014-11-11	56.577 mi
Registration #8	2014-11-11	56.579 mi
Registration #9	2015-10-30	64.815 mi
Registration #10	2015-10-30	64.815 mi
Registration #11	2016-11-15	72.524 mi
Registration #12	2016-11-15	72.524 mi
Registration #13	2016-11-15	72.524 mi
Registration #14	2016-11-15	72.524 mi
Registration #15	2016-11-15	72.524 mi
Registration #16	2016-11-15	72.524 mi
Registration #17	2016-11-15	72.524 mi
Registration #18	2016-11-15	72.524 mi
Registration #19	2016-11-15	72.524 mi
Registration #20	2016-11-15	72.524 mi
Registration #21	2016-11-15	72.524 mi
Registration #22	2016-11-15	72.524 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1725 mm
Length	4650 mm
Wheel base	2700 mm
Kerb weight	1823 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4EB7137132