





report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Yellow
Year of manufacture	-
Top speed	86 mph
0 - 60 mph	18.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	62 BHP
Max. torque	98 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-11-16

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #15	2021-08-03 12	:10
MOT test	number 9900824820)62
Result	✓ Pass	sed
Next expi	ry date 2022-08	-26
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	ı

MOT #14		2020-07-27 12:09
MOT test	number	942272775728
Result		✓ Passed
Advice	Rear axle mount repaired by welding	
Advice	Suspension parts corroded	
Advice	Front discs scored / worn	

MOT #13	2019-08-27 09:46
MOT test number	353219902884
Result	✓ Passed
MOT #12	2019-08-26 11:56
MOT test number	232783734845
Result	X Failed
Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))	

CarCheck.co.uk page 3/11



MOT #11

MOT test number

270059782587

Result

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #10
 2017-05-06 09:20

 MOT test number
 108034917762

 Result
 ✓ Passed

 MOT #9
 2017-05-06 09:17

 MOT test number
 278775957887

 Result
 X Failed

 Fail
 Nearside Stop lamp not working (1.2.1b)

MOT #8

MOT test number

408009699625

Result

Advice Exhaust system is slightly corroded

MOT #7

MOT test number

Result

Notice Exhaust system slightly deteriorated

2015-05-26 11:57

787566145139

✓ Passed

 MOT #6
 2014-05-12 11:33

 MOT test number
 935392834190

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



MOT #5 2013-05-29 09:07 **MOT test number** 639049143171 Result ✓ Passed MOT #4 2012-03-09 10:05 **MOT** test number 876809462035 Result ✓ Passed MOT #3 2011-02-05 11:18 627216431093 **MOT test number** Result ✓ Passed MOT #2 2010-02-19 12:56 953020250051 **MOT test number** Result ✓ Passed **MOT #1** 2010-02-19 12:56 **MOT test number** 582060850042 Result × Failed **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK NEZ
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-02-23
Last registration	2021-08-03
Complete history	See info



Registration #1	2007-02-23	15 mi
Registration #2	2010-02-19	3.070 mi
Registration #3	2011-02-05	4.418 mi
Registration #4	2012-03-09	6.111 mi
Registration #5	2013-05-29	8.553 mi
Registration #6	2014-05-12	10.949 mi
Registration #7	2015-05-26	13.258 mi
Registration #8	2016-05-17	16.418 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	946 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	G4HG6M028672

CarCheck.co.uk page 11/11