





report date: 2024-03-29

# General information

Make	MAZDA
Model	6 TS2
Colour	Red
Year of manufacture	2006
Top speed	126 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	140 BHP
Max. torque	181 Nm at 4.100 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg
CO2 emission	191 g/km
CO2 label	1



CarCheck.co.uk page 1/14



# Internet history

# Entry 1

Date 2021-05-26

Pictures 39

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2022-05-29
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	11

MOT #17	2021-05-24 12:51
MOT test number	895823049901
Result	✓ Passed
Next expiry date	2022-05-29
Advice Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced Suspension arm (6.1.1 (c) (i))	
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is no Suspension arm (6.1.1 (c) (i))	ot significantly reduced

MOT #16	2020-05-30 12:26
MOT test number	690626255988
Result	✓ Passed

MOT #15	2019-06-07 08:33	
MOT test number	148564497042	
Result	✓ Passed	
Advice Offside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Under seal (jacking point) has small rust whole not with in 30cm of prescribed areas. (6.2.2 (d) (i))		
Advice Offside Rear Axle has rust whole	e but not in dangerous place.	
Advice Offside Rear Nail in tyre		

CarCheck.co.uk page 3/14



**MOT #14** 2019-05-30 08:54

MOT test number 390513701061

Result

× Failed

**Fail** Nearside Rear Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting Under seal (jacking point) seriously corroded within 30cm of trialling arm bush. (6.2.2 (d) (i))

**Advice** 

Offside Rear Nail in tyre

Advice Offside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Under seal (jacking point) has small rust whole not with in 30cm of prescribed areas. (6.2.2 (d) (i))

Advice

Offside Rear Axle has rust whole but not in dangerous place.

**MOT #13** 2018-06-01 10:34

MOT test number 195927548868

Result \rightarrow Passed

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Nearside Front Lower Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point (6.1.1 (c) (i))

Advice Nearside Rear Lower Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point (6.1.1 (c) (i))

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Offside Front Lower Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point (6.1.1 (c) (i))

MOT #12 2017-05-20 12:38

**MOT test number** 916697114093

Result 

Passed

MOT #11 2016-05-28 10:08

MOT test number 952846285616

CarCheck.co.uk page 4/14



**MOT #10** 2015-05-20 16:53

MOT test number 608390945121

**Result** ✓ Passed

**Notice** Brake & Clutch pedal rubbers wearing smooth

Advice Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

(2.5.C.1a)

**Notice** NSF Tyre outer edge wearing

Advice Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #9 2015-05-20 14:49

**MOT test number** 236090445467

**Result** X Failed

**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Notice** Brake & Clutch pedal rubbers wearing smooth

**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Notice** NSF Tyre outer edge wearing

**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Rear wiper split

**Pass with rectification** Front Headlamp aim too high (1.8)

**Fail** Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #8 2014-05-21 16:44

MOT test number 667721344178

**Notice** Pedal rubbers worn

CarCheck.co.uk page 5/14



Nearside Front coil spring cracked (2.4.C.1a)

Fail

FL06UZX report date: 2024-03-29

 MOT #7
 2013-05-15 15:56

 MOT test number
 447365133181

 Result
 ✓ Passed

 MOT #6
 2013-05-15 09:50

 MOT test number
 398315933178

 Result
 X Failed

 Notice
 Tyre sidewall perishing nsr

NoticeTrye sidewall cracking osrMOT #52012-05-15 15:52MOT test number227446032114Result✓ PassedMOT #42011-05-16 10:05MOT test number348766431138Result✓ Passed

MOT #3	2010-05-25 16:42
MOT test number	451425040160
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/14



MOT #2 2010-05-25 10:52

MOT test number 232065740180

Result X Failed

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Headlamp aim too high (1.8)

Fail Offside Front Front wheel bearing has excessive play (2.5.A.3c)

**Notice** Nsr tyre badly cracked between treads and sidewall

**MOT #1** 2009-06-05 09:11

**MOT test number** 760076459132

**Result** ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



MOT
Expired:
29 May 2022

Tax expired: 11 June 2022

Tax status	Expired at 11 June 2022
Days left	689 days too late
MOT expiry date	29 May 2022
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



# Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



## Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



FL06UZX

report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



## Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-03-17
Last registration	2021-05-24
Complete history	See info



Registration #1	2006-03-17	20 mi
Registration #2	2009-06-05	25.033 mi
Registration #3	2010-05-25	31.644 mi
Registration #4	2010-05-25	31.644 mi
Registration #5	2011-05-16	38.571 mi
Registration #6	2012-05-15	46.444 mi
Registration #7	2013-05-15	53.263 mi
Registration #8	2013-05-15	53.263 mi
Registration #9	2014-05-21	61.857 mi
Registration #10	2015-05-20	69.803 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****

**Video** <u>see crash video</u>



# Dimensions & weight

Width	1780 mm
Height	1480 mm
Length	4710 mm
Wheel base	2675 mm
Kerb weight	1375 kg
Max. allowed weight	1940 kg

# Additional information

Fuel tank capacity	64 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 769760

CarCheck.co.uk page 14/14