





General informationMakeVOLKSWAGENModelPASSAT HIGHLINE TDIColourBlackYear of manufacture2008Gearbox6 speed Manual

Engine & fuel consumption

| Power | 138 BHP |
|-------------------------|----------|
| Engine capacity | 1.986 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 156 g/km |
| CO2 label | G |



MOT history

| MOT expiry date | 2024-06-05 |
|--------------------|------------|
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 24 |
| Total items failed | 2 |

| MOT #15 | 2023-06-06 19:29 |
|---|----------------------------|
| MOT test number | 608312831187 |
| Result | ✓ Passed |
| Next expiry date 2024-06-05 | |
| Minor Offside Front Outer Drive shaft joint constant velocity boot severely det | teriorated (6.1.7 (g) (i)) |

| MOT #14 | 2022-04-07 19:27 |
|-----------------|------------------|
| MOT test number | 616590704893 |
| Result | ✓ Passed |

| MOT #13 | 2022-04-07 19:27 |
|-------------------------|--|
| MOT test number | 509425947740 |
| Result | × Failed |
| Pass with rectification | Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) |

| MOT #12 | | 2021-03-25 17:47 |
|---|---|------------------------|
| MOT test | number | 736685389676 |
| Result | | ✓ Passed |
| Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) | | |
| Minor Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | | |
| Advice | Nearside Front Shock absorbers light misting of oil or has limited damp | ing effect (5.3.2 (b)) |





| MOT #11 | 2020-02-27 09:27 |
|---|------------------|
| MOT test number | 797105930344 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2019-02-28 09:21 |
| MOT test number | 465886889194 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #9 | 2018-02-19 11:37 |
|--|--|
| MOT test number | 322278347996 |
| Result | ✓ Passed |
| Advice Nearside Front constant velocity j (2.5.C.1a) | oint gaiter deteriorated, but preventing the ingress of dirt |
| Advice Under trays fitted | |

| MOT #8 | 2017-02-27 10:41 |
|--|---------------------------|
| MOT test number | 375208741830 |
| Result | ✓ Passed |
| Advice Nearside Rear Inner Brake pad(s) wearing thin (3.5.1g) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Under trays fitted | |
| Advice Nearside Front Front constant velocity joint gaiter damaged, but preve (2.5.C.1a) | nting the ingress of dirt |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front Upper Anti-roll bar linkage ball joint dust cover damage ingress of dirt (2.4.G.2) | d, but preventing the |





| MOT #7 | 2016-02-26 09:33 | |
|---|------------------|--|
| MOT test number | 758444541037 | |
| Result | ✓ Passed | |
| Advice Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2) | | |
| Advice Engine cover & undertrays fitted obscuring some components | | |
| | | |

| MOT #6 | | 2015-02-26 10:34 |
|----------|--|------------------|
| MOT test | number | 508237655063 |
| Result | | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Under-trays fitted obscuring some underside components | |

| MOT #5 | | 2014-02-27 10:16 |
|----------|--|------------------|
| MOT test | number | 347308754052 |
| Result | | 🗸 Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Notice | Under-trays fitted obscuring some underside components | |

| MOT #4 | | 2013-02-28 10:34 |
|----------|---|------------------|
| MOT test | number | 539379253064 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Under-trays fitted obscuring some underside components | |





| MOT #3 | 2012-02-29 09:22 |
|--|---|
| MOT test number | 326210562050 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2011-03-02 10:00 |
| MOT test number | 928511061076 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2011-03-02 10:00 |
| MOT test number | 498541061084 |
| Result | × Failed |
| Pass with rectification (8.2.2) | Nearside Front Windscreen wiper does not clear the windscreen effectively |



Tax & MOT check

| √ Taxed | мот |
|--------------------------|--------------------------------|
| Tax due: 1 April 2025 | Expires: 5 June 2024 |
| Tax status | Valid until 1 April |
| Days left | 337 |
| MOT expiry date | 5 June 2024 |
| Full MOT history | See MOT history |
| | |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Damaye 2 | E CAT D |
| Date | * |
| Category | AMPL |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ******** | |
| | |
| and a second sec | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 15 |
| First mileage registration | 2008-04-30 |
| Last registration | 2023-06-06 |
| Complete history | <u>See info</u> |



| Registration #1 | 2008-04-30 | 21 mi |
|------------------|------------|------------|
| Registration #2 | 2011-03-02 | 31.658 mi |
| Registration #3 | 2012-02-29 | 40.126 mi |
| Registration #4 | 2013-02-28 | 47.778 mi |
| Registration #5 | 2014-02-27 | 54.502 mi |
| Registration #6 | 2015-02-26 | 61.030 mi |
| Registration #7 | 2016-02-26 | 68.557 mi |
| Registration #8 | 2017-02-27 | 74.831 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 mi |
| Registration #15 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1820 mm Height 1517 mm Length 4774 mm Wheel base 2709 mm Kerb weight 1510 kg Max. allowed weight 2170 kg Additional information Fuel tank capacity 70 I **Fuel delivery Direct Injection** Number of doors 5

| Number of seats | 5 |
|-----------------|------------|
| Engine number | CBA 067351 |
| | |