



R4ENH

report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 T6 EXECUTIVE
Colour	Black
Year of manufacture	2004
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	272 BHP
Max. torque	380 Nm at 5.000 rpm
Engine capacity	2.922 cc
Cylinders	6
Fuel type	Petrol
Consumption city	15.3 mpg
Consumption extra urban	29.4 mpg
Consumption combined	21.9 mpg
CO2 emission	309 g/km
CO2 label	M





MOT history

MOT expiry date	2021-10-07
MOT pass rate	56 %
MOT passed	14
Failed MOT tests	11
Total advice items	39
Total items failed	41

MOT #25	2020-10-08 15:49
---------	------------------

MOT test number	524825618478
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2021-10-07
------------------	------------

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #24**

2020-10-07 14:43

MOT test number

819577697878

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #23

2019-05-24 09:57

MOT test number

655395076598

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22

2018-05-25 12:11

MOT test number

474115843689

Result

✓ Passed

**MOT #21** 2018-05-16 09:49**MOT test number** 757119130987**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #20** 2017-05-30 08:29**MOT test number** 871188035416**Result** ✓ Passed**MOT #19** 2017-05-24 10:03**MOT test number** 423653645673**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Fuel cap/sealing device sealing washer deteriorated (7.2.4c)**MOT #18** 2016-05-27 08:37**MOT test number** 382519867986**Result** ✓ Passed**MOT #17** 2016-05-26 08:49**MOT test number** 667907561115**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)

**MOT #16** 2015-05-19 12:34**MOT test number** 515779135126**Result** ✓ Passed**MOT #15** 2014-07-21 16:01**MOT test number** 218022304228**Result** ✓ Passed**MOT #14** 2014-07-21 10:09**MOT test number** 349972904458**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #13** 2013-07-31 13:54**MOT test number** 758142713228**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Fuel cap sealing washer deteriorated

**MOT #12**

2013-07-25 12:53

MOT test number

819506703250

Result**✗ Failed**

- Notice** Offside rear tyre worn to 1.6mm
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Track rod end has had excessive heat applied (2.2.C.1e)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Offside Headlamp cleaning device inoperative (1.7.2)
- Notice** Fuel cap sealing washer deteriorated
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Nearside Headlamp cleaning device inoperative (1.7.2)
- Fail** Parking brake lever has no reserve travel (3.1.6b)

MOT #11

2012-08-23 09:19

MOT test number

588606332227

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2012-08-20 09:36

MOT test number

477113632277

Result**✗ Failed****Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Fail** Brake performance not tested (3.7.A.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Service brake: efficiency below requirements (3.7.C.1a)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #9**

2011-06-03 16:25

MOT test number

685354951136

Result**✓ Passed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2011-06-03 12:54**MOT test number** 908014651129**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-05-17 13:00**MOT test number** 887017331163**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front brake discs slightly worn**Fail** Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2010-05-20 12:29**MOT test number** 682510140160**Result** ✓ Passed**MOT #5** 2009-05-01 14:40**MOT test number** 361391129108**Result** ✓ Passed



MOT #4	2009-05-01 10:03
MOT test number	474431929135
Result	✗ Failed
<div><div>Notice</div>Front brake pads low, front brake discs on limit, rear brake discs slightly worn</div> <div><div>Fail</div>Parking brake: efficiency below requirements (3.7.C.1b)</div>	

MOT #3	2008-05-09 16:21
MOT test number	684670038181
Result	✓ Passed

MOT #2	2007-05-11 15:45
MOT test number	932511337178
Result	✓ Passed

MOT #1	2007-05-11 11:58
MOT test number	512731337145
Result	✗ Failed
<div><div>Fail</div>Parking brake: efficiency below requirements (3.7.C.1b)</div>	



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2021

✕
MOT

Expired:
7 October 2021

Tax status	Expired at 31 January 2021
Days left	1184 days too late
MOT expiry date	7 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-05-19
Last registration	2020-10-08
Complete history	See info



Registration #1	2004-05-19	7 mi
Registration #2	2007-05-11	26.362 mi
Registration #3	2007-05-11	26.362 mi
Registration #4	2008-05-09	35.370 mi
Registration #5	2009-05-01	45.406 mi
Registration #6	2009-05-01	45.406 mi
Registration #7	2010-05-20	57.429 mi
Registration #8	2011-05-17	66.460 mi
Registration #9	2011-06-03	66.596 mi
Registration #10	2011-06-03	66.596 mi
Registration #11	2012-08-20	72.859 mi
Registration #12	2012-08-23	72.860 mi
Registration #13	2013-07-25	78.988 mi
Registration #14	2013-07-25	78.988 mi
Registration #15	2013-07-25	78.988 mi
Registration #16	2013-07-25	78.988 mi
Registration #17	2013-07-25	78.988 mi
Registration #18	2013-07-25	78.988 mi
Registration #19	2013-07-25	78.988 mi
Registration #20	2013-07-25	78.988 mi
Registration #21	2013-07-25	78.988 mi
Registration #22	2013-07-25	78.988 mi
Registration #23	2013-07-25	78.988 mi
Registration #24	2013-07-25	78.988 mi
Registration #25	2013-07-25	78.988 mi
Registration #26	2013-07-25	78.988 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2123 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Engine number	3399365