



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ-L
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	133 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-04
Pictures	4
Listing price	View report



BML
BLYTH MOTORS LTD
Car sales, brakes fitting, car servicing, exhaust
3 errington street
Belside
Blyth
NE24 4HP
01670226365
07475449989
07845708326
Blythmotorsltd@gmail.com





source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-06-13
MOT pass rate	53 %
MOT passed	9
Failed MOT tests	8
Total advice items	46
Total items failed	24

MOT #17	2023-06-14 10:51
MOT test number	172160466470
Result	✓ Passed
Next expiry date	2024-06-13
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16	2023-06-14 10:51
MOT test number	183462430715
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Central Rear Rear fog lamp not working (4.5.1 (a) (ii))



MOT #15

2022-04-21 16:01

MOT test number

492585664494

Result		✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Fuel Pipe/s corroded	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Coolant leak	

**MOT #14**

2022-04-21 13:50

MOT test number

362732694244

Result**✗ Failed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Fuel Pipe/s corroded
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Coolant leak
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #13

2021-04-22 14:08

MOT test number

964844781018

Result**✓ Passed**

- Advice** Brake pipe corroded, covered in grease or other material all metal (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2021-04-22 10:38

MOT test number

329206548306

Result**✗ Failed****Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material all metal (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Central Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11**

2019-04-04 15:51

MOT test number

542231967678

Result**✓ Passed**

**MOT #10** 2019-04-02 13:52**MOT test number** 187766492824**Result** ✗ Failed

- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Exhaust fumes entering cabin (6.1.2 (b) (i))
- Fail** Exhaust system insecure (6.1.2 (a))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))

MOT #9 2018-04-17 13:16**MOT test number** 358966844230**Result** ✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2018-04-17 13:16

MOT test number

318099847272

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7**

2017-03-08 17:27

MOT test number

403638682743

Result**✓ Passed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6**

2017-02-08 13:26

MOT test number

648574108205

Result**✗ Failed****Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Brake pipe slightly corroded offside front to rear (3.6.B.2c)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside rear brake recording little or no effort (3.7.B.5a)**MOT #5**

2016-02-11 16:01

MOT test number

457873172790

Result**✓ Passed**
page 8/16

**MOT #4** 2016-02-11 12:45**MOT test number** 453007777091**Result** ✗ Failed

- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)
- Fail** Offside Rear Rear fog lamp not working (1.3.2b)

MOT #3 2015-11-02 15:35**MOT test number** 405330658578**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Fail** Offside Rear Rear fog lamp not working (1.3.2b)

MOT #2 2014-01-11 10:19**MOT test number** 836371114095**Result** ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Nearside front tyre close too legal limit(1.6mm)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1 2012-11-20 12:42**MOT test number** 567875822310**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
13 June 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	SV59DTN
Plate since	2024-03-29
Current registration	SV59DTN
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-13
Last registration	2023-06-14
Complete history	See info



Registration #1	2009-11-13	6 mi
Registration #2	2012-11-20	28.606 mi
Registration #3	2014-01-11	34.340 mi
Registration #4	2015-11-02	47.470 mi
Registration #5	2016-02-11	48.610 mi
Registration #6	2016-02-11	48.610 mi
Registration #7	2017-02-08	56.108 mi
Registration #8	2017-03-08	56.503 mi
Registration #9	2018-04-17	65.662 mi
Registration #10	2018-04-17	65.662 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3760 mm
Wheel base	2380 mm
Kerb weight	980 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M13A-2167015