

₩ MASERATI



### General information

Make	MASERATI
Model	COUPE V8 SPYDER
Colour	White
Year of manufacture	2003
Top speed	174 mph
0 - 60 mph	4.9 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	385 BHP
Max. torque	450 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.0 mpg
Consumption extra urban	21.7 mpg
Consumption combined	15.2 mpg
CO2 emission	430 g/km
CO2 label	Μ







# Internet history

Entry 1	
Date	2021-06-05
Pictures	19
Listing price	View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-16
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	23
Total items failed	4

MOT #20	2023-06-17 08:54
MOT test number	186823798534
Result	✓ Passed
Next expiry date	2024-06-16

MOT #19	2022-05-28 10:14
MOT test number	839770083144
Result	✓ Passed
Advice Rear Brake pipe corroded, covered in grease or other material feed pipe	s (1.1.11 (c))

MOT #18	2021-05-01 11:21
MOT test number	284230704840
Result	✓ Passed
Advice Nearside Rear Brake pipe corrod	ed, covered in grease or other material (1.1.11 (c))





MOT #17		2020-05-29 16:09
MOT test	number	627511546535
Result		🗸 Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	))

MOT #16			2020-05-29 16:09
MOT test	number		699769929475
Result			🗙 Failed
<b>Pass wit</b> (4.7.1 (b) (	<b>h rectification</b>	Rear Registration plate lamp inoperative in the ca	ase of a single lamp or all lamps
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))			
Advice	<b>dvice</b> Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii))		
Advice	vice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		

MOT #15	2018-11-30 18:24
MOT test number	978773303702
Result	✓ Passed
MOT #14	2016-11-14 15:34
MOT test number	562506191034

Result

🗸 Passed





MOT #13		2015-11-03 11:32
MOT test	number	999482929416
Result		✓ Passed
Advice	Parking brake efficiency only just met	
MOT #12		2014-11-10 15:53
MOT test	number	239144514379
Result		Passed
Notice	Offside front to rear brake pipe slightly corroded	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Nearside front to rear brake pipe slightly corroded	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Nearside front wiper blade split	

MOT #11	2013-11-14 11:15
MOT test number	257068513375
Result	✓ Passed

MOT #10	2012-11-28 17:07
MOT test number	868923932370
Result	✓ Passed

MOT #9	2012-11-28 17:07	
MOT test number	486783232436	
Result	× Failed	
Pass with rectification	n Nearside Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	<b>Pass with rectification</b> Offside Windscreen washer provides insufficient washer liquid (8.2.3)	





MOT #8	2011-07-08 16:13
MOT test number	786389081192
Result	✓ Passed
MOT #7	2010-08-23 13:11
MOT test number	391995030294
Result	✓ Passed
MOT #6	2009-07-21 10:37
MOT test number	390582209442
Result	✓ Passed
MOT #5	2008-06-04 11:09
MOT test number	734786958104
Result	✓ Passed
Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
MOT #4	2007-07-19 12:24
MOT test number	884810007204
Result	✓ Passed
Notice Handbrake just passed minium standed	
Notice Handbrake just bassed minium standed	

MOT #3	2006-08-03 16:23
MOT test number	393915616430
Result	✓ Passed

MOT #2	2006-08-03 14:16
MOT test number	322465416447
Result	🗙 Failed
<b>Fail</b> Parking brake: efficiency below requirements (3.7.B.7)	





MOT #1		2006-02-03 09:56
MOT test	number	263884336018
Result		✓ Passed
Advice	Offside Front brake disc slightly pitted (3.5.1h)	
Advice	Nearside Front brake disc slightly pitted (3.5.1h)	





#### Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	*
Category	A SHIP .
Туре	

#### Extra MASERATI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MASERATI? How many owners did this MASERATI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
***********	
*********	
And a second sec	
**********	
********	
	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-01-14
Last registration	2023-06-17
Complete history	See info



Registration #1	2003-01-14	25 mi
Registration #2	2006-02-03	9.379 mi
Registration #3	2006-08-03	10.506 mi
Registration #4	2006-08-03	10.506 mi
Registration #5	2007-07-19	11.570 mi
Registration #6	2008-06-04	23.764 mi
Registration #7	2009-07-21	20.401 mi
Registration #8	2010-08-23	28.502 mi
Registration #9	2011-07-08	33.020 mi
Registration #10	2012-11-28	33.785 mi
Registration #11	2013-11-14	34.240 mi
Registration #12		11.777 est
Registration #13		11.222 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi

More info >



# Dimensions & weight

Width	1822 mm
Height	1305 mm
Length	4303 mm
Wheel base	2440 mm
Kerb weight	1720 kg

## Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	071875