



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Silver
Year of manufacture	2006
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-05
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-24
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	73
Total items failed	3

MOT #18	2024-01-25 17:14
---------	------------------

MOT test number	622685363832
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-24
------------------	------------

- Minor

Nearside Front Headlamp lens slightly defective misting (4.1.1 (b) (i))
- Advice

Front slight leak at power steering pipe.
- Advice

Brake pipe corroded, covered in grease or other material os front to rear pipe corroded at rear. (1.1.11 (c))
- Advice

Front Exhaust has a minor leak of exhaust gases on flexy section. (6.1.2 (a))
- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material corroded. (1.1.11 (c))
- Minor

Offside Front Headlamp lens slightly defective misting. (4.1.1 (b) (i))
- Advice

Items removed from driver's view prior to test phone mount.
- Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material corroded. (1.1.11 (c))

**MOT #17**

2024-01-25 09:45

MOT test number

903653136701

Result

✗ Failed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Offside Front Headlamp lens slightly defective misting. (4.1.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded. (1.1.11 (c))
- Advice** Brake pipe corroded, covered in grease or other material os front to rear pipe corroded at rear. (1.1.11 (c))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Items removed from driver's view prior to test phone mount.
- Minor** Nearside Front Headlamp lens slightly defective misting (4.1.1 (b) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases on flexy section. (6.1.2 (a))
- Advice** Front slight leak at power steering pipe.
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded. (1.1.11 (c))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16

2023-01-24 10:45

MOT test number

569636237430

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #15**

2022-01-25 16:15

MOT test number

424623832424

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement Both Sides (5.3.4 (a) (i))
- Minor** Offside Front Headlamp lens slightly defective Cloudy (4.1.1 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Exhaust has a minor leak of exhaust gases Centre Box (6.1.2 (a))
- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Minor** Nearside Front Headlamp lens slightly defective Cloudy (4.1.1 (b) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt

**MOT #14**

2022-01-23 14:28

MOT test number

899167321035

Result**✗ Failed**

- Minor** Offside Front Headlamp lens slightly defective Cloudy (4.1.1 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Outer Tyre has a bulge, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Exhaust has a minor leak of exhaust gases Centre Box (6.1.2 (a))
- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Minor** Nearside Front Headlamp lens slightly defective Cloudy (4.1.1 (b) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement Both Sides (5.3.4 (a) (i))

MOT #13

2021-01-21 14:23

MOT test number

790844895660

Result**✓ Passed**

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front flexy deteriorating
- Advice** Power steering pipe/hose has slight seepage high pressure hose (2.1.5 (a))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Exhaust has a minor leak of exhaust gases center box (6.1.2 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #12**

2020-02-24 09:24

MOT test number

166746078645

Result

✓ Passed

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2019-02-12 15:24

MOT test number

213920124738

Result

✓ Passed

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Rear Registration plate insecure but not likely to fall off (0.1 (a))

Advice

Central Lower Power steering pipe/hose has slight seepage pipe from rack (2.1.5 (a))

Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10

2018-02-05 09:36

MOT test number

191544360119

Result

✓ Passed

Advice

Central Items removed from driver's view prior to test

Advice

Offside Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #9** 2017-03-01 10:54**MOT test number** 504936993554**Result** ✓ Passed**Advice** Offside Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Items removed from driver's view prior to test**MOT #8** 2015-10-15 14:02**MOT test number** 936810696624**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-10-22 11:05**MOT test number** 259815194233**Result** ✓ Passed**MOT #6** 2013-10-07 15:49**MOT test number** 147760383250**Result** ✓ Passed**MOT #5** 2013-10-07 10:12**MOT test number** 377680583201**Result** ✗ Failed**Fail** Offside Obligatory mirror seriously deteriorated, affecting the rear view (8.1.2a)**MOT #4** 2012-10-10 12:01**MOT test number** 256444582259**Result** ✓ Passed



MOT #3	2011-10-13 14:01
MOT test number	189896581245
Result	✓ Passed
MOT #2	2010-10-07 12:01
MOT test number	720320380272
Result	✓ Passed
MOT #1	2009-10-27 12:49
MOT test number	824290809374
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-07
Last registration	2024-01-25
Complete history	See info



Registration #1	2006-09-07	9 mi
Registration #2	2009-10-27	12.650 mi
Registration #3	2010-10-07	20.029 mi
Registration #4	2011-10-13	26.025 mi
Registration #5	2012-10-10	32.288 mi
Registration #6	2013-10-07	39.012 mi
Registration #7	2013-10-07	39.012 mi
Registration #8	2014-10-22	45.644 mi
Registration #9	2015-10-15	51.106 mi
Registration #10	2017-03-01	55.963 mi
Registration #11	2019-05-20	59.377 mi
Registration #12	2019-05-20	59.377 mi
Registration #13	2019-05-20	59.377 mi
Registration #14	2019-05-20	59.377 mi
Registration #15	2019-05-20	59.377 mi
Registration #16	2019-05-20	59.377 mi
Registration #17	2019-05-20	59.377 mi
Registration #18	2019-05-20	59.377 mi
Registration #19	2019-05-20	59.377 mi
Registration #20	2019-05-20	59.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1685 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1327 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED6437696