





General information

Make	HONDA
Model	S2000 16V GT
Colour	Grey
Year of manufacture	2005
Top speed	150 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	240 BHP
Max. torque	208 Nm at 7.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	15.7 mpg
Consumption combined	28.3 mpg
CO2 emission	237 g/km
CO2 label	L







Internet history

Entry	1
Date	

Pictures

2021-07-10

19

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	28
Total items failed	12

MOT #22	2023-07-06 16:22
MOT test number	106221010690
Result	✓ Passed
Next expiry date	2024-07-05

MOT #21	2023-07-06 08:57
MOT test number	294226113671
Result	🗙 Failed
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #20		2022-07-25 13:52
MOT test	number	527597807910
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #19	2021-08-10 15:28
MOT test number	152764549241
Result	✓ Passed





MOT #18		2021-08-09 10:11
MOT test number		150974029795
Result		🗙 Failed
Fail Offside Front Anti-r	oll bar linkage fractured (5.3.3 (b) (ii))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	
Minor Nearside Registr (b) (i))	ation plate lamp inoperative in the case of multiple la	amps or light sources (4.7.1
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	

MOT #17	2021-02-03 15:15
MOT test number	746165254884
Result	✓ Passed

MOT #1	6	2021-01-27 16:37
MOT tes	st number	782303911903
Result		🗙 Failed
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #15	2020-02-14 14:21
MOT test	number 454088625459
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))





MOT #14	2	019-01-11 15:44
MOT test	number	325786350496
Result		🗸 Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

MOT #13	2018-01-08 11:53
MOT test number	225527412084
Result	✓ Passed
Advice Brake disc worn, pitted or scored, but not seriously weakened all four (3.5.1i)	

MOT #12		2016-12-07 16:44
MOT test	number	275478302169
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #11	2016-12-07 15:28
MOT test number	943402150033
Result	🗙 Failed
Fail Offside rear brake binding (3.7.B.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
FailParking brake lever has no reserve travel (3.1.6b)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #10	2015-12-16 09:37
MOT test number	420860588436
Result	✓ Passed





MOT #9		2014-11-25 17:25
MOT test	number	457009924497
Result		✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1	Li)
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice movement	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting t (2.4.G.2)	in excessive
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Notice	Front windscreen wiper blades slight smearing in operation	

MOT #8	2014-11-25 10:32
MOT test number	575289024312
Result	🗙 Failed
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice Front windscreen wiper blades slight smearing in operation	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.	.5.1i)
Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulti movement (2.4.G.2)	ng in excessive
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	





MOT #7	2013-12-06 09:45
MOT test number	808610443329
Result	✓ Passed
МОТ #6	2012-11-22 11:23
MOT test number	615947522306
Result	✓ Passed
МОТ #5	2011-10-28 12:20
MOT test number	888521301303
Result	✓ Passed
МОТ #4	2010-11-08 17:22
MOT test number	404242110466
Result	Passed

Result		Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2009-11-13 15:26
MOT test number	913537219365
Result	✓ Passed

MOT #2		2009-11-12 10:03
MOT test numbe	er	213696119350
Result		🗙 Failed
Fail Offside R	ear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside	Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	





MOT #1	2008-11-19 11:34
MOT test number	410634328360
Result	✓ Passed



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 July 2024	Expires: 5 July 2024
Tax status	Valid until 1 July
Days left	63
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plates	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-11-22
Last registration	2023-07-06
Complete history	See info



Registration #1	2005-11-22	14 mi
Registration #2	2008-11-19	23.280 mi
Registration #3	2009-11-12	35.173 mi
Registration #4	2009-11-13	35.212 mi
Registration #5	2010-11-08	43.740 mi
Registration #6	2011-10-28	52.613 mi
Registration #7	2012-11-22	69.833 mi
Registration #8	2013-12-06	84.944 mi
Registration #9	2014-11-25	103.911 mi
Registration #10	2014-11-25	103.911 mi
Registration #11	2015-12-16	108.949 mi
Registration #12	2016-12-07	109.845 mi
Registration #13		11.777 es
Registration #13 Registration #14		11.777 es
		11.777 es
Registration #14		10.000 est 10.000 est 10.000 est 10.000 est
Registration #14 Registration #15		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est
Registration #14 Registration #15 Registration #16		01.007 est 01.007 est 01.007 est 01.007 est 01.007 est 01.007 est
Registration #14 Registration #15 Registration #16 Registration #17		11.777 48 11.777 48 11.777 48 11.777 48 11.777 48 11.777 48
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 48 11,777 48 11,777 48 11,777 48 11,777 48 11,777 48 11,777 48
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.777 48 1.777 48 1.777 48 1.777 48 1.777 48 1.777 48 1.777 48 1.777 48
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,227 48 11,227 48 11,227 48 11,227 48 11,227 48 11,227 48 11,227 48 11,227 48 11,227 48 11,227 48
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		10.000 46 10.000 46 10.0000 46 1

More info \rightarrow



LD55ZDZ report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1860 mm
Height	1295 mm
Length	4140 mm
Kerb weight	1260 kg
Additional information	
Fuel tank capacity	50 I
Fuel tank capacity Fuel delivery	50 l Multi-Point Injection
Fuel delivery	Multi-Point Injection
Fuel delivery Number of doors	Multi-Point Injection 2