



WJ60MXS

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	White
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	116 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg



**MOT history****MOT #11** 2021-10-04 09:42**MOT test number** 398108366916**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Rear Exhaust silencer insecure rear box missing (8.1.1 (b) (i))**Advice** Front Fuel Pipe/s corroded**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Fail** Emissions not tested (8.2.1.2 (d))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge showing cracks (5.2.3 (e))**Advice** Front Coil spring corroded both sides (5.3.1 (b) (i))**MOT #10** 2020-09-30 15:48**MOT test number** 251467948097**Result** ✓ Passed**MOT #9** 2020-09-30 09:01**MOT test number** 261885498115**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #8** 2019-10-04 14:41**MOT test number** 629918055458**Result** ✓ Passed**MOT #7** 2019-10-03 15:51**MOT test number** 281692563877**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Fuel filler pipe corroded**MOT #6** 2018-10-31 16:01**MOT test number** 223025059044**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2017-10-31 16:14**MOT test number** 970213215738**Result** ✓ Passed**Advice** Cracking around nearside rear tyre inner sidewall**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**MOT #4** 2016-11-01 15:43**MOT test number** 877504880081**Result** ✓ Passed**Advice** Low on engine oil

**MOT #3** 2015-10-30 10:55**MOT test number** 687683597885**Result** ✓ Passed**MOT #2** 2014-10-28 10:33**MOT test number** 827571204376**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1 2013-11-01 12:56**MOT test number** 779585403389**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-11-10
Last registration	2021-10-04
Complete history	See info



Registration #1	2010-11-10	15 mi
Registration #2	2013-11-01	30.649 mi
Registration #3	2014-10-28	42.659 mi
Registration #4	2015-10-30	56.722 mi
Registration #5	2016-11-01	77.081 mi
Registration #6	2017-10-31	93.843 mi
Registration #7	2018-10-31	110.604 mi
Registration #8	2019-10-31	127.365 mi
Registration #9	2020-10-31	144.126 mi
Registration #10	2021-10-04	160.887 mi
Registration #11	2022-10-04	177.648 mi
Registration #12	2023-10-04	194.409 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3760 mm
Wheel base	2380 mm
Kerb weight	970 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2226353