



BJ07HZM

report date: 2024-03-29

General information

Make	MAZDA
Model	3 SPORT
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	187 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg



**MOT history**

MOT #16	2020-10-20 09:37
MOT test number	403052781239
Result	✓ Passed
Next expiry date	2021-10-19
Advice Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice Offside Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills (6.1.1 (c) (i))	
Advice Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills corroded (6.1.1 (c) (i))	

MOT #15	2020-10-13 13:57
MOT test number	552992553425
Result	✗ Failed
Advice Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills corroded (6.1.1 (c) (i))	
MAJOR Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice Offside Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills (6.1.1 (c) (i))	
MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

**MOT #14**

2019-03-29 13:13

MOT test number

661367606290

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive floor (5.3.6 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive floor (5.3.6 (a) (i))**MOT #13**

2018-03-28 12:54

MOT test number

893376540885

Result

✓ Passed

MOT #12

2018-03-24 13:11

MOT test number

149183278041

Result

✗ Failed

Fail Nearside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #11**

2017-04-24 13:36

MOT test number

353127806500

Result

✓ Passed

**MOT #10** 2017-04-22 11:55**MOT test number** 475148113370**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #9** 2016-04-11 15:59**MOT test number** 855176082880**Result** ✓ Passed**MOT #8** 2016-04-11 15:59**MOT test number** 807813114605**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #7** 2015-04-16 14:27**MOT test number** 617086205182**Result** ✓ Passed**Notice** O/s n/s front lower arm bushes split

**MOT #6** 2015-04-11 10:51**MOT test number** 325471705158**Result** ✗ Failed**Notice** N/s rear tyre worn bald on inside edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** O/s n/s front lower arm bushes split**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #5** 2014-04-09 09:47**MOT test number** 459279894016**Result** ✓ Passed**Notice** O/s n/s front lower arm bushes split/worn**MOT #4** 2013-04-11 11:14**MOT test number** 628661503144**Result** ✓ Passed**Notice** O/s n/s front lower arm bushes worn**MOT #3** 2012-04-14 10:13**MOT test number** 156765502188**Result** ✓ Passed**MOT #2** 2011-04-23 10:03**MOT test number** 585573811100**Result** ✓ Passed**Notice** O/s n/s front & rear tyres worn on edges



MOT #1	2010-03-01 15:09
MOT test number	721250660076
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-31
Last registration	2020-10-20
Complete history	See info



Registration #1	2007-03-31	11 mi
Registration #2	2010-03-01	23.995 mi
Registration #3	2011-04-23	33.429 mi
Registration #4	2012-04-14	43.396 mi
Registration #5	2013-04-11	53.820 mi
Registration #6	2014-04-09	62.956 mi
Registration #7	2015-04-11	73.520 mi
Registration #8	2015-04-16	73.583 mi
Registration #9	2016-04-11	82.947 mi
Registration #10	2016-04-11	82.947 mi
Registration #11	2016-04-11	82.947 mi
Registration #12	2016-04-11	82.947 mi
Registration #13	2016-04-11	82.947 mi
Registration #14	2016-04-11	82.947 mi
Registration #15	2016-04-11	82.947 mi
Registration #16	2016-04-11	82.947 mi
Registration #17	2016-04-11	82.947 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF10348721