



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	TIGRA 16V SPORT
Colour	Black
Year of manufacture	2005
Top speed	112 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 2

Date	2023-01-15
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-02-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-22
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	40
Total items failed	18

MOT #23	2024-01-19 14:43
MOT test number	265258975751
Result	✓ Passed
Next expiry date	2025-01-22
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #22** 2024-01-18 10:05**MOT test number** 115437588709**Result** ✗ Failed**Minor** Nearside Front Brake pipe inadequately clipped or supported (1.1.11 (d) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Inner Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #21** 2023-01-23 18:47**MOT test number** 747416952203**Result** ✓ Passed**MOT #20** 2023-01-19 10:50**MOT test number** 599159843146**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**MOT #19** 2022-03-07 12:26**MOT test number** 786885452524**Result** ✓ Passed**MOT #18** 2021-03-09 14:11**MOT test number** 684276524149**Result** ✓ Passed

**MOT #17** 2019-12-03 10:22**MOT test number** 239976871318**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2018-12-03 15:05**MOT test number** 127581904881**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15** 2018-12-03 10:49**MOT test number** 306819326992**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Pass with rectification** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #14** 2017-11-13 11:17**MOT test number** 159987243477**Result** ✓ Passed

**MOT #13** 2017-11-13 11:17**MOT test number** 168265483342**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #12** 2016-12-09 10:35**MOT test number** 184883409944**Result** ✓ Passed**MOT #11** 2014-05-03 14:07**MOT test number** 678193124128**Result** ✓ Passed**Notice** Park brake cables corroded & frayed**Notice** Brake pipes corroded**MOT #10** 2014-05-03 14:07**MOT test number** 838563624179**Result** ✗ Failed**Notice** Park brake cables corroded & frayed**Notice** Brake pipes corroded**Pass with rectification** Fuel system component leaking (7.2.3)**MOT #9** 2013-05-03 14:12**MOT test number** 405603623180**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)



MOT #8	2013-05-03 12:50
MOT test number	819363723192
Result	✗ Failed
Fail	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #7	2012-09-12 10:42
MOT test number	317206052257
Result	✓ Passed
Advice	Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Notice	Header tank empty
Notice	Front wiper skate across screen intermitantly
Advice	Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Notice	Clutch rubber missing
Notice	Internal bonnet release faulty
Notice	Items removed from driver's view prior to test

**MOT #6** 2012-09-12 09:41**MOT test number** 927966452257**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Front wiper skate across screen intermitantly**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Clutch rubber missing**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Internal bonnet release faulty**Fail** Offside Rear Rear fog lamp not working (1.3.2b)**Notice** Items removed from driver's view prior to test**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Header tank empty**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2011-09-19 13:49**MOT test number** 359472361255**Result** ✓ Passed**MOT #4** 2010-08-06 16:20**MOT test number** 312358710293**Result** ✓ Passed**MOT #3** 2009-09-02 11:21**MOT test number** 782445649278**Result** ✓ Passed





MOT #2	2009-09-01 14:34
MOT test number	431834749214
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Nearside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

MOT #1	2008-08-30 14:01
MOT test number	942383648243
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
22 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	22 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-01
Last registration	2024-01-19
Complete history	<a href="#">See info</a>



Registration #1	2005-09-01	23 mi
Registration #2	2008-08-30	24.701 mi
Registration #3	2009-09-01	35.335 mi
Registration #4	2009-09-02	35.339 mi
Registration #5	2010-08-06	40.417 mi
Registration #6	2011-09-19	48.107 mi
Registration #7	2012-09-12	50.166 mi
Registration #8	2012-09-12	50.166 mi
Registration #9	2013-05-03	51.253 mi
Registration #10	2013-05-03	51.253 mi
Registration #11	2014-05-03	56.863 mi
Registration #12	2016-12-09	58.681 mi
Registration #13	2017-11-13	61.471 mi
Registration #14	2019-05-20	65.377 mi
Registration #15	2019-05-20	65.377 mi
Registration #16	2019-05-20	65.377 mi
Registration #17	2019-05-20	65.377 mi
Registration #18	2019-05-20	65.377 mi
Registration #19	2019-05-20	65.377 mi
Registration #20	2019-05-20	65.377 mi
Registration #21	2019-05-20	65.377 mi
Registration #22	2019-05-20	65.377 mi
Registration #23	2019-05-20	65.377 mi
Registration #24	2019-05-20	65.377 mi
Registration #25	2019-05-20	65.377 mi



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1685 mm
Height	1349 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1160 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	19FP4351