





General information

Make	HONDA
Model	FR-V I-CTDI EX
Colour	Red
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP	0 < 101 A
Max. torque	340 Nm at 2.000 rpm	101 - 120 ^B _C
Cylinders	4	121 - 140
Fuel type	Diesel	141 - 165
Consumption city	35.3 mpg	166 - 185
Consumption extra urban	53.3 mpg	186 - 225
Consumption combined	44.8 mpg	225+





Internet history

Entry	1
Date	

Pictures

2021-09-28

19

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #14		2021-12-03 14:59
MOT test	number	357190380323
Result		✓ Passed
Next expi	ry date	2022-12-02
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice (i))	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or o	cords Wall (5.2.3 (d)
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Advice Rear Coil spring corroded Both (5.3.1 (b) (i))	
Advice	Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Valve stem slightly damaged (5.2.3 (j))	
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))	





MOT #13		2021-12-03 13:01
MOT test	number	127740380453
Result		🗙 Failed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Valve stem slightly damaged (5.2.3 (j))	
Advice	Rear Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))	
Fail Of (5.2.3 (d) (ffside Rear Tyre has a cut in excess of the requirements deep enough to reach the (i))	e ply or cords
Advice (i))	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cor	ds Wall (5.2.3 (d)
Pass wit	th rectification Offside Headlamp aim too high (4.1.2 (a))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or light s	sources (4.7.1 (b)
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))	
Pass wit	th rectification Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #12	2020-11-06 10:10
MOT test number	469547096695
Result	✓ Passed

MOT #11	2019-11-05 15:28
MOT test number	776089539886
Result	✓ Passed





MOT #10	2018-09-04 12:46
MOT test number	397344603234
Result	✓ Passed
MOT #9	2018-09-04 08:52
MOT test number	885192684238
Result	× Failed
Fail Offside Registration plate lamp inoperative in the case of a single la	mp or all lamps (4.7.1 (b) (ii))
МОТ #8	2017-09-12 14:25
MOT test number	364359401616
Result	✓ Passed
MOT #7	2016-08-24 15:11
MOT test number	277115864928
Result	✓ Passed
MOT #6	2015-08-06 12:33
MOT test number	923088738622
Result	✓ Passed
Advice Nearside Front caliper slight binding	
MOT #5	2014-08-20 10:55
MOT test number	329242434429
Result	✓ Passed





✓ Passed

🗸 Passed

MOT #4		2013-08-19 15:57
MOT test ı	number	935041433220
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #3		2012-09-14 11:00
MOT test ı	number	886008552268

Result

MOT #2	2011-10-14 12:31
MOT test number	445947681279
Result	✓ Passed
MOT #1	2010-10-13 10:15
MOT test number	413016280221

Result





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		ASMPL
Date		
Category	10000000	AMPL
Туре		

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-10-12
Last registration	2021-12-03
Complete history	See info



Registration #1	2007-10-12	18 mi
Registration #2	2010-10-13	37.393 mi
Registration #3	2011-10-14	48.738 mi
Registration #4	2012-09-14	59.075 mi
Registration #5	2013-08-19	67.639 mi
Registration #6	2014-08-20	78.915 mi
Registration #7	2015-08-06	89.788 mi
Registration #8	2016-08-24	97.380 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Max. allowed weight	2130 kg
Additional information	
Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of seats Number of axles	6 2