





General information

| Make | LAND ROVER |
|---------------------|---------------------|
| Model | RANGE ROVER TD6 HSE |
| Colour | Black |
| Year of manufacture | 2006 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.7 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 174 BHP |
|-------------------------|---------------------|
| Max. torque | 390 Nm at 2.000 rpm |
| Engine capacity | 2.926 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 19.6 mpg |
| Consumption extra urban | 30.1 mpg |
| Consumption combined | 25.0 mpg |
| CO2 emission | 299 g/km |
| CO2 label | Μ |







Internet history

| Entry 2 | | | |
|---------------|-------------|--|--|
| Date | 2021-08-02 | | |
| Pictures | 26 | | |
| Listing price | View report | | |



source: autotrader.co.uk

Entry 1

Date

Pictures

Listing price

26 <u>View report</u>

2021-07-27



source: autotrader.co.uk



0 005





MOT history

| MOT expiry date | 2023-11-22 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 21 |
| Total items failed | 16 |

| MOT #11 | 2022-11-23 17:37 |
|------------------|------------------|
| MOT test number | 837579688034 |
| Result | ✓ Passed |
| Next expiry date | 2023-11-22 |

| MOT #10 | 2022-11-14 16:08 |
|--|----------------------------------|
| MOT test number | 459817734499 |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre has a cut in excess of the requirements deep enortread (5.2.3 (d) (i)) | ugh to reach the ply or cords on |

Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on tread (5.2.3 (d) (i))

| МОТ #9 | 2020-12-18 08:30 |
|-----------------|------------------|
| MOT test number | 480961394767 |
| Result | ✓ Passed |
| | |

| MOT #8 | 2020-02-24 18:34 |
|-----------------|------------------|
| MOT test number | 244216838217 |
| Result | ✓ Passed |



| MC56HHY |
|-------------------------|
| report date: 2024-03-29 |

| MOT # | 7 | 2020-01-24 11:43 |
|--------|---|------------------|
| MOT te | st number | 864499779063 |
| Result | | 🗙 Failed |
| Fail | Nearside Front Brake pipe excessively corroded (1.1.11 (c)) | |
| Fail | Nearside Brake pipe excessively corroded front to rear (1.1.11 (c)) | |
| Fail | Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) | |
| Fail | Offside Front Brake pipe excessively corroded (1.1.11 (c)) | |
| Fail | Offside Brake pipe excessively corroded front to rear (1.1.11 (c)) | |

| MOT #6 | | 2018-12-18 09:38 |
|--------------------------|---|-------------------|
| MOT test | number | 295046258416 |
| Result | | ✓ Passed |
| Advice | Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Brake pipe corroded, covered in grease or other material both front to rears (| (1.1.11 (c)) |
| Advice (5.3.4 (a) | Nearside Rear Upper Suspension arm pin or bush worn but not resulting in ex (i)) | ccessive movement |
| Advice | Slight oil leaks | |

| MOT #5 | | 2017-12-27 15:57 |
|----------|--|------------------|
| MOT test | number | 364674894263 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Upper Suspension arm has slight play in a pin/bush (2.4.G.2) | |
| Advice | Rear Brake pipe slightly corroded front to rears (3.6.B.2c) | |
| Advice | Oil leak | |
| Advice | Front Steering system has slight free play detected at steering wheel x2 racke | nds (2.2.A.1b) |
| Advice | Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2) | |





| МОТ #4 | 2016-0 | 7-07 10:24 |
|--------------------|---|------------|
| MOT test | number 8182 | 216021153 |
| Result | | 🗸 Passed |
| Advice | Nearside Front Track rod end ball joint has slight play (2.2.B.1f) | |
| Advice | Rear Tyre worn close to the legal limit x2 inner edges (4.1.E.1) | |
| Advice | Brake pipe slightly corroded front to rears (3.6.B.2c) | |
| Advice | Nearside Front Steering system has slight free play detected at steering wheel (2.2.A.1b |) |
| Advice movement | Nearside Rear Upper Suspension arm rubber bush deteriorated but not resulting in excest (2.4.G.2) | ssive |
| Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | |

| MOT #3 | 2016-07-04 11:19 |
|---|------------------|
| MOT test number | 571528287979 |
| Result | 🗙 Failed |
| Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Brake pipe slightly corroded front to rears (3.6.B.2c) | |
| Advice Nearside Front Steering system has slight free play detected at steering whee | el (2.2.A.1b) |
| FailRear Brake pad(s) less than 1.5 mm thick (3.5.1g) | |
| Advice Nearside Rear Upper Suspension arm rubber bush deteriorated but not result movement (2.4.G.2) | ng in excessive |
| Fail Offside Rear Brake pipe excessively corroded chalked part of flexi (3.6.B.2c) | |
| Fail Front Windscreen wiper does not clear the windscreen effectively x2 (8.2.2) | |
| Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f) | |
| Advice Rear Tyre worn close to the legal limit x2 inner edges (4.1.E.1) | |
| Fail Rear Anti-roll bar fractured x2 links (2.4.G.1) | |





| MOT #2 | 2015-07-03 10:51 |
|--|------------------|
| MOT test number | 888174685137 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2015-06-30 10:58 |
| MOT test number | 465171885173 |
| Result | × Failed |
| Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3) | |
| Fail Offside Rear Upper Suspension arm has excessive play in a ball joint (2.4. | G.2) |
| Fail Nearside Rear Lower Suspension arm has excessive play in a ball joint (2. | 4.G.2) |
| Fail Exhaust emits excessive smoke or vapour of any colour (7.4.B.4) | |





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| | MP1E |
| Category | ter . |
| Туре | |

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | | |
|---|-----------|---|
| ********** | | |
| And a second s | | |
| | | |
| | | |
| | | |
| ******** | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this LAND ROVER had different number plates. | | |

| Number of plates | |
|----------------------|-------------|
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 14 |
| First mileage registration | 2006-12-31 |
| Last registration | 2022-11-23 |
| Complete history | <u>See info</u> |



| Registration #1 | 2006-12-31 | 29 mi |
|--------------------------------------|------------|--|
| Registration #2 | 2015-06-30 | 95.398 mi |
| Registration #3 | 2015-07-03 | 95.398 mi |
| Registration #4 | 2016-07-04 | 101.714 mi |
| Registration #5 | 2016-07-07 | 101.714 mi |
| Registration #6 | 2017-12-27 | 111.682 mi |
| Registration #7 | 2018-12-18 | 115.193 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | |
| | | |
| Registration #10 | | 11.000 est |
| Registration #10 Registration #11 | | 0.100 es |
| - | | 0.000 est 0.000 est 0.000 est |
| Registration #11 | | 0.000 est 0.000 est 0.000 est 0.000 est |

More info \rightarrow





Safety ratings

NCAP rating

Video

<u>see crash video</u>



| Dimensions & weight | |
|--|--------------------------|
| Width | 2191 mm |
| Height | 1863 mm |
| Length | 4950 mm |
| Wheel base | 2880 mm |
| Max. allowed weight | 3050 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 90 I |
| | 90 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |