



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC CLIMATE
Colour	Grey
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	106 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-03
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #16</b>	2021-06-04 09:43
<b>MOT test number</b>	656654711166
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-06-03
<b>Advice</b>	Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Front Shock absorbers has a slightly worn bush slight play in nearside and offside top mounts (5.3.2 (c))
<b>Advice</b>	Offside Integral body structure is corroded but structural rigidity is not significantly reduced offside outer sill corroded (6.1.1 (c) (i))

<b>MOT #15</b>	2020-05-02 07:34
<b>MOT test number</b>	796370019987
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Shock absorbers has a slightly worn bush Both top mounts (5.3.2 (c))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Body corrosion

**MOT #14**

2020-04-24 15:13

**MOT test number**

409363703801

**Result****✗ Failed**

- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill and inner wing (6.1.1 (c) (i))
- Fail** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced near seat belt mounting (7.1.1 (a) (i))
- Advice** Body corrosion
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Rear Suspension component pin or bush excessively worn axle bush (5.3.4 (a) (i))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill (6.1.1 (c) (i))
- Fail** Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced near seat belt mounting (7.1.1 (a) (i))
- Advice** Front Shock absorbers has a slightly worn bush Both top mounts (5.3.2 (c))
- Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Offside Rear Suspension component pin or bush excessively worn axle bush (5.3.4 (a) (i))

**MOT #13**

2019-07-03 13:32

**MOT test number**

635952744403

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Badly cracked and perished (5.2.3 (d) (ii))
- Advice** Slight corrosion to both sills
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Badly cracked and perished (5.2.3 (d) (ii))



**MOT #12** 2019-07-03 13:32**MOT test number** 265001287722**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Badly cracked and perished (5.2.3 (d) (ii))**Advice** Slight corrosion to both sills**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Badly cracked and perished (5.2.3 (d) (ii))**MOT #11** 2018-07-03 15:16**MOT test number** 519285560463**Result** ✓ Passed**MOT #10** 2018-07-03 07:54**MOT test number** 513612341394**Result** ✗ Failed**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength under car sill as marked (5.3.6 (a) (i))**MOT #9** 2017-07-03 10:26**MOT test number** 567690984088**Result** ✓ Passed

**MOT #8**

2017-07-03 10:26

**MOT test number**

608733873160

**Result**

✗ Failed

- Pass with rectification** Offside Front Headlamp aim too high (1.8)
- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)
- Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)

**MOT #7**

2016-07-02 09:49

**MOT test number**

233245215579

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Ball joint has slight play (2.2.B.1f)

**MOT #6**

2015-06-02 12:38

**MOT test number**

339303155178

**Result**

✓ Passed

- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5**

2014-06-30 14:46

**MOT test number**

905191984198

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2013-07-01 16:47**MOT test number** 776202283168**Result** ✓ Passed**MOT #3** 2013-07-01 11:45**MOT test number** 568362683179**Result** ✗ Failed**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Inner Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Inner Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #2** 2012-06-16 11:19**MOT test number** 449448962123**Result** ✓ Passed**MOT #1** 2011-06-24 14:10**MOT test number** 436935871105**Result** ✓ Passed





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>VE08WXC</b>
Plate since	2019-03-28
Current registration	<b>VE08WXC</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-27
Last registration	2021-06-04
Complete history	<a href="#">See info</a>



Registration #1	2008-06-27	18 mi
Registration #2	2011-06-24	35.028 mi
Registration #3	2012-06-16	44.138 mi
Registration #4	2013-07-01	51.891 mi
Registration #5	2013-07-01	51.892 mi
Registration #6	2014-06-30	58.061 mi
Registration #7	2015-06-02	64.483 mi
Registration #8	2016-07-02	72.369 mi
Registration #9	2017-07-03	79.284 mi
Registration #10	2018-06-27	85.217 mi
Registration #11	2019-06-27	91.150 mi
Registration #12	2020-06-27	97.083 mi
Registration #13	2021-06-04	103.016 mi
Registration #14	2022-06-27	108.949 mi
Registration #15	2023-06-27	114.882 mi
Registration #16	2024-06-27	120.815 mi
Registration #17	2025-06-27	126.748 mi
Registration #18	2026-06-27	132.681 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	905 kg
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number

7P13319