





report date: 2024-03-28

### General information

Make	FORD
Model	RANGER DCB 4X4
Colour	Silver
Year of manufacture	2009
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	140 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/17



report date: 2024-03-28

# MOT history

MOT expiry date	2024-06-06
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	87
Total items failed	11

MOT #19	2023-06-07 16:11
MOT test number	426159432635
Result	✓ Passed
Next expiry date	2024-06-06
Advice Front Suspension arm corroded but not seriously weakened upper and lower (5.3.3 (b) (i))	er arms both sides
Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice Power steering component has slight seepage from a component steering	box (2.1.5 (a))
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))	

CarCheck.co.uk page 2/17



report date: 2024-03-28

**MOT #18** 2023-06-07 12:27

**MOT test number** 610383445772

Result X Failed

**Advice** Front Suspension arm corroded but not seriously weakened upper and lower arms both sides (5.3.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))

Advice Power steering component has slight seepage from a component steering box (2.1.5 (a))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

CarCheck.co.uk page 3/17



report date: 2024-03-28

## MOT #17 2022-05-31 12:41

**MOT test number** 750478227044

Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Under body covered in underseal
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Steering box has seepage (2.1.1 (e) (i))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Offside Front Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Towbar component corroded, but not excessively (6.1.6 (a))

CarCheck.co.uk page 4/17



report date: 2024-03-28

**MOT #16** 2022-04-28 11:23

**MOT test number** 793064726297

Result × Failed Advice Vehicle in rusty condition **MAJOR** Nearside Front Anti-roll bar linkage corroded and seriously weakened (5.3.3 (b) (i)) MAJOR Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i)) Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i)) **MAJOR** Nearside Front Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i)) Advice Offside Front Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Towbar component corroded, but not excessively (6.1.6 (a)) **MAJOR** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **MAJOR** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i)) Minor Steering box leaking oil (2.1.1 (e) (i)) Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i)) MAJOR Offside Front Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i)) Nearside Front Play in steering rack inner joint(s) Advice Advice Nearside Front Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) **DANGEROUS** Offside Front Brake master cylinder/servo mounting prescribed area is excessively corroded and functionality of the braking system is affected (1.1.21 (e) (ii)) Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **MAJOR** Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

CarCheck.co.uk page 5/17



report date: 2024-03-28

**MOT #15** 2021-04-28 10:47

**MOT test number** 754596530240

**MOT #14** 2020-07-15 13:07

**MOT test number** 934854666768

Result 

Passed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Steering box leaking oil (2.1.1 (e) (i))

**MOT #13** 2020-07-15 08:46

**MOT test number** 212237126332

**Result** X Failed

**DANGEROUS** Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MAJOR** Brake load sensing valve seized but ABS functioning (1.1.17 (c) (i))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Minor** Steering box leaking oil (2.1.1 (e) (i))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #12** 2019-07-09 14:34

**MOT test number** 789049947119

**Result** 
✓ Passed

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 6/17



report date: 2024-03-28

**MOT #11** 2019-07-09 12:07

**MOT test number** 762107336155

Result X Failed

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #10** 2018-06-07 07:47

MOT test number 856207292306

Result 

Passed

MOT #9 2017-05-22 14:49

**MOT test number** 353705596306

Result 

Passed


**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 7/17



report date: 2024-03-28



MOT #7	2016-03-15 18:43
MOT test number	746169800506
Result	✓ Passed
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)  Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 8/17



Fail

SY09SBU

report date: 2024-03-28

**MOT** #6 2016-03-14 15:42 **MOT** test number 857353267071 Result × Failed Fail Brake pipe excessively corroded 3 pipes at load valve (3.6.B.2c) **Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c) Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Offside Rear Leaf spring fractured (2.4.B.1a) Fail Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c) **Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i) Fail Nearside Rear Leaf spring fractured (2.4.B.1a) **Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #5

MOT test number

Fesult

Advice

Brake pipe slightly corroded (3.6.B.2c)

Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Underside needs cleaned all mud/dirt

CarCheck.co.uk page 9/17



report date: 2024-03-28

MOT #3 2013-04-10 15:46

**MOT test number** 408020703169

**Result** ✓ Passed

MOT #2 2013-04-09 13:01

**MOT test number** 757969093043

**Result** X Failed

Fail Offside Front Seat belt flexible stalk deteriorated likely to lead to failure under load (5.2.4a)

MOT #1 2012-03-01 14:47

MOT test number 458081062064

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 10/17



report date: 2024-03-28

### Tax & MOT check



Days left 95

MOT expiry date 6 June 2024

Full MOT history See MOT history

CarCheck.co.uk page 11/17



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



SY09SBU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	
***************************************	
***************************************	
THE PARTY OF THE P	
***************************************	
*************	
	More info >
	110100
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 14/17



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 15/17



SY09SBU report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-13
Last registration	2023-06-07
Complete history	See info



Registration #1	2009-03-13	19 mi
Registration #2	2012-03-01	24.263 mi
Registration #3	2013-04-09	34.015 mi
Registration #4	2013-04-10	34.015 mi
Registration #5	2014-05-12	40.750 mi
Registration #6	2015-05-08	49.168 mi
Registration #7	2016-03-14	59.112 mi
Registration #8	2016-03-15	59.112 mi
Registration #9	2017-05-20	71.094 mi
Registration #10	2017-05-22	71.124 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		71.777 es
Registration #19		D.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 16/17



SY09SBU report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	*****
Video	see crash video



## Additional information

-	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	113188

CarCheck.co.uk page 17/17