





General information

Make	VOLKSWAGEN
Model	LUPO E
Colour	Green
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	57.6 mpg
Consumption combined	44.8 mpg



Internet history

Entry	1

Date Pictures 2021-09-24

14

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #22		2022-01-04 11:44
MOT test	number	112565312806
Result		✓ Passed
Next expi	ry date	2023-01-15
Advice	Front Direction indicator slightly discoloured Both front indicators disco	loured (4.4.3 (a))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front suspension struts running close to front tyres	
Advice shrouds (4	Headlamp has a product on the lens but not seriously reducing light ou 1.1.4 (b))	tput Both headlamps have
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Both front interior door cards loose	

MOT #21		2021-01-07 09:54
MOT test	number	416430976383
Result		✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (:))



BU51WWZ report date: 2024-03-29

MOT #20	2021-01-05 12:20
MOT test number	427439162354
Result	🗙 Failed
Advice Rear Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c)))
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Fail Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
FailOffside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Battery insecure and likely to fall from carrier (4.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))	
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	



B	U	5	1	W	W	Ζ
	re	epoi	rt d	ate: 2	2024-0)3-29

MOT #19		2020-01-16 15:19
MOT test	number	812443481166
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Brake pipe corroded, covered in grease or other material all rear brake pipes co	rroding (1.1.11
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 ($lpha$	2))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect	: (5.3.2 (b))
Minor	Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a	a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	





MOT #18		2020-01-16 14:55
MOT test	number	961692328866
Result		🗙 Failed
Advice (c))	Brake pipe corroded, covered in grease or other material all rear brake pipes cor	roding (1.1.11
Advice	Engine management light on	
Fail E (a))	xhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specifi	ed limits (8.2.1.2
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5	5.3.2 (b))
Minor	Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect	(5.3.2 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	





MOT #17		2019-01-11 14:31
MOT test	number	331848362141
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material all rear pipes corroding	g (1.1.11 (c))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Minor	Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a	n) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	



BU51WWZ report date: 2024-03-29

MOT #16 2	2019-01-07 11:54
MOT test number	696623437318
Result	🗙 Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b)))
Minor Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Fail Offside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))	
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Brake pipe corroded, covered in grease or other material all rear pipes corroding (2	1.1.11 (c))
Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))	
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	



B	U	5	1	W	W	ΙZ
	re	epoi	't d	ate: 2	2024-	03-29

MOT #15		2018-01-10 16:13
MOT test	number	292733058564
Result		✓ Passed
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Front Sub-frame corroded but not seriously weakened (2.4.G.1)	
Advice	Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Central Stop lamp has light sources not illuminating, but not more than 50% (1.2)	2.1b)



BU51WWZ report date: 2024-03-29

MOT #14 2018-	01-08 10:40
MOT test number 560	0599960119
Result	🗙 Failed
Advice Front Sub-frame corroded but not seriously weakened (2.4.G.1)	
Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Offside Front Suspension arm corroded but not seriously weakened (2.4.G.1)	
Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)	
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)	
Advice Offside Rear coil spring corroded (2.4.C.1b)	
Advice Engine management light on	
Advice Nearside Front Suspension arm corroded but not seriously weakened (2.4.G.1)	
Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
FailExhaust has a major leak of exhaust gases catalyst (7.1.2)	
Advice Nearside Rear coil spring corroded (2.4.C.1b)	

MOT #13	2017-01-05 12:16
MOT test number	444250330926
Result	✓ Passed

MOT #12	2017-01-04 10:09
MOT test number	139551751555
Result	🗙 Failed
Fail Nearside Direction indicators not working (1.4.A.2c)	





MOT #11	2016-01-13 09:49
MOT test number	711599984708
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #10	2015-01-14 12:06
MOT test number	639044215040
Result	✓ Passed
MOT #9	2013-12-16 14:53
MOT test number	809820453362
Result	✓ Passed
MOT #8	2012-12-20 13:37
MOT test number	545745452320
Result	✓ Passed
MOT #7	2011-12-19 14:17
MOT test number	125863451342
Result	✓ Passed
МОТ #6	2010-12-20 12:14
MOT test number	404114850418
Result	✓ Passed
MOT #5	2009-12-21 11:27
MOT test number	543935759385
Result	Passed





MOT #4 2008-12-12 09:27 **MOT test number** 823267348306 Result ✓ Passed MOT #3 2008-01-10 16:45 791300618001 **MOT test number** Result Passed Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) MOT #2 2007-06-12 15:07 692983967119 **MOT test number** Result 🗸 Passed

MOT #1	2005-10-24 09:35
MOT test number	514007395251
Result	✓ Passed
Advice Tyre worn close to the legal limit (4.1.E.1)	





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDER
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CONTROL ON
Date	S.
Category	AMPY
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
and the second sec	

And a second s	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-09-20
Last registration	2022-01-04
Complete history	See info



Registration #1	2001-09-20	17 mi
Registration #2	2005-10-24	26.538 mi
Registration #3	2007-06-12	37.800 mi
Registration #4	2008-01-10	39.402 mi
Registration #5	2008-12-12	44.914 mi
Registration #6	2009-12-21	48.188 mi
Registration #7	2010-12-20	52.450 mi
Registration #8	2011-12-19	58.016 mi
Registration #9	2012-12-20	63.484 mi
Registration #10	2013-12-16	69.029 mi
Registration #11	2015-01-14	72.637 mi
Registration #12	2016-01-13	74.625 mi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #14 Registration #15		11.777 es
-		11.777 es
Registration #15		0.777 es 0.777 es 0.777 es 0.777 es
Registration #15 Registration #16		0.777 es 0.777 es 0.777 es 0.777 es 0.777 es
Registration #15 Registration #16 Registration #17		11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est
Registration #15 Registration #16 Registration #17 Registration #18		0.777 es 0.777 es 0.777 es 0.777 es 0.777 es 0.777 es
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		11.777 46 11.777 46







Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1860 mm
Height	1459 mm
Length	3527 mm
Wheel base	2321 mm
Additional information	
Fuel tank capacity	34 I
Fuel delivery	Multi-Point Injection
Number of doors	3

2

AUA010470

Number of axles

Engine number