



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA 12V EXPRESSION TWINPORT
Colour	Blue
Year of manufacture	2005
Top speed	88 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	58 BHP
Max. torque	85 Nm at 3.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-25
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-27
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	21
Total items failed	13

MOT #21	2023-05-25 09:29
MOT test number	199812450771
Result	✓ Passed
Next expiry date	2024-05-27
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20	2022-05-26 08:26
MOT test number	983902012172
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #19	2021-05-28 12:52
MOT test number	269834015756
Result	✓ Passed

MOT #18	2020-09-28 13:19
MOT test number	758847496028
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2020-09-28 08:29

MOT test number

309693776950

Result**✗ Failed**

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Rear Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))

MOT #16

2019-10-02 10:06

MOT test number

625569176485

Result**✓ Passed**

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

2019-10-02 08:27

MOT test number

619204712725

Result**✗ Failed**

Fail Rear Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2018-09-17 11:44

MOT test number

903654168965

Result**✓ Passed**

Advice Creaking noise from front shock absorber area.

**MOT #13**

2018-09-17 08:42

MOT test number

307177044469

Result**✗ Failed**

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Creaking noise from front shock absorber area.
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #12

2017-09-14 10:30

MOT test number

566493093438

Result**✓ Passed**

- Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #11

2017-09-14 08:52

MOT test number

377148032153

Result**✗ Failed**

- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #10** 2016-10-03 09:49**MOT test number** 476309189520**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #9** 2015-10-09 10:07**MOT test number** 157243123888**Result** ✓ Passed**MOT #8** 2014-12-03 08:58**MOT test number** 466977034381**Result** ✓ Passed**MOT #7** 2013-12-20 09:10**MOT test number** 117474853363**Result** ✓ Passed**MOT #6** 2012-12-03 16:35**MOT test number** 479868332484**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-12-14 08:56**MOT test number** 939658841380**Result** ✓ Passed

**MOT #4** 2010-12-14 10:13**MOT test number** 462398340489**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #3** 2010-12-14 10:13**MOT test number** 242538040316**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #2** 2009-12-08 09:31**MOT test number** 691832649301**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Nail in offside rear tyre**MOT #1** 2008-12-15 10:56**MOT test number** 313860058318**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
27 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	27 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-28
Current registration	 VAUXH
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-23
Last registration	2023-05-25
Complete history	See info



Registration #1	2005-12-23	26 mi
Registration #2	2008-12-15	3.563 mi
Registration #3	2009-12-08	4.926 mi
Registration #4	2010-12-14	6.512 mi
Registration #5	2011-12-14	7.934 mi
Registration #6	2012-12-03	9.859 mi
Registration #7	2013-12-20	11.649 mi
Registration #8	2014-12-03	13.465 mi
Registration #9	2015-10-09	19.423 mi
Registration #10	2016-10-03	25.605 mi
Registration #11	2017-09-14	31.586 mi
Registration #12	2018-05-22	35.277 mi
Registration #13	2018-05-22	35.277 mi
Registration #14	2018-05-22	35.277 mi
Registration #15	2018-05-22	35.277 mi
Registration #16	2018-05-22	35.277 mi
Registration #17	2018-05-22	35.277 mi
Registration #18	2018-05-22	35.277 mi
Registration #19	2018-05-22	35.277 mi
Registration #20	2018-05-22	35.277 mi
Registration #21	2018-05-22	35.277 mi
Registration #22	2018-05-22	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1660 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	965 kg
Max. allowed weight	1435 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19EH5413