





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SHARAN S TDI (115BHP)
Colour	Blue
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.2 mpg
CO2 emission	196 g/km
CO2 label	J



CarCheck.co.uk page 1/19



report date: 2024-03-29


Internet history

Entry 1

Date 2021-08-26

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/19



report date: 2024-03-29

MOT history

MOT expiry date	2022-08-22
MOT pass rate	50 %
MOT passed	12
Failed MOT tests	12
Total advice items	57
Total items failed	65

MOT #24	2021-08-23 15:47
MOT test number	845906029603
Result	✓ Passed
Next expiry date	2022-08-22
Advice Offside Rear Vehicle structure is corroded but structural (c) (i))	I rigidity is not significantly reduced (6.1.1
Advice Nearside Rear Vehicle structure is corroded but structure (6.1.1 (c) (i))	ral rigidity is not significantly reduced
Advice Rear Brake pipe corroded, covered in grease or other m	naterial both (1.1.11 (c))

CarCheck.co.uk page 3/19



report date: 2024-03-29

MOT #23 2021-08-16 17:21

MOT test number 215426840855

Result X Failed

Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

Fail Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Front Brake disc in such a condition that it is seriously weakened both (1.1.14 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #22 2020-07-28 14:10

MOT test number 411993250875

Result \(\sqrt{Passed} \)

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/19



report date: 2024-03-29

MOT #21 2020-07-28 11:40

MOT test number 403721180206

Result X Failed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 5/19



ADO8DBZ

report date: 2024-03-29

MOT #20 2020-02-27 13:26

MOT test number 737267705772 Result × Failed Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii)) Offside Front Brake hose excessively twisted (1.1.12 (b) (ii)) Fail Advice Oil leak, but not excessive (8.4.1 (a) (i)) Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Transmission issue car struggles to drive Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) Fail Nearside Front Steering linkage ball joint worn to the extent there is a serious risk of detachment inner joint (2.1.3 (b) (ii)) Nearside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i)) Fail Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i)) Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Nearside Front brake pipe was damp, pumped brake several times no further leak Fail Offside Front Brake pipe excessively corroded flexi to calliper (1.1.11 (c)) Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Fail** Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii)) **Advice** Oil leak, but not excessive transmission (8.4.1 (a) (i)) Fail Fuel pipe insecure fuel filter hanging loose pipes touching engine block (6.1.3 (a) (i)) Tailgate cannot be secured in the closed position (6.2.1 (e)) Fail **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Suspension arm pin or bush excessively worn FRONT BUSH (5.3.4 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources CarCheckico.µk page 6/19 Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Rear Brake pipe leaking on a hydraulic braking system on suspension arm (1.1.11 (b) (ii))

Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))



report date: 2024-03-29

MOT #19 2019-01-04 08:24

MOT test number 789565847902

Result ✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MOT #18 2018-12-20 15:39

MOT test number 692142072245

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Minor Nearside Obligatory mirror slightly damaged mirror cracked (3.3 (b) (i))

Fail Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))

Exhaust emissions exceed manufacturer's specified limit plate limit 0.60 1/m (8.2.2.2 (a))

Fail Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

MOT #17 2017-12-29 10:51

MOT test number 138363806581

Result ✓ Passed

CarCheck.co.uk page 7/19



report date: 2024-03-29

MOT #16

MOT test number

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Fail Nearside Front Headlamp aim beam image obviously incorrect dip (1.8.A.1b)

Fail Offside Front Headlamp aim beam image obviously incorrect dip (1.8.A.1b)

MOT test number

Result

Advice (2.4.G.2)

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT test number

157792750186

Result

Advice (2.4.G.2)

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.5.A.1c)

Advice (2.4.G.2)

Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)

Advice (2.4.G.2)

MOT #13 2016-11-18 12:31
MOT test number 132918223478
Result ✓ Passed

CarCheck.co.uk page 8/19



report date: 2024-03-29

MOT #12 2016-02-03 14:37 **MOT test number** 777934155075 Result ✓ Passed **Advice** Track rod end ball joint has slight play nsf (2.2.B.1f) Tyre worn close to the legal limit osf (4.1.E.1) Advice Advice Osf sill damaged Advice Exhaust has a minor leak of exhaust gases (7.1.2) Advice Offside oil leak Advice Anti-roll bar linkage worn but not seriously weakened nsf (2.4.G.1)

MOT #11	2016-01-26 16:29
MOT test number	619062631518
Result	★ Failed
Fail Exhaust system not adequately supported (7.1.1)	
Advice Track rod end ball joint has slight play nsf (2.2.B.1f)	
Advice Osf sill damaged	
Advice Tyre worn close to the legal limit osf (4.1.E.1)	
Advice Exhaust has a minor leak of exhaust gases (7.1.2)	
Fail Macpherson strut worn and seriously weakened front both (2.4.G.1)	
Advice Offside oil leak	
Fail Front brake application uneven (3.7.B.2)	
Fail Front position lamp(s) not working osf (1.1.A.3b)	
Advice Anti-roll bar linkage worn but not seriously weakened nsf (2.4.G.1)	

CarCheck.co.uk page 9/19



report date: 2024-03-29

MOT #10

MOT test number

878723515161

Result

Notice Play in steering rack inner joint(s)

Notice Under-trays fitted obscuring some underside components

MOT #9 2015-04-23 13:07 **MOT** test number 867463015134 Result **X** Failed Fail Offside Front Headlamp excessively damaged so that the light output is severely reduced (1.7.5a) Notice Play in steering rack inner joint(s) Fail Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2) Fail Nearside Rear Rear reflector excessively damaged so that its function is impaired (1.5.1c) Notice Under-trays fitted obscuring some underside components Fail Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT test number

Result

Advice

Offside Front Drag link end ball joint has slight play (2.2.B.1f)

Advice

Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice

Under-trays fitted obscuring some underside components

Advice

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

 MOT #7
 2013-04-23 08:56

 MOT test number
 505393413102

 Result
 ✓ Passed

CarCheck.co.uk page 10/19



report date: 2024-03-29

MOT #6

MOT test number

938938803122

Result

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT test number

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Bonnet cannot be secured in the closed position (8.4.1)

Fail Offside Headlamp aim too low (1.8)

MOT #4		2012-11-23 16:33
MOT test	number	465808122327
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Shock absorber has a slightly worn shock absorber pivot (2.7.4)	
Advice	Offside Front Macpherson strut has slight movement at the upper attachment	t (2.5.A.1c)
Advice	Offside Front Steering arm damaged but serviceable (2.2.C.1d)	
Advice	Nearside Rear Shock absorber has a slightly worn shock absorber pivot (2.7.4	1)
Advice	Nearside Front Macpherson strut has slight movement at the upper attachme	ent (2.5.A.1c)
Advice	Nearside Front Steering arm damaged but serviceable (2.2.C.1d)	

CarCheck.co.uk page 11/19



report date: 2024-03-29

MOT #3 2012-11-20 13:47

MOT test number 365015322302

Result X Failed

Fail Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)

Fail Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)

Fail Offside Headlamp aim too low (1.8)

MOT #2 2011-09-02 12:27

MOT test number 397545941469

Result ✓ Passed

MOT #1 2011-09-01 10:40

MOT test number 705204341239

Result × Failed

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Headlamp aim too low (1.8)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Notice Brake lining lamp on

CarCheck.co.uk page 12/19



report date: 2024-03-29

Tax & MOT check



Tax expired: 30 September 2021

Х мот

Expired: 22 August 2022

Tax status	Expired at 30 September
Days left	942 days too late
MOT expiry date	22 August 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 13/19



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Туре

Date

Damage 2

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 14/19



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 15/19



report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 16/19



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 17/19



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2008-04-01
Last registration	2021-08-23
Complete history	See info



Registration #1	2008-04-01	12 mi
Registration #2	2011-09-01	92.304 mi
Registration #3	2011-09-02	92.309 mi
Registration #4	2012-11-20	97.033 mi
Registration #5	2012-11-23	97.043 mi
Registration #6	2013-04-17	98.689 mi
Registration #7	2013-04-18	98.729 mi
Registration #8	2013-04-23	98.781 mi
Registration #9	2014-04-23	124.336 mi
Registration #10	2015-04-23	128.784 mi
Registration #11	2015-04-23	128.784 mi
Registration #12	2016-01-26	133.965 mi
Registration #13	2016-02-03	133.965 mi
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		11.777 es

CarCheck.co.uk page 18/19



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1759 mm
Length	4634 mm
Wheel base	2841 mm
Kerb weight	1957 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
CarChaelesaule	maga 10/10

CarCheck.co.uk page 19/19

Number of seats	7
Number of axles	2
Engine number	BVK 026091