



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA SI
Colour	Red
Year of manufacture	2001
Top speed	85 mph
0 - 60 mph	19.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	58 BHP
Max. torque	84 Nm at 3.250 rpm
Engine capacity	999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G






Internet history

Entry 2



Date	2022-02-22
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2022-02-17
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-08-05
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	59
Total items failed	27

MOT #27	2023-08-04 17:00
---------	------------------

MOT test number	291452115213
-----------------	--------------

Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive engine and gearbox have small oil leak (8.4.1 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front both front Drive shaft joint constant velocity boot clips loose leaking grease but not insecure
Advice	Rear Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material both rear small pipes to drums (1.1.11 (c))

**MOT #26** 2022-07-16 08:18**MOT test number** 148815677487**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #25** 2022-07-16 08:18**MOT test number** 470738437359**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #24** 2021-08-06 11:03**MOT test number** 615570992183**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #23** 2020-07-27 12:41**MOT test number** 792343576699**Result** ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Both headlamp patterns deteriorated

**MOT #22** 2019-08-02 14:22**MOT test number** 696553643287**Result** ✓ Passed

- Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill (7.1.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened very corroded on inner faces. (1.1.14 (a) (ii))
- Advice** Offside Rear chassis corroded
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive rear axle retaining bar from axle to body very corroded advise further investigation (5.3.6 (a) (i))
- Advice** Front both brakes slight binding
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill (7.1.1 (a) (i))
- Advice** Exhaust corroded.
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear chassis corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #21**

2018-03-20 15:17

**MOT test number**

473333012279

**Result**

✓ Passed

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill and under arch (2.4.A.3)

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill and under arch (2.4.A.3)

**MOT #20**

2018-03-12 12:43

**MOT test number**

479990079659

**Result**

✗ Failed

**Fail** Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Emissions not tested exhaust blocked from broken up catalytic converter (7.3.A.1)

**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded sill end (2.4.A.3)

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill and under arch (2.4.A.3)

**Fail** Offside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Exhaust has a major leak of exhaust gases (7.1.2)

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill and under arch (2.4.A.3)

**MOT #19**

2017-03-14 10:21

**MOT test number**

627821246376

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill/floor (5.2.6)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill/floor (5.2.6)



**MOT #18**

2017-03-08 15:30

**MOT test number**

232633141113

**Result**

✗ Failed

**Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill/floor (5.2.6)

**Fail** Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Rear Seat belt anchorage prescribed area is excessively corroded outer sill end. (5.2.6)

**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill/floor (5.2.6)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #17**

2016-02-27 09:30

**MOT test number**

837262803685

**Result**

✓ Passed

**MOT #16**

2016-02-22 14:44

**MOT test number**

530353591123

**Result**

✗ Failed

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Engine missfiring

**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

**Fail** Offside Rear Outer Seat belt anchorage prescribed area is excessively corroded wing (5.2.6)

**Fail** Offside rear brake recording little or no effort (3.7.B.5a)

**Advice** E M L illuminated



**MOT #15**

2015-03-06 16:06

**MOT test number**

827505365003

**Result**

✓ Passed

**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** Slight cracking in rear tyres and o/s rear tyre getting down**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Slight corrosion in front discs**MOT #14**

2015-02-24 17:09

**MOT test number**

736835255011

**Result**

✗ Failed

**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Slight cracking in rear tyres and o/s rear tyre getting down**Notice** Slight corrosion in front discs**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #13**

2014-02-26 16:13

**MOT test number**

505257354022

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #12</b>	2014-02-26 10:49
----------------	------------------

<b>MOT test number</b>	116947054081
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)
-------------	---

<b>Fail</b>	Brakes imbalanced across an axle (3.7.B.5b)
-------------	---

<b>Fail</b>	Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
-------------	---

<b>Fail</b>	Service brake: efficiency below requirements (3.7.B.7)
-------------	--

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #11</b>	2013-02-22 11:44
----------------	------------------

<b>MOT test number</b>	447713553050
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #10</b>	2012-03-05 10:36
----------------	------------------

<b>MOT test number</b>	145485162435
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2011-03-16 09:10
---------------	------------------

<b>MOT test number</b>	705905471028
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2010-12-03 16:19
---------------	------------------

<b>MOT test number</b>	531797030324
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**MOT #7** 2010-12-03 16:19**MOT test number** 890797430346**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #6** 2009-11-30 13:14**MOT test number** 412914439397**Result** ✓ Passed**MOT #5** 2009-11-30 13:14**MOT test number** 960044339336**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2008-12-10 09:11**MOT test number** 651175548310**Result** ✓ Passed**MOT #3** 2007-12-11 09:20**MOT test number** 402555547355**Result** ✓ Passed**MOT #2** 2006-12-12 09:26**MOT test number** 462036046357**Result** ✓ Passed



MOT #1	2005-12-14 10:15
MOT test number	421838645311
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
21 August 2023

X

MOT

Expired:  
5 August 2023

Tax status	Expired at 21 August 2023
Days left	253 days too late
MOT expiry date	5 August 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2001-12-28
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2001-12-28	12 mi
Registration #2	2005-12-14	32.284 mi
Registration #3	2006-12-12	37.917 mi
Registration #4	2007-12-11	45.476 mi
Registration #5	2008-12-10	55.832 mi
Registration #6	2009-11-30	65.926 mi
Registration #7	2010-12-03	75.019 mi
Registration #8	2011-03-16	77.463 mi
Registration #9	2012-03-05	78.283 mi
Registration #10	2013-02-22	78.978 mi
Registration #11	2014-02-26	79.695 mi
Registration #12	2014-02-26	79.698 mi
Registration #13	2015-02-24	80.554 mi
Registration #14	2015-03-06	80.554 mi
Registration #15	2015-03-06	80.554 mi
Registration #16	2015-03-06	80.554 mi
Registration #17	2015-03-06	80.554 mi
Registration #18	2015-03-06	80.554 mi
Registration #19	2015-03-06	80.554 mi
Registration #20	2015-03-06	80.554 mi
Registration #21	2015-03-06	80.554 mi
Registration #22	2015-03-06	80.554 mi
Registration #23	2015-03-06	80.554 mi
Registration #24	2015-03-06	80.554 mi
Registration #25	2015-03-06	80.554 mi
Registration #26	2015-03-06	80.554 mi

Registration #27	2023-05-20	20,000,000
Registration #28	2023-05-20	20,000,000

[More info >](#)



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1496 mm
Height	1580 mm
Length	3495 mm
Wheel base	2380 mm
Kerb weight	858 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4HC1501028