



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4
Colour	Red
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	410 Nm at 2.800 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	35.3 mpg
Consumption combined	30.7 mpg
CO2 emission	243 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-05-18
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-05-26
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	49
Total items failed	6

MOT #14	2022-05-27 13:43
MOT test number	718927029034
Result	✓ Passed
Next expiry date	2023-05-26



MOT #13

2021-08-26 15:28

MOT test number

750662888985

Result

✓ Passed

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive Spring mounting on axle corroded . (5.3.6 (a) (i))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated Leaking grease from small end . (6.1.7 (g) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Panhard rod mounting on rear axle is corroded . (5.3.6 (a) (i))

Advice Rear Passenger seat(s) missing at time of test Very rear row .

Advice Front Brake pipe corroded, covered in grease or other material Both sides pipes on brake calipers are corroded . (1.1.11 (c))

Advice Rear Fuel hose deteriorated Filler neck and breather pipes corroded . (6.1.3 (c) (ii))

Advice Lower Integral body structure is corroded but structural rigidity is not significantly reduced Underside generally corroded . (6.1.1 (c) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect Damp . (5.3.2 (b))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Corroded by body mounting behind front wheel . (6.2.2 (d) (i))

Advice Spare tyre defective

Advice Rear Brake pipe corroded, covered in grease or other material Both sides and unions into rear flexis are corroded . (1.1.11 (c))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect Misted . (5.3.2 (b))

**MOT #12**

2021-08-17 10:19

MOT test number

438695707876

Result**✗ Failed**

Fail Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced Inner sill corroded and holed . (7.1.1 (a) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material Brake pipe to flexi is corroded and very borderline . (1.1.11 (c))

Advice Rear Passenger seat(s) missing at time of test Very rear row .

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect Misted . (5.3.2 (b))

Advice Rear Brake pipe corroded, covered in grease or other material Both sides and unions into rear flexis are corroded . (1.1.11 (c))

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive Spring mounting on axle corroded . (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Panhard rod mounting on rear axle is corroded . (5.3.6 (a) (i))

Fail Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced Inner sill corroded and holed . (7.1.1 (a) (i))

Advice Front Brake pipe corroded, covered in grease or other material Both sides pipes on brake calipers are corroded . (1.1.11 (c))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated Leaking grease from small end . (6.1.7 (g) (i))

Advice Rear Fuel hose deteriorated Filler neck and breather pipes corroded . (6.1.3 (c) (ii))

Fail Offside Front Brake pipe excessively corroded Brake pipe to flexi . (1.1.11 (c))

Advice Spare tyre defective

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect Damp . (5.3.2 (b))

Advice Lower Integral body structure is corroded but structural rigidity is not significantly reduced Underside generally corroded . (6.1.1 (c) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Corroded by body mounting behind front wheel . (6.2.2 (d) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2019-06-18 15:18**MOT test number** 689004688450**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))**MOT #10** 2019-06-17 15:29**MOT test number** 615321158934**Result** ✗ Failed**Advice** Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9** 2018-03-29 09:29**MOT test number** 828460008778**Result** ✓ Passed**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2017-03-21 16:42**MOT test number** 825276117724**Result** ✓ Passed**Advice** Fuel neck corroded**Advice** All 4 tyres perished**MOT #7** 2016-03-17 14:37**MOT test number** 298758690253**Result** ✓ Passed**Advice** Offside Rear fog lamp held on by sticky tape**Advice** Offside front tyre tread has cut in it , both front tyre shoulders are perished**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 30% recorded , maximum limit is 30% (3.7.B.5b)**Advice** Both front wiper blades deteriorated**Advice** Trailer electrical socket damaged, but the lead can still be securely connected cover flap missing (1.9.3b)**MOT #6** 2015-03-02 13:18**MOT test number** 616921165085**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Offside rear fog lamp has been repaired with collected**MOT #5** 2014-03-05 10:19**MOT test number** 167614364499**Result** ✓ Passed**MOT #4** 2013-02-14 11:04**MOT test number** 508465743066**Result** ✓ Passed



MOT #3	2012-02-15 09:19
MOT test number	365856542026
Result	✓ Passed
MOT #2	2011-02-18 09:21
MOT test number	226029141043
Result	✓ Passed
MOT #1	2010-03-17 16:53
MOT test number	791746870030
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 May 2022

X

MOT

Expired:
26 May 2023

Tax status	Expired at 1 May 2022
Days left	730 days too late
MOT expiry date	26 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-22
Last registration	2022-05-27
Complete history	See info



Registration #1	2007-03-22	26 mi
Registration #2	2010-03-17	40.421 mi
Registration #3	2011-02-18	52.507 mi
Registration #4	2012-02-15	65.933 mi
Registration #5	2013-02-14	78.074 mi
Registration #6	2014-03-05	92.638 mi
Registration #7	2015-03-02	96.753 mi
Registration #8	2016-03-17	98.850 mi
Registration #9	2016-05-20	99.377 mi
Registration #10	2016-05-20	99.377 mi
Registration #11	2016-05-20	99.377 mi
Registration #12	2016-05-20	99.377 mi
Registration #13	2016-05-20	99.377 mi
Registration #14	2016-05-20	99.377 mi
Registration #15	2016-05-20	99.377 mi
Registration #16	2016-05-20	99.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4405 mm
Wheel base	2790 mm
Kerb weight	2180 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2

Engine number	1KD1561153
---------------	------------