



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA EXTREME DCI (120BHP)
Colour	Blue
Year of manufacture	2004
Top speed	123 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	270 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	152 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-06-10
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-23
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2022-02-25
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	34
Total items failed	19

MOT #22	2021-02-23 11:11
MOT test number	426783953098
Result	✓ Passed
Next expiry date	2022-02-25
Advice	Offside Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #21	2021-02-23 11:11
MOT test number	798007439289
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #20	2020-02-18 13:35
MOT test number	919748999117
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Steering linkage ball joint has slight play inner (2.1.3 (b) (i))
Advice	Nearside Front Steering linkage ball joint has slight play inner (2.1.3 (b) (i))

**MOT #19** 2019-02-26 15:45**MOT test number** 421887972798**Result** ✓ Passed**Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #18** 2018-03-27 13:41**MOT test number** 928625401715**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Ball joint has slight play inner tie rod (2.2.B.1f)**Advice** Nearside Front Ball joint has slight play inner tie rod (2.2.B.1f)**MOT #17** 2018-03-27 11:24**MOT test number** 665821868680**Result** ✗ Failed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Ball joint has slight play inner tie rod (2.2.B.1f)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front Ball joint has slight play inner tie rod (2.2.B.1f)

**MOT #16**

2017-03-24 12:35

**MOT test number**

830279169081

**Result**

✓ Passed

- Advice** Exhaust heat shield insecure
- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)
- Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Play in steering rack inner joint(s) both sides

**MOT #15**

2016-03-29 17:19

**MOT test number**

554019741824

**Result**

✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Rear wheel bearing has slight play both sides rear (2.6.2)
- Advice** Both sides steering rack joint plays slightly

**MOT #14**

2016-03-26 13:50

**MOT test number**

158277135227

**Result**

✗ Failed

- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Nearside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)
- Advice** Both sides steering rack joint plays slightly
- Advice** Rear wheel bearing has slight play both sides rear (2.6.2)
- Fail** Nearside Rear Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #13**

2015-03-31 16:49

**MOT test number**

906110495070

**Result**

✓ Passed

**MOT #12**

2015-03-30 11:57

**MOT test number**

725289185087

**Result**

✗ Failed

- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #11** 2014-03-25 10:33**MOT test number** 735214284006**Result** ✓ Passed**MOT #10** 2013-03-27 11:16**MOT test number** 218916083075**Result** ✓ Passed**Notice** Both rack arms slight play**MOT #9** 2012-03-26 11:33**MOT test number** 116266482079**Result** ✓ Passed**MOT #8** 2011-03-17 15:16**MOT test number** 908786271077**Result** ✓ Passed**MOT #7** 2011-03-17 15:16**MOT test number** 548786471017**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**MOT #6** 2010-03-23 09:50**MOT test number** 370152680073**Result** ✓ Passed**MOT #5** 2010-03-22 09:57**MOT test number** 413221580091**Result** ✗ Failed**Fail** Nearside Headlamp not working on main beam (1.7.5a)

**MOT #4** 2009-03-27 11:45**MOT test number** 810976689017**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)**MOT #3** 2009-03-26 10:26**MOT test number** 632855289064**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front coil spring cracked (2.4.C.1a)**Fail** Offside Front brake disc excessively pitted (3.5.1h)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front brake disc excessively pitted (3.5.1h)**Advice** Nearside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**MOT #2** 2008-03-29 12:54**MOT test number** 192309288086**Result** ✓ Passed**MOT #1** 2007-10-10 14:52**MOT test number** 853823787229**Result** ✓ Passed





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YH54KEK
Plate since	2019-03-29
Current registration	YH54KEK
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-10-13
Last registration	2021-02-23
Complete history	<a href="#">See info</a>



Registration #1	2004-10-13	8 mi
Registration #2	2007-10-10	111.112 mi
Registration #3	2008-03-29	120.951 mi
Registration #4	2009-03-26	122.545 mi
Registration #5	2009-03-27	122.546 mi
Registration #6	2010-03-22	123.471 mi
Registration #7	2010-03-23	123.471 mi
Registration #8	2011-03-17	124.474 mi
Registration #9	2012-03-26	131.223 mi
Registration #10	2013-03-27	137.454 mi
Registration #11	2014-03-25	141.821 mi
Registration #12	2015-03-30	148.613 mi
Registration #13	2016-03-29	155.404 mi
Registration #14	2017-03-28	162.195 mi
Registration #15	2018-03-27	168.986 mi
Registration #16	2019-03-26	175.777 mi
Registration #17	2020-03-25	182.568 mi
Registration #18	2021-03-24	189.359 mi
Registration #19	2022-03-23	196.150 mi
Registration #20	2023-03-22	202.941 mi
Registration #21	2024-03-21	209.732 mi
Registration #22	2025-03-20	216.523 mi
Registration #23	2026-03-19	223.314 mi
Registration #24	2027-03-18	230.105 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1562 mm
Length	4695 mm
Wheel base	2745 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	C411104