






## General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	2010
Top speed	113 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	115 BHP	0 < 101 A
Max. torque	165 Nm at 4.000 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	1.798 cc	121 - 140
Cylinders	4	141 - 165
Fuel type	Petrol	166 - 185
Consumption city	28.0 mpg	186 - 225
Consumption extra urban	46.3 mpg	225+
Consumption combined	37.2 mpg	
CO2 emission	179 g/km	
CO2 label	I	







### Internet history

Entry 1

Date

Pictures

2021-10-30

7

Listing price

View report



source: cargurus.co.uk



# MOT history

MOT expiry date	2025-04-17
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	58
Total items failed	18

MOT #23		2024-03-19 15:19
MOT test	number	272122901945
Result		✓ Passed
Next expi	ry date	2025-04-17
Advice	Rear subframe / suspension component corroded but not excessive	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #22 2024-03-19 09:51
<b>MOT test number</b> 560203097422
Result × Failed
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b> Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
FailNearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt(5.3.4 (b) (ii))
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
<b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice Rear subframe / suspension component corroded but not excessive
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b> Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #21		2023-04-18 11:31
MOT test	number	381609896330
Result		✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front cloth trapped in brake	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	





MOT #20	2023-04-18 09:21
MOT test number	838558091126
Result	🗙 Failed
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Front cloth trapped in brake	
<b>Fail</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #19	2022-04-14 08:11
MOT test number	773554720226
Result	✓ Passed

MOT #18	2022-04-14 08:11
MOT test number	779360812773
Result	× Failed
<b>Pass with rectification</b> (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

MOT #17	2020-10-21 12:58
MOT test number	854762284686
Result	✓ Passed

MOT #16	2020-03-19 13:13
MOT test	number 826318865197
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on 2mm and 0mm on edges (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm and 0mm on edges (5.2.3 (e))





MOT #15	2020-03-13 13:54
MOT test number	777371588946
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge on 2mm and 0mm	n on edges (5.2.3 (e))
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii	))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm and 0m	im on edges (5.2.3 (e))
Fail Offside Front Headlamp aim not tested (4.1.2 (b))	

MOT #14		2019-03-26 16:46
MOT test	number	394545639587
Result		✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		movement (5.3.4
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6	.1.7 (g) (i))
Advice	Rear slightly long parking brake travel	





MOT #13	2019-03-15 14:01
MOT test number	443059001484
Result	🗙 Failed
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive r (a) (i))	movement (5.3.4
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Fail         Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Rear slightly long parking brake travel	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1	7 (g) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2018-03-21 12:06
MOT test number	810458836254
Result	✓ Passed

MOT #11	2018-03-13 13:16
MOT test number	658185216176
Result	🗙 Failed
AdviceBrake hydraulic reservoir fluid close to minimum level (3.6.G.1b)FailOffside Rear Upper Brake pipe leaking to reservoir (3.6.A.1)	

MOT #10	2017-02-28 16:57
MOT test number	885446112447
Result	✓ Passed
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	





MOT #9	2017-02-28 14:19
MOT test number	178216527137
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	
<b>Fail</b> Nearside Rear Outer Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Advice Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	

MOT #8		2016-03-15 12:26
MOT test	number	859945221209
Result		✓ Passed
Advice	Nearside rear fog light lens damaged	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush outer (2.4.G.2)	

MOT #7	2016-03-07 14:54
MOT test number	558458465664
Result	🗙 Failed
Fail         Nearside Front Headlamp not working on dipped beam (1.7.5a)	
Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush outer (2.4.G.2)	
Advice Parking brake lever has little reserve travel (3.1.6b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside rear fog light lens damaged	



HV10EFT
report date: 2024-03-29

MOT #6		2015-03-19 11:38
MOT test	number	667088875072
Result		✓ Passed
Notice Notice	Engine covers fitted obscuring some components in the engine bay Under-trays fitted obscuring some underside components	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2015-03-17 15:31
MOT test number	475136375003
Result	🗙 Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
<b>Notice</b> Engine covers fitted obscuring some components in the engine bay	
<b>Fail</b> Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	
Fail         Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
<b>Notice</b> Under-trays fitted obscuring some underside components	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)	
Fail         Nearside Front Anti-lock braking system wiring excessively damaged (3.4.3)	

MOT #4	2014-01-29 07:49
MOT test number	137159624417
Result	✓ Passed





MOT #3		2013-12-05 09:36
MOT test	number	586439333363
Result		✓ Passed
Notice	Offside front screen washers too low	
Advice	Nearside Front Anti-lock braking system wiring damaged but not excessively (3.4	.3)

MOT #2		20	)13-12-05 09:36
MOT test	number		237589933362
Result			🗙 Failed
Pass wi	th rectification	Nearside Rear Direction indicator not working (1.4.A.2c)	
Notice	Offside front scr	een washers too low	
Advice	Nearside Front A	Anti-lock braking system wiring damaged but not excessively (3.4.3)	

MOT #1		2013-01-24 13:03
MOT test	number	565324323038
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 17 April 2025
Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	e cut of
Date	St Contraction
Category	AMP
Туре	

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2010-03-20
Last registration	2024-03-19
Complete history	See info



Registration #1	2010-03-20	22 mi
Registration #2	2013-01-24	36.832 mi
Registration #3	2013-12-05	49.897 mi
Registration #4	2014-01-29	50.309 mi
Registration #5	2015-03-17	59.229 mi
Registration #6	2015-03-19	59.229 mi
Registration #7	2016-03-07	65.428 mi
Registration #8	2016-03-15	65.551 mi
Registration #9	2017-02-28	68.533 mi
Registration #10	2017-02-28	68.533 mi
Registration #11	2018-03-13	72.936 mi
Registration #12	2018-03-21	73.021 mi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		
Registration #15 Registration #16		0.177 es
		0.107 es
Registration #16		0.107 es
Registration #16 Registration #17		0.107 es 0.107 es 0.107 es 0.107 es
Registration #16 Registration #17 Registration #18		0.107 es 0.107 es 0.107 es 0.107 es 0.107 es
Registration #16 Registration #17 Registration #18 Registration #19		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		0.107 46 0.107 46 0.107 46 0.107 46 0.107 46 0.107 46 0.107 46
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		0.107 46 0.107 46 0.107 46 0.107 46 0.107 46 0.107 46 0.107 46 0.107 46
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		10.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46

More info >



HV10EFT report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5