



KYI2FHP

report date: 2024-03-29

General information

Make	MAZDA
Model	5 TAKUYA
Colour	Silver
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	193 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-01
Pictures	36
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2023-08-29 14:59
MOT test number	979069287355
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #13	2022-08-31 11:22
MOT test number	458764463759
Result	✓ Passed
Advice	Sill cover panels fitted preventing full inspection of some testable components
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Engine cover and under cover panels fitted obscuring some testable components

MOT #12	2022-08-11 11:44
MOT test number	348039008357
Result	✗ Failed
MAJOR	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Under cover fitted obscuring some testable components
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #11	2021-08-10 08:15
MOT test number	128169169236
Result	✓ Passed
Advice	Engine cover & under cover panels fitted obscuring some testable components.
Advice	Sill cover panels fitted preventing full inspection of some testable components.

**MOT #10** 2021-08-02 11:14**MOT test number** 384882094352**Result** ✗ Failed**MAJOR** Rear Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Sill cover panels fitted preventing full inspection of some testable components.**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Engine cover & under cover panels fitted obscuring some testable components.**MOT #9** 2020-12-10 15:35**MOT test number** 529655193634**Result** ✓ Passed**MOT #8** 2019-12-20 09:53**MOT test number** 327891454300**Result** ✓ Passed**MOT #7** 2019-12-16 12:43**MOT test number** 856944022150**Result** ✓ Passed**MOT #6** 2019-05-28 08:39**MOT test number** 421953734918**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-06-08 11:44**MOT test number** 236339403142**Result** ✓ Passed**MOT #4** 2018-05-29 09:11**MOT test number** 738563267788**Result** ✗ Failed**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Tyre pressure monitoring system inoperative (5.2.3 (h) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #3** 2017-05-15 09:24**MOT test number** 264907232937**Result** ✓ Passed**Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**Advice** Undertrays and engine covers fitted**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear parking (secondary) brake grabbing slightly (3.7.B.6b)**Advice** E.m.l on**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** N/s and o/s front tyres scrubbed



MOT #2	2016-03-08 11:30
MOT test number	712795525814
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)

MOT #1	2015-03-06 09:47
MOT test number	488975965063
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Items removed from driver's view prior to test
Notice	Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	KY12 FHP
Plate since	2019-03-29
Current registration	KY12 FHP
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-01
Last registration	2023-08-29
Complete history	See info



Registration #1	2012-03-01	20 mi
Registration #2	2015-03-06	16.875 mi
Registration #3	2016-03-08	24.021 mi
Registration #4	2017-05-15	34.950 mi
Registration #5	2018-05-29	46.720 mi
Registration #6	2018-06-08	46.776 mi
Registration #7	2019-05-28	56.789 mi
Registration #8	2019-12-16	60.087 mi
Registration #9	2020-05-29	65.277 mi
Registration #10	2020-05-29	65.277 mi
Registration #11	2020-05-29	65.277 mi
Registration #12	2020-05-29	65.277 mi
Registration #13	2020-05-29	65.277 mi
Registration #14	2020-05-29	65.277 mi
Registration #15	2020-05-29	65.277 mi
Registration #16	2020-05-29	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1435 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20409679