



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY GHIA TDDI
Colour	Silver
Year of manufacture	2005
Top speed	117 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-08-08
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-17
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	129
Total items failed	20

MOT #24	2023-07-18 17:47
---------	------------------

MOT test number	917861724904
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-17
------------------	------------

- Advice** Offside Front Inner support beam sign of repair covered with black substance
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Both rear arches corroded
- Advice** Both sides rear outer sills sign of corrosion
- Advice** Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. both sides (1.4.2 (a) (i))
- Advice** General underbody and all the components are corroded
- Advice** Vehicle tested in wet condition
- Advice** Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. both sides (1.2.2 (a) (i))
- Minor** Nearside Rear Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))
- Advice** Both sides front outer & inner sills sign of repair (welding) covered with grey and black substance

**MOT #23**

2023-05-12 10:23

**MOT test number**

152146935644

**Result**

✗ Failed

**Advice** Nearside Front Outer Vehicle structure fractured not seriously affecting its strength with 30cm of a towbar mounting sill (6.1.6 (i) (i))

**Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**Minor** Front Suspension component ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

**Advice** Rear end corroded

**Fail** Offside Rear Position lamp lens seriously defective (4.2.1 (b))

**Fail** Rear Shock absorbers has a serious fluid leak both (5.3.2 (b))

**MOT #22**

2021-08-13 15:41

**MOT test number**

887992601598

**Result**

✓ Passed

**MOT #21**

2020-09-29 10:47

**MOT test number**

323105315636

**Result**

✓ Passed

**Advice** Front Subframe mounting prescribed area is corroded but not considered excessive both chassis rails (5.3.6 (a) (i))

**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bushes slightly deteriorated (5.3.4 (a) (i))

**Advice** Rear Coil spring corroded both sides slightly at top (5.3.1 (b) (i))

**Minor** Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))

**Advice** Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced inner and outer side sills (6.1.1 (c) (i))

**MOT #20**

2020-09-22 16:53

**MOT test number**

133432084466

**Result****✗ Failed**

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**Advice** Front Subframe mounting prescribed area is corroded but not considered excessive both chassis rails (5.3.6 (a) (i))

**Advice** Rear Coil spring corroded both sides slightly at top (5.3.1 (b) (i))

**Fail** Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced inner and outer side sills (6.1.1 (c) (i))

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bushes slightly deteriorated (5.3.4 (a) (i))

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Minor** Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced inner and outer side sills (6.1.1 (c) (i))

**MOT #19**

2019-09-14 10:45

**MOT test number**

883167955552

**Result****✓ Passed**

**Advice** Rear Coil spring corroded both sides slightly (5.3.1 (b) (i))

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bushes slightly deteriorated (5.3.4 (a) (i))

**Advice** Rear shock absorber casings slightly corroded

**Minor** Front Anti-roll bar linkage ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**Minor** Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both sides slightly cracked/perished (2.1.3 (g) (i))

**Advice** Nearside Front Coil spring corroded slightly (5.3.1 (b) (i))

**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced including places on side sills and front out riggers (6.1.1 (c) (i))

**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

**MOT #18**

2018-09-15 10:33

**MOT test number**

640314097505

**Result**

✓ Passed

- Advice** Offside rear parking brake effort reduced
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated small split (5.3.4 (b) (i))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Coil spring corroded both rear and nearside front slightly (5.3.1 (b) (i))
- Advice** Offside Play in steering rack inner joint(s) slight
- Minor** Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both sides slightly deteriorated (2.1.3 (g) (i))
- Advice** Both rear shock absorbers slightly corroded
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both sides, nearside seeping grease slightly (5.3.4 (b) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides, rear bushes slightly (5.3.4 (a) (i))

**MOT #17**

2017-09-20 11:03

**MOT test number**

931102000747

**Result**

✓ Passed

- Advice** Steering rack gaiter deteriorated both sides (2.2.D.2d)
- Advice** Coil spring corroded offside rear and nearside front slightly (2.4.C.1b)
- Advice** Oil leak
- Advice** Rear Shock absorber has slight corrosion to the casing both sides (2.7.2a)
- Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides slightly (2.4.G.2)

**MOT #16**

2017-09-09 11:33

**MOT test number**

906632795670

**Result****✗ Failed**

- Advice** Oil leak
- Fail** Emissions not tested due to exhaust (7.3.A.1)
- Fail** Exhaust system not adequately supported (7.1.1)
- Advice** Rear Shock absorber has slight corrosion to the casing both sides (2.7.2a)
- Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides slightly (2.4.G.2)
- Advice** Steering rack gaiter deteriorated both sides (2.2.D.2d)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)
- Advice** Coil spring corroded offside rear and nearside front slightly (2.4.C.1b)

**MOT #15**

2016-09-15 09:42

**MOT test number**

388503357891

**Result****✓ Passed**

- Advice** Exhaust system slightly corroded
- Advice** Turbo boost pipe adrift
- Advice** Steering rack gaiter deteriorated both sides slightly cracked/perished (2.2.D.2d)
- Advice** Nearside rear wheel bearing slightly noisy when rotated
- Advice** Oil leak
- Advice** Play in steering rack inner joint(s)



**MOT #14**

2015-09-28 09:51

**MOT test number**

275453478670

**Result**

✓ Passed

**Advice** Offside rear tyre 3mm in places - nearside rear tyre wearing on inner edge**Advice** Rear brake discs heavily corroded**Advice** Oil leak**Advice** Slight play in inner track rod joints**Advice** Front brake discs corroded**Advice** Brake pad warning light on**MOT #13**

2015-09-18 16:24

**MOT test number**

226174161024

**Result**

✗ Failed

**Advice** Rear brake discs heavily corroded**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Oil leak**Advice** Slight play in inner track rod joints**Advice** Front brake discs corroded**Fail** Offside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Brake pad warning light on**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**Advice** Offside rear tyre 3mm in places - nearside rear tyre wearing on inner edge



MOT #12

2014-09-26 15:51

MOT test number

525639464255

Result

✓ Passed

- Advice

Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice

Nearside rear tyre wearing edges slightly
- Advice

Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Notice

Front wipers poor
- Advice

Body has slight corrosion (6.1.B.2)
- Notice

Passenger seat(s) missing at time of test
- Notice

Front and rear brake discs corroded
- Advice

Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice

Steering rack gaiter deteriorated (2.2.D.2d)
- Notice

Oil leak
- Notice

Exhaust slightly deteriorated

**MOT #11**

2014-09-19 15:05

**MOT test number**

447442364251

**Result****✗ Failed****Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Body has slight corrosion (6.1.B.2)**Fail** Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Oil leak**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Exhaust slightly deteriorated**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Notice** Both rear tyres wearing on inner edges - offside worn smooth almost to cords**Advice** Steering rack gaiter deteriorated (2.2.D.2d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Front wipers poor**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Passenger seat(s) missing at time of test**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Front and rear brake discs corroded**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #10**

2013-09-30 12:55

**MOT test number**

399893373260

**Result**

✓ Passed

**Notice** O/s/f spot light broken**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2013-09-30 11:57

**MOT test number**

809613273221

**Result**

✗ Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s/f spot light broken**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8**

2012-09-28 09:50

**MOT test number**

119312172241

**Result**

✓ Passed

**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Osf spot light damaged**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #7 2011-09-28 09:19

MOT test number 115941771293

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/f inner drive shaft boot split
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2011-09-28 09:19

MOT test number 238721271252

Result ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** N/s/f inner drive shaft boot split
- Pass with rectification** Offside Inner Rear position lamp(s) not working (1.1.A.3b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2010-09-29 09:04

MOT test number 902842070226

Result ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** F discs worn

**MOT #4** 2009-09-30 15:41**MOT test number** 792513379204**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake discs lipped**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-01-19 15:56**MOT test number** 253129519069**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #2** 2009-01-19 14:30**MOT test number** 912779819050**Result** ✗ Failed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Nearside Front Headlamp aim too low (1.8)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Offside Front Headlamp aim too low (1.8)**MOT #1** 2008-01-19 08:59**MOT test number** 134469018462**Result** ✓ Passed**Notice** Advise front pads worn



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
17 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	17 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EF54ZTX</b>
Plate since	2019-03-28
Current registration	<b>EF54ZTX</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-01-21
Last registration	2023-07-18
Complete history	<a href="#">See info</a>



Registration #1	2005-01-21	8 mi
Registration #2	2008-01-19	42.567 mi
Registration #3	2009-01-19	52.046 mi
Registration #4	2009-01-19	52.046 mi
Registration #5	2009-09-30	59.341 mi
Registration #6	2010-09-29	68.395 mi
Registration #7	2011-09-28	75.809 mi
Registration #8	2012-09-28	85.661 mi
Registration #9	2013-09-30	91.552 mi
Registration #10	2013-09-30	91.560 mi
Registration #11	2014-09-19	100.199 mi
Registration #12	2014-09-26	100.267 mi
Registration #13	2015-09-18	107.639 mi
Registration #14	2016-09-18	115.000 mi
Registration #15	2017-09-18	122.361 mi
Registration #16	2018-09-18	129.722 mi
Registration #17	2019-09-18	137.083 mi
Registration #18	2020-09-18	144.444 mi
Registration #19	2021-09-18	151.805 mi
Registration #20	2022-09-18	159.166 mi
Registration #21	2023-07-18	166.527 mi
Registration #22	2023-07-18	166.527 mi
Registration #23	2023-07-18	166.527 mi
Registration #24	2023-07-18	166.527 mi
Registration #25	2023-07-18	166.527 mi



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4641 mm
Wheel base	2835 mm
Kerb weight	1694 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	5A18422