



report date: 2024-03-28

General information

Make	SUZUKI
Model	GRAND VITARA 16V
Colour	Black
Year of manufacture	-
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	174 Nm at 4.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	36.2 mpg
Consumption combined	23.5 mpg



LABEL UNKNOWN



## MOT history

MOT #19	2020-09-28 08:52
MOT test number	341892570575
Result	✓ Passed
Next expiry date	2021-10-10
Advice	Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #18	2019-04-04 12:00
MOT test number	354725090399
Result	✓ Passed

MOT #17	2018-04-04 09:42
MOT test number	313133086987
Result	✓ Passed

MOT #16	2018-04-04 09:42
MOT test number	135197116879
Result	✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #15	2017-04-05 12:54
MOT test number	750988979860
Result	✓ Passed

MOT #14	2017-04-04 12:05
MOT test number	462482794857
Result	✗ Failed
Fail	Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #13** 2016-03-31 13:09**MOT test number** 985264110604**Result** ✓ Passed**MOT #12** 2015-04-11 10:01**MOT test number** 677431405179**Result** ✓ Passed**Notice** Nearside rear tyre wearing outer edges**MOT #11** 2015-04-04 12:31**MOT test number** 169464995012**Result** ✗ Failed**Notice** Nearside rear tyre wearing outer edges**Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #10** 2014-04-03 10:35**MOT test number** 345583694061**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #9** 2013-04-06 14:41**MOT test number** 576536593094**Result** ✓ Passed

**MOT #8** 2012-04-03 16:25**MOT test number** 959524192082**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2011-03-26 11:06**MOT test number** 169945081067**Result** ✓ Passed**MOT #6** 2010-03-27 09:23**MOT test number** 604766380046**Result** ✓ Passed**MOT #5** 2009-04-03 14:59**MOT test number** 132463299007**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2008-04-01 13:48**MOT test number** 274792598036**Result** ✓ Passed**MOT #3** 2008-04-01 11:12**MOT test number** 130192298056**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2007-04-04 09:43
MOT test number	654204597037
Result	✓ Passed

MOT #1	2006-04-05 12:36
MOT test number	674855496088
Result	✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>MA03GUJ</b>
Plate since	2019-03-28
Current registration	<b>MA03GUJ</b>
Plate since	2019-03-28

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-04-05
Last registration	2020-09-28
Complete history	<a href="#">See info</a>



Registration #1	2003-04-05	19 mi
Registration #2	2006-04-05	28.199 mi
Registration #3	2007-04-04	35.082 mi
Registration #4	2008-04-01	40.303 mi
Registration #5	2008-04-01	40.303 mi
Registration #6	2009-04-03	44.900 mi
Registration #7	2010-03-27	49.666 mi
Registration #8	2011-03-26	54.582 mi
Registration #9	2012-04-03	59.720 mi
Registration #10	2013-04-06	61.624 mi
Registration #11	2014-04-06	61.624 mi
Registration #12	2015-04-06	61.624 mi
Registration #13	2016-04-06	61.624 mi
Registration #14	2017-04-06	61.624 mi
Registration #15	2018-04-06	61.624 mi
Registration #16	2019-04-06	61.624 mi
Registration #17	2020-09-28	61.624 mi
Registration #18	2020-09-28	61.624 mi
Registration #19	2020-09-28	61.624 mi
Registration #20	2020-09-28	61.624 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1780 mm
Height	1740 mm
Length	4195 mm
Wheel base	2480 mm
Kerb weight	1355 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	J20A-198770