



DU52AXG

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BORA GT TDI (150BHP)
Colour	Blue
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	234 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	6
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #20** 2022-02-09 15:26**MOT test number** 530689569393**Result** ✓ Passed**Next expiry date** 2023-02-18**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Play in steering rack inner joint(s)**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19** 2022-01-31 15:49**MOT test number** 681494574521**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Play in steering rack inner joint(s)**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18** 2021-02-19 17:11**MOT test number** 647044635654**Result** ✓ Passed

**MOT #17**

2020-01-14 13:42

**MOT test number**

355947969285

**Result**

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Shock absorbers has slight external damage to the casing both (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension component corroded but not seriously weakened trailing arm (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material and o/s/r (1.1.11 (c))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Corrosion on fuel tank support straps
- Advice** Offside Rear Suspension component corroded but not seriously weakened trailing arm (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #16 2019-01-10 14:55

MOT test number 202500753183

Result ✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Shock absorbers have slight corrosion to the casing
- Advice** Nearside Rear Suspension component corroded but not seriously weakened Trailing arm (5.3.3 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component corroded but not seriously weakened Trailing arm (5.3.3 (b) (i))

**MOT #15**

2018-01-27 10:24

**MOT test number**

793316783436

**Result**

✓ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Trailing arm corroded but not seriously weakened (2.4.G.1)
- Advice** Rear Shock absorber has slight corrosion to the casing both (2.7.2a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Trailing arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)

**MOT #14**

2017-01-22 08:48

**MOT test number**

427156293900

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Shock absorber has slight external damage to the casing (2.7.2a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)

**MOT #13** 2016-01-07 16:54**MOT test number** 728111785132**Result** ✓ Passed**Advice** Nearside Rear Inner Brake pipe slightly corroded (3.6.B.2c)**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Inner edge worn smooth on offside rear tyre**MOT #12** 2014-12-11 15:12**MOT test number** 915125544314**Result** ✓ Passed**Advice** Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Inner Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Corrosion to rear axle**MOT #11** 2014-01-10 12:31**MOT test number** 575430614081**Result** ✓ Passed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Inner Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #10**

2013-01-07 15:52

**MOT test number**

128057103430

**Result**

✓ Passed

- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Tread slightly cracked on rear tyres
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9**

2013-01-07 15:52

**MOT test number**

529267803095

**Result**

✗ Failed

- Notice** Tread slightly cracked on rear tyres
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Pass with rectification** Rear fog lamp not working (1.3.2b)

**MOT #8**

2012-01-04 10:03

**MOT test number**

645184902012

**Result**

✓ Passed

- Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Notice** N/s/f outer driveshaft gaitor not fully secure on small clip.
- Advice** Offside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)



**MOT #7** 2011-01-10 09:49**MOT test number** 676840211047**Result** ✓ Passed**Notice** Front and rear brake disks seriously pitted**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #6** 2010-01-06 12:22**MOT test number** 174826400079**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2009-01-08 16:32**MOT test number** 974408509079**Result** ✓ Passed**Notice** Slight play in steering collum top bush**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight play in nearside steering rack

**MOT #4** 2009-01-08 11:53**MOT test number** 154378009474**Result** ✗ Failed**Notice** Slight play in steering collum top bush**Fail** Offside Front Front constant velocity joint gaiter split (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)**Notice** Slight play in nearside steering rack**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-01-10 16:22**MOT test number** 164290418436**Result** ✓ Passed**MOT #2** 2007-01-11 16:07**MOT test number** 533371217062**Result** ✓ Passed**MOT #1** 2006-01-11 11:52**MOT test number** 593361216095**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>DU52AXG</b>
Plate since	2019-03-29
Current registration	 <b>DU52AXG</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-01-10
Last registration	2022-02-09
Complete history	<a href="#">See info</a>



Registration #1	2003-01-10	13 mi
Registration #2	2006-01-11	23.870 mi
Registration #3	2007-01-11	32.264 mi
Registration #4	2008-01-10	39.749 mi
Registration #5	2009-01-08	46.310 mi
Registration #6	2009-01-08	46.310 mi
Registration #7	2010-01-06	53.345 mi
Registration #8	2011-01-10	60.093 mi
Registration #9	2012-01-04	65.834 mi
Registration #10	2013-01-07	70.815 mi
Registration #11	2014-01-10	78.426 mi
Registration #12	2015-01-10	78.426 mi
Registration #13	2016-01-10	78.426 mi
Registration #14	2017-01-10	78.426 mi
Registration #15	2018-01-10	78.426 mi
Registration #16	2019-01-10	78.426 mi
Registration #17	2020-01-10	78.426 mi
Registration #18	2021-01-10	78.426 mi
Registration #19	2022-01-10	78.426 mi
Registration #20	2023-01-10	78.426 mi
Registration #21	2024-01-10	78.426 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1439 mm
Length	4149 mm
Wheel base	2511 mm
Kerb weight	1389 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2



**Engine number**

ARL 073617