





report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D3 DRIVE ES
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2021-08-29
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	9
Total items failed	6

MOT #10	2020-08-27 19:54
MOT test number	878180086631
Result	✓ Passed
Next expiry date	2021-08-29

MOT #9	2019-08-30 09:26
MOT test number	528228024629
Result	✓ Passed
Minor Offside Front Obligatory mirror slightly damaged lens satisfactory, but casing damaged (3.3 (b) (i))	
Advice Boot lid component damaged but not likely to cause injury of closes securely (6.2.1 (a) (i))	difficult to open and close, however

MOT #8	2019-08-30 09:15
MOT test number	399271516483
Result	X Failed
Fail Nearside Rear Tyre(s) of different sizes are fitted on the same axle. dange Advice Boot lid component damaged but not likely to cause injury difficult to o closes securely (6.2.1 (a) (i))	

MOT #7	2018-08-24 09:17
MOT test number	486576659990
Result	✓ Passed

CarCheck.co.uk page 2/10



DA12CCU

report date: 2024-03-29

MOT #6 2017-08-28 10:24

MOT test number 119740111759

MOT #5 2017-08-25 09:53

MOT test number 863689036140

Result X Failed

Fail Nearside Front Outer Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #4 2016-08-05 08:43

MOT test number 762012058195

Result \rightarrow Passed

Advice Nearside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2016-08-04 11:58

MOT test number 791783587087

Result × Failed

Advice Nearside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Front Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)

Advice Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2015-07-21 09:33

MOT test number 195352505243

Result \rightarrow Passed

Notice Nail in nearside rear tyre

CarCheck.co.uk page 3/10



MOT test number
926902605227

Result

Pass with rectification
Offside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification
Nearside Headlamp not working on dipped beam (1.7.5a)

Notice
Nail in nearside rear tyre


CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



DA12CCU

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

Plate changes	More info >
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	UK MEZ MEZ
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-08-21
Last registration	2020-08-27
Complete history	See info



Registration #1	2012-08-21	17 mi
Registration #2	2015-07-21	27.468 mi
Registration #3	2016-08-04	49.142 mi
Registration #4	2016-08-05	49.148 mi
Registration #5	2017-08-25	75.482 mi
Registration #6		11.777 es
B		
Registration #7		11.777 46
Registration #8		1.77 4
-		1.77 m

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1756 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	.0/10

Number of axles 2
Engine number 1161516