





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	AMICA GSI
Colour	Black
Year of manufacture	-
Top speed	91 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg



CarCheck.co.uk page 1/14



# Internet history

_		4		7
ᆮ	n	Т	rν	1

Lifety 1	
Date	2021-09-05
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



**MOT** history

**MOT #19** 2022-09-02 11:12

MOT test number 397626441567

**Result** ✓ Passed

Next expiry date 2023-09-02

**Advice** Suspension arm corroded but not seriously weakened n/s/f & o/s/f (5.3.3 (b) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18 2022-09-01 12:40

**MOT test number** 427970265129

Result X Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Steering locking device missing track rod end (split pin) (2.1.3 (d))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Fail** Front Service brake excessively fluctuating (1.2.1 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Front Anti-lock braking system component excessively damaged abs sensor ring split (1.6 (e))

**Advice** Suspension arm corroded but not seriously weakened n/s/f & o/s/f (5.3.3 (b) (i))

CarCheck.co.uk page 3/14



**DS57YYM** 

report date: 2024-03-28

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Oil leak, but not excessive sump corroded (8.4.1 (a) (i))

MOT #16

MOT test number

Result

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Front Brake pipe corroded, covered in grease or other material to flex (1.1.11 (c))

MOT test number
620951118106

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material to flex (1.1.11 (c))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14

MOT test number

Result

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

CarCheck.co.uk page 4/14



**MOT #13** 2019-02-01 13:22

**MOT test number** 271517320222

Result X Failed

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Exhaust system insecure (6.1.2 (a))

Fail Emissions not tested ref:- exhaust leak (8.2.1.2 (d))

**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Fail** Exhaust has a major leak of exhaust gases front pipe (6.1.2 (a))

**MOT #12** 2018-02-17 12:17

**MOT test number** 968350378274

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #11** 2018-02-17 12:17

**MOT test number** 263335989437

**Result** X Failed

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)

**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

**MOT #10** 2017-02-20 15:41

**MOT test number** 461916745070

**Result** 
✓ Passed

CarCheck.co.uk page 5/14



**DS57YYM** 

report date: 2024-03-28

MOT test number

Result

Fail Offside Front front brake binding (3.7.B.1)

Advice Front brake discs corroded

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #8** 2016-10-27 09:47 **MOT** test number 229057037852 Result ✓ Passed **MOT #7** 2015-11-02 14:45 290739683315 **MOT** test number Result ✓ Passed **Advice** Centre stop light disconnected **Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Offside Rear brake binding slightly Advice Rear exhaust bracket insecure Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice

MOT #6		2014-10-22 15:12
MOT test	number	519055494297
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Rear exhaust bracket insecure	

CarCheck.co.uk page 6/14



**DS57YYM** 

report date: 2024-03-28

MOT #5 2013-10-22 09:54 **MOT test number** 467445893208 Result ✓ Passed **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Notice Rattle on rear exhaust box Notice N/s/f tyre wearing on inner edge Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Both front brakes binding slightly Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4	2013-10-21 13:39
MOT test number	635374393278
Result	<b>×</b> Failed
Notice N/s/f tyre wearing on inner edge	
Fail Offside Rear position lamp(s) adversely affected by the operation of another lamp	(1.1.A.3f)
Fail Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice Both front brakes binding slightly	
Fail Nearside Rear position lamp(s) adversely affected by the operation of another lam	p (1.1.A.3f)
Fail Nearside Stop lamp adversely affected by the operation of another lamp (1.2.1f)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Rattle on rear exhaust box	

CarCheck.co.uk page 7/14



MOT #3 2012-10-24 12:08 **MOT test number** 375918592267 ✓ Passed Result MOT #2 2012-01-27 13:50 **MOT test number** 437847122017 Result ✓ Passed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Front blades smear screen advise new blades

MOT #1	2011-01-24 17:01
MOT test number	799944521006
Result	✓ Passed

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-02-01
Last registration	2022-09-02
Complete history	See info



Registration #1	2008-02-01	12 mi
Registration #2	2011-01-24	33.907 mi
Registration #3	2012-01-27	44.437 mi
Registration #4	2012-10-24	51.316 mi
Registration #5	2013-10-21	54.265 mi
Registration #6	2013-10-22	54.265 mi
Registration #7	2014-10-22	57.880 mi
Registration #8	2015-11-02	61.727 mi
Registration #9	2016-10-27	64.752 mi
Registration #10	2017-02-20	65.512 mi
Registration #11	2017-02-20	65.512 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.117 au
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		10.777 es

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

# Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	1007 kg
Max. allowed weight	1336 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	G4HG7M300131

CarCheck.co.uk page 14/14