



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | VOLVO |
| Model | S40 D4 R-DESIGN |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 134 mph |
| 0 - 60 mph | 8.2 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 177 BHP |
| Max. torque | 400 Nm at 1.750 rpm |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 48.7 mpg |



LABEL UNKNOWN



MOT history

| | |
|------------------|--|
| MOT #11 | 2020-08-06 16:07 |
| MOT test number | 696991357362 |
| Result | ✓ Passed |
| Next expiry date | 2021-08-05 |
| Advice | Front brake pads & discs appear too small for vehicle |
| Minor | Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |

| | |
|-----------------|---|
| MOT #10 | 2020-07-24 12:25 |
| MOT test number | 619381143323 |
| Result | ✗ Failed |
| Fail | Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm, worn on inner edge has damage to outer sidewall (5.2.3 (e)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Fail | Offside Rear Direction indicator incorrect colour (4.4.3 (a)) |
| Minor | Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |
| Fail | Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii)) |
| Fail | Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b)) |
| Advice | Front brake pads & discs appear too small for vehicle |
| Fail | Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure Outer sidewall (5.2.3 (d) (ii)) |
| Fail | Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) |
| Fail | Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Split (6.1.7 (g) (ii)) |
| Minor | Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i)) |
| Fail | Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords In tread (5.2.3 (d) (i)) |

**MOT #9** 2019-04-27 13:38**MOT test number** 880617164364**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement o/s n/s (5.3.4 (a) (i))**MOT #8** 2018-02-15 14:22**MOT test number** 720157232964**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** High level stop lamp inoperative**MOT #7** 2018-02-15 09:21**MOT test number** 321830968608**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** High level stop lamp inoperative**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2017-02-11 10:43**MOT test number** 220300344730**Result** ✓ Passed

**MOT #5** 2017-01-28 10:29**MOT test number** 190895402459**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Engine covers fitted**Fail** Offside Headlamp aim too high (1.8)**Advice** Coolant on minimum**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Undertrays fitted**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Front brake excessively fluctuating (3.7.B.3)**MOT #4** 2016-02-11 15:35**MOT test number** 550976253336**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-02-20 11:46**MOT test number** 129261055034**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #2 | 2014-01-24 09:34 |
| MOT test number | 986894324043 |
| Result | ✓ Passed |

| | |
|-------------------------|---|
| MOT #1 | 2014-01-24 09:34 |
| MOT test number | 156964024401 |
| Result | ✗ Failed |
| Pass with rectification | Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Pass with rectification | Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------|
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2010-10-11 |
| Last registration | 2020-08-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-10-11 | 21 mi |
| Registration #2 | 2014-01-24 | 37.865 mi |
| Registration #3 | 2015-02-20 | 52.800 mi |
| Registration #4 | 2016-02-11 | 67.551 mi |
| Registration #5 | 2017-01-28 | 87.915 mi |
| Registration #6 | 2017-02-11 | 88.169 mi |
| Registration #7 | 2019-05-20 | 95.277 mi |
| Registration #8 | 2019-05-20 | 95.277 mi |
| Registration #9 | 2019-05-20 | 95.277 mi |
| Registration #10 | 2019-05-20 | 95.277 mi |
| Registration #11 | 2019-05-20 | 95.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4266 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1469 kg |
| Max. allowed weight | 1900 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|---------------|--------|
| Engine number | 862339 |
|---------------|--------|