





General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Blue
Year of manufacture	2005
Top speed	100 mph
0 - 60 mph	14.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

E	ntrv	2

Date Pictures 2021-07-03

20

Listing price

View report









source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

25 View report

2021-07-02

ocs



source: autotrader.co.uk









MOT history

MOT expiry date	2024-01-17
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	48
Total items failed	42

МОТ #26	2024-01-11 09:51
MOT test number	570658130674
Result	🗙 Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))	
(i)) Offside Registration plate lamp inoperative in the case of multiple lamps or light	: sources (4.7.1 (b)
Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e)))
Fail Nearside Parking brake inoperative on one side (1.4.1 (a))	
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no lo ingress of dirt (6.1.7 (g) (ii))	onger prevents the
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	



MOT test number 893998228705 Result Passed Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside, mid outer sills (6.1.1 (c) (i)) MOT #24 2023-01-16 12:02 MOT test number 717837262559 Result X Failed Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Oil leak, but not excessive (8.4.1 (a) (i))
Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside, mid outer sills (6.1.1 (c) (i)) MOT #24 2023-01-16 12:02 MOT test number 717837262559 Result × Failed Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside, mid outer sills (6.1.1 (c) (i)) MOT #24 2023-01-16 12:02 MOT test number 717837262559 Result × Failed Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside, mid outer sills (6.1.1 (c) (i)) MOT #24 2023-01-16 12:02 MOT test number 717837262559 Result × Failed Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
offside, mid outer sills (6.1.1 (c) (i)) MOT #24 2023-01-16 12:02 MOT test number 717837262559 Result Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
MOT test number 717837262559 Result X Failed Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Result X Failed Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice Oil leak, but not excessive (8.4.1 (a) (i))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail (ii))Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b)
Advice Integral body structure is corroded but structural rigidity is not significantly reduced nearside and offside, mid outer sills (6.1.1 (c) (i))
Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #23	2022-01-11 16:07
MOT test number	608606914785
Result	✓ Passed

EX05VLL

report date: 2024-03-29



MOT #2	22	2022-01-05 15:47
MOT te	st number	395913616971
Result		🗙 Failed
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b)	o) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))	
Fail	Stop lamp(s) all not working (4.3.1 (a) (iii))	

MOT #21	2021-01-18 12:42
MOT test number	709490029442
Result	✓ Passed

EX05VLL

report date: 2024-03-29



EX05VLL report date: 2024-03-29

MOT #20	2021-01-05 15:04
MOT test number	666737061130
Result	🗙 Failed
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no lor ingress of dirt (6.1.7 (g) (ii))	nger prevents the
Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Nearside Rear Registration plate lamp does not illuminate simultaneously with (4.7.2 (a))	h the position lamps
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no long of dirt (6.1.7 (g) (ii))	er prevents the ingress

MOT #19	2019-05-14 15:23
MOT test	number 691396680473
Result	✓ Passed
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
Advice	Nearside Rear Nail in tyre leaking
Advice (e))	Offside Rear Tyre worn close to legal limit/worn on edge showing 2.6mm - 195/60 r14 86h (5.2.3
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))





MOT #18	2019-05-08 16:15
MOT test number	964484470716
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge showing 2.6mm - 195/6 (e))	50 r14 86h (5.2.3
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light	וt sources (4.7.1
Fail Nearside Front Position lamp not working (4.2.1 (a))	
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no lo ingress of dirt split (6.1.7 (g) (ii))	nger prevents the
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated	(6.1.7 (g) (i))
Advice Nearside Rear Nail in tyre leaking	
Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	

MOT #17		2018-06-07 14:01
MOT test	number	643369272624
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2018-06-07 13:15
MOT test number	308769945889
Result	🗙 Failed
Fail Nearside Front Position lamp not working (4.2.1 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))	





MOT #15	2017-06-05 11:14
MOT test number	805933271983
Result	✓ Passed
Advice Rear Tyres are perishing and have small cracks appearing	
MOT #14	2016-06-06 11:38
MOT test number	965753746965
Result	✓ Passed
Advice Nearside Rear Tyre is perishing and has small cracks appearing	
Advice Front Tyre worn close to the legal limit Both (4.1.E.1)	
MOT #13	2016-06-06 10:38
MOT test number	963356779326

MOT test number	963356779326
Result	🗙 Failed
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Nearside Rear Tyre is perishing and has small cracks appearing	
FailFront All position lamps not working (1.1.A.3b)	
Advice Front Tyre worn close to the legal limit Both (4.1.E.1)	

MOT #12		2015-06-04 10:17
MOT test	number	905865955123
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



MOT #11		2014-06-03 13:28
MOT test	number	919384954174
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Nearside front tyre cracking/perishing between tread	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	
MOT #10		2014-05-31 10:49

	2014-05-51 10.49
MOT test number	586271254143
Result	🗙 Failed
Notice Under-trays fitted obscuring some underside components	
Notice Nearside front tyre cracking/perishing between tread	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Engine covers fitted obscuring some components in the engine bay	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #9	2013-06-03 13:32
MOT test number	266894353431
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #8	2012-06-02 15:13
MOT test number	698094252135
Result	✓ Passed

EX05VLL

report date: 2024-03-29



Notice



MOT #7	2012-06-02 15:13
MOT test number	298244952449
Result	🗙 Failed
Pass with rectification Offside Stop lamp not working (1.2.1b)	
МОТ #6	2011-06-03 14:07
MOT #6 MOT test number	2011-06-03 14:07 325094151174

Offside front wiper blade ends split

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5	2011-06-02 16:49
MOT test number	298003451417
Result	🗙 Failed
Notice Child seat fitted not allowing full inspection of adult belt	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice Offside front wiper blade ends split	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2010-05-22 09:46
MOT test number	140982940168
Result	✓ Passed
Notice Front brake pads getting low	





MOT #3		2010-05-22 09:46
MOT test number		952072540178
Result		🗙 Failed
Notice Front brake pade	s getting low	
Pass with rectification	Centre Rear Stop lamp not working (1.2.1b)	

MOT #2		2009-06-01 13:54
MOT test	number	182912559152
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
MOT #1		2008-05-27 13:02

MOT test number	620338448198
Result	✓ Passed



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expired: 17 January 2024	Х МОТ
Tax status			Valid until 1 August
Days left			94
MOT expiry date			17 January 2024
Full MOT history			<u>See MOT history</u>
Tax calculation			

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

-
AMP
- A

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
formed methods	
Carrient registration	







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2005-03-01
Last registration	2024-01-11
Complete history	See info



Registration #1	2005-03-01	23 mi
Registration #2	2008-05-27	10.386 mi
Registration #3	2009-06-01	12.629 mi
Registration #4	2010-05-22	14.909 mi
Registration #5	2011-06-02	19.837 mi
Registration #6	2011-06-03	19.853 mi
Registration #7	2012-06-02	24.084 mi
Registration #8	2013-06-03	30.818 mi
Registration #9	2014-05-31	38.721 mi
Registration #10	2014-06-03	38.765 mi
Registration #11	2015-06-04	47.876 mi
Registration #12	2016-06-06	53.865 mi
Registration #13	2016-06-06	53.866 mi
Registration #14	2017-06-05	61.072 mi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.117 est
Registration #21		11.777 est
Registration #22		11.777 ed
Registration #23		11.777 est
Registration #24		11.117 est
Registration #25		11.777 esi
Registration #26		11.117 est
CarCheck.co.uk		page 17/18





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1124 kg
Max. allowed weight	1530 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 18/18

Number of axles	2
Engine number	G4EA5801186