





General information

| Make | ΤΟΥΟΤΑ |
|---------------------|--------|
| Model | ESTIMA |
| Colour | White |
| Year of manufacture | 2005 |
| Gearbox | - |

Engine & fuel consumption

| Engine capacity | 2.360 cc | 0 < 101 A | |
|-----------------|----------|--|--|
| Fuel type | Petrol | 101 - 120 ^B _C 121 - 140 ^B _E | |
| | | 141 - 165 F | |

225+





Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-09-01 |
| Pictures | 15 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-08-30

15

View report



source: autotrader.co.uk









MOT history

| MOT expiry date | 2025-03-31 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 10 |
| Failed MOT tests | 5 |
| Total advice items | 18 |
| Total items failed | 18 |

| MOT #15 | 2024-03-26 12:04 |
|---|----------------------------|
| MOT test number | 929384523490 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-31 |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material From (1.1.11 (c)) | nt to rear pipe into flexi |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe into flexi (1.1.11 (c)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #14 | 2024-03-21 12:19 |
|--|----------------------|
| MOT test number | 999168734888 |
| Result | 🗙 Failed |
| Fail Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3 | .4 (b) (ii)) |
| Advice Offside Rear Brake pipe corroded, covered in grease or other material Front to (1.1.11 (c)) | rear pipe into flexi |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | |
| FailRegistration plate inscription illegible (0.1 (b)) | |
| Advice Nearside Rear Brake pipe corroded, covered in grease or other material Front to flexi (1.1.11 (c)) | o rear pipe into |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | |

| MOT #13 | 2023-03-30 14:54 |
|---|------------------|
| MOT test number | 308215957783 |
| Result | Passed |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

| MOT #12 | 2023-03-27 14:02 |
|--|------------------|
| MOT test number | 721342470648 |
| Result | 🗙 Failed |
| Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2) | (c)) |
| Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c | ;)) |





| MOT #11 | | 2022-03-21 10:50 |
|----------|--|------------------|
| MOT test | number | 363525462136 |
| Result | | Passed |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Headlamp beam images poor and slightly dim | |

| MOT #10 | 2021-04-01 07:49 |
|-----------------|------------------|
| MOT test number | 890592007105 |
| Result | ✓ Passed |

| MOT #9 | 2021-03-31 14:19 |
|--|------------------|
| MOT test number | 745325434100 |
| Result | 🗙 Failed |
| Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Fail Nearside Headlamp lens seriously defective (4.1.1 (b) (ii)) | |
| FailWindscreen washer not working (3.5 (a)) | |
| Fail Offside Headlamp lens seriously defective (4.1.1 (b) (ii)) | |

| MOT #8 | 2020-03-25 17:37 |
|---|------------------|
| MOT test number | 872397102023 |
| Result | ✓ Passed |
| Advice Nearside Child Seat fitted not allowing full inspection of adult belt middle row | |
| Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) | |





| MOT #7 | 7 | 2019-03-26 17:29 |
|--|--|------------------|
| MOT te | st number | 651483817809 |
| Result | | ✓ Passed |
| | | |
| MOT #6 | 5 | 2019-03-26 15:43 |
| MOT te | st number | 384743466627 |
| Result | | 🗙 Failed |
| Fail | Nearside Front Position lamp not working (4.2.1 (a)) | |
| Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) | | |
| Fail | Nearside Front Position lamp not working (4.2.1 (a)) | |
| Fail | Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |) |

| MOT #5 | 2018-03-29 12:59 |
|-----------------|------------------|
| MOT test number | 210440462533 |
| Result | ✓ Passed |

| MOT #4 | 2018-03-28 12:29 |
|--|------------------|
| MOT test number | 470021618249 |
| Result | 🗙 Failed |
| Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm (4.1.E.1)Fail Nearside Front Inner Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |

| MOT #3 | 2017-01-17 10:33 |
|---|---------------------|
| MOT test number | 394151832860 |
| Result | ✓ Passed |
| Advice Central Stop lamp has light sources not illuminating, but not more | e than 50% (1.2.1b) |






| MOT #2 | 2016-01-20 09:41 |
|-----------------|------------------|
| MOT test number | 764946127459 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2015-01-29 11:44 |
| MOT test number | 178809725014 |
| Result | ✓ Passed |



Tax & MOT check







Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | FET A |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| | |
| Date | Nº I |
| Category | ANNY. |
| Туре | |

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|---|-------------|
| ******** | |
| ******* | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2015-01-29 |
| Last registration | 2024-03-26 |
| Complete history | See info |



| Registration #1 | 2015-01-29 | 59.689 mi |
|------------------|------------|------------|
| Registration #2 | 2016-01-20 | 63.395 mi |
| Registration #3 | 2017-01-17 | 66.932 mi |
| Registration #4 | 2018-03-28 | 78.008 mi |
| Registration #5 | 2018-03-29 | 78.008 mi |
| Registration #6 | 2019-03-26 | 89.664 mi |
| Registration #7 | 2019-03-26 | 89.664 mi |
| Registration #8 | 2020-03-25 | 97.718 mi |
| Registration #9 | 2021-03-31 | 105.890 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.777 esi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 est |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 est |
| | | |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Additional information | |
|------------------------|-----|
| Number of seats | 8 |
| Engine number | 2AZ |