





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 LX LWB P/V
Colour	Silver
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/11



report date: 2024-03-29

MOT history

MOT #18 2022-10-11 11:14

MOT test number 570801424283

Result X Failed

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

Fail Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Fail Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill under vehicle (5.3.6 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #17 2020-12-21 12:43

MOT test number 580994853894

Result \(\sqrt{Passed} \)

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #16 2019-10-07 15:12

MOT test number 812133077248

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 2/11



the position lamps (1.1.C.1a)

GK560GF

report date: 2024-03-29

MOT #15 2019-10-03 14:10

MOT test number 282105428231

Result X Failed

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Within seat mounting radius (6.1.1 (c) (i))

Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Within radius of axle mounting (6.1.1 (c) (i))

MOT #14 2018-06-08 10:11

MOT test number 322395497370

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2017-06-06 07:10

MOT test number 180582329620

Result

Passed

Advice Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt perished (2.5.C.1a)

MOT #12 2016-07-30 07:48

MOT test number 500734305858

Result
✓ Passed

MOT #11 2016-07-30 07:48

MOT test number 877660603621

Result ★ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)

Pass with rectification Nearside Rear Registration plate lamp does not illuminate simultaneously with

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #10 2015-08-10 07:04

MOT test number 819943740506

MOT #9 2014-05-08 07:52

MOT test number 145848124162

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2013-05-28 15:58

MOT test number 927898043109

Result
✓ Passed

Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2013-04-19 10:35

MOT test number 198629203158

Result
✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2013-04-19 10:35

MOT test number 689909603154

Result X Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Exhaust system not adequately supported (7.1.1)

CarCheck.co.uk page 4/11



Result

Result

GK560GF

report date: 2024-03-29

× Failed

Passed

MOT #5 2012-04-02 17:12

525993492064 **MOT** test number

Result Passed

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #4 2012-04-02 17:12

MOT test number 498943792038

Pass with rectification Nearside Headlamp aim too high (1.8)

Pass with rectification Centre Stop lamp not working (1.2.1b)

Pass with rectification Offside Headlamp aim too low (1.8)

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #3 2011-03-19 09:51

977028671054 **MOT** test number

Advice Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2010-03-24 17:21

921123380030 **MOT** test number

Result × Failed

Pass with rectification Offside Registration plate lamp not working (1.1.5c)

Pass with rectification Nearside Registration plate lamp not working (1.1.5c)

MOT #1 2010-03-24 17:21

MOT test number 151083880042

Result Passed

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

GK560GF

report date: 2024-03-29

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FORD had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-09-26
Last registration	2022-10-11
Complete history	See info



Registration #1	2006-09-26	15 mi
Registration #2	2010-03-24	87.788 mi
Registration #3	2011-03-19	97.787 mi
Registration #4	2012-04-02	106.932 mi
Registration #5	2013-04-19	130.482 mi
Registration #6	2013-05-28	130.765 mi
Registration #7	2014-05-08	144.077 mi
Registration #8	2015-08-10	161.052 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	6U10251

CarCheck.co.uk page 11/11