



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 2 PICASSO
Colour	Red
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	135 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-08
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #27</b>	2021-10-02 09:56
<b>MOT test number</b>	125330895495
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-18
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #26</b>	2021-10-01 10:28
<b>MOT test number</b>	393831269086
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
<b>Fail</b>	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Fail</b>	Nearside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
<b>Fail</b>	Offside Power steering ram leaking (2.1.5 (a))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Fail</b>	Central Stop lamp(s) not working (4.3.1 (a) (ii))

<b>MOT #25</b>	2020-09-21 11:33
<b>MOT test number</b>	942648565632
<b>Result</b>	✓ Passed

<b>MOT #24</b>	2020-09-21 11:23
<b>MOT test number</b>	362359176415
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Central Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #23** 2020-09-21 08:57**MOT test number** 136120075416**Result** ✗ Failed

- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #22** 2019-10-03 13:29**MOT test number** 175400264344**Result** ✓ Passed**MOT #21** 2019-09-25 09:54**MOT test number** 365073293491**Result** ✗ Failed

- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #20** 2018-10-02 13:41**MOT test number** 110374565875**Result** ✓ Passed

**MOT #19** 2018-10-02 08:35**MOT test number** 719806306363**Result** ✗ Failed**Fail** Nearside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**MOT #18** 2017-10-19 10:38**MOT test number** 562009377984**Result** ✓ Passed**MOT #17** 2017-10-18 08:01**MOT test number** 820424394679**Result** ✗ Failed**Fail** Nearside Outer Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Outer Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**MOT #16** 2016-10-19 10:49**MOT test number** 836152869141**Result** ✓ Passed

**MOT #15** 2016-10-17 16:01**MOT test number** 621633886621**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported loose at joint (7.1.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Brake pipe excessively corroded front to offside rear (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2015-07-30 11:02**MOT test number** 369371115462**Result** ✓ Passed**MOT #13** 2014-07-13 11:44**MOT test number** 236004994450**Result** ✓ Passed**MOT #12** 2013-06-25 15:22**MOT test number** 969966073108**Result** ✓ Passed**MOT #11** 2013-06-25 12:31**MOT test number** 169376373175**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10** 2012-08-28 10:31**MOT test number** 647451242278**Result** ✓ Passed**Notice** Rear exhaust box corroded**Notice** N/s front tyre outer edge starting to wear**MOT #9** 2011-09-06 10:38**MOT test number** 655059241210**Result** ✓ Passed**MOT #8** 2011-09-06 10:38**MOT test number** 199009541246**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2010-09-09 10:57**MOT test number** 930152550239**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2009-09-11 10:14**MOT test number** 783774759207**Result** ✓ Passed**MOT #5** 2008-09-08 16:14**MOT test number** 183232758289**Result** ✓ Passed

**MOT #4** 2008-09-08 12:50**MOT test number** 590662958275**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2007-09-04 16:00**MOT test number** 684157447239**Result** ✓ Passed**MOT #2** 2007-09-04 16:00**MOT test number** 981697547228**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #1** 2006-08-29 15:46**MOT test number** 512041446274**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-09-09
Last registration	2021-10-02
Complete history	<a href="#">See info</a>



Registration #1	2003-09-09	19 mi
Registration #2	2006-08-29	25.322 mi
Registration #3	2007-09-04	33.255 mi
Registration #4	2008-09-08	40.137 mi
Registration #5	2008-09-08	40.137 mi
Registration #6	2009-09-11	47.720 mi
Registration #7	2010-09-09	53.125 mi
Registration #8	2011-09-06	61.149 mi
Registration #9	2012-08-28	67.158 mi
Registration #10	2013-06-25	71.544 mi
Registration #11	2013-06-25	71.544 mi
Registration #12	2014-07-13	85.674 mi
Registration #13	2015-07-30	91.038 mi
Registration #14	2016-10-17	96.479 mi
Registration #15	2016-10-17	96.479 mi
Registration #16	2016-10-17	96.479 mi
Registration #17	2016-10-17	96.479 mi
Registration #18	2016-10-17	96.479 mi
Registration #19	2016-10-17	96.479 mi
Registration #20	2016-10-17	96.479 mi
Registration #21	2016-10-17	96.479 mi
Registration #22	2016-10-17	96.479 mi
Registration #23	2016-10-17	96.479 mi
Registration #24	2016-10-17	96.479 mi
Registration #25	2016-10-17	96.479 mi
Registration #26	2016-10-17	96.479 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FX4C1972979