



 **RI73EJA**

report date: 2024-03-29

General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Blue
Year of manufacture	1997
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.980 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.4 mpg
Consumption combined	23.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-12
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-12
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	50
Total items failed	41



MOT #25	2024-03-15 14:17
MOT test number	812461376372
Result	✗ Failed

Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Fail Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced centre floor (7.1.1 (a) (i))

Advice Oil leak, but not excessive advise repair (8.4.1 (a) (i))

Fail Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Fail Nearside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Shock absorbers likely to become detached spring base corroded though (5.3.2 (a) (ii))

Advice Both front inner sills holed and corroded / not within load bearing point

Advice Brake hose has slight corrosion to ferrule both rears / past service standards / advise repair (1.1.12 (f) (i))

Fail Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Fail Offside Headlamp aim too high (4.1.2 (a))

Advice Suspension component mounting prescribed area is corroded but not considered excessive both outer sills (5.3.6 (a) (i))

Fail Offside Rear Sub-frame corroded and seriously weakened bracket (5.3.3 (b) (i))

Fail Power steering component leaking rack (2.1.5 (a))

Advice Both front and nearside rear floorpans appear to be repaired from inside the vehicle

Fail Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Advice Sub-frame corroded but not seriously weakened plus all attached suspension components (5.3.3 (b) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Rattling noise from auxiliary belt area / advise further investigation

Fail Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced only just met requirements / advise repair (6.1.1 (c) (i))

**MOT #24** 2023-03-13 12:36**MOT test number** 873898994973**Result** ✓ Passed**Advice** Offside Rear Parking brake lever worn, but not excessively (1.1.6 (b) (i))**MOT #23** 2022-02-16 16:00**MOT test number** 686324130142**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear floorpans appear to be repaired from inside the vehicle**MOT #22** 2022-01-24 11:32**MOT test number** 826202841353**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Subframe mounting prescribed area fractured significantly reducing structural strength Mounting bracket (5.3.6 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear floor pans appear to have been repaired from the inside of the vehicle**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner sill (5.3.6 (a) (i))**Fail** Power steering pump leaking (2.1.5 (a))**Fail** Tyre has a tear, caused by separation or partial failure of its structure Both rear (5.2.3 (d) (ii))

**MOT #21** 2020-12-21 16:32**MOT test number** 548116745645**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #20** 2020-12-21 16:32**MOT test number** 332260541378**Result** ✗ Failed**Pass with rectification** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Offside Front Windscreen wiper not working (3.4 (a))**MOT #19** 2020-01-06 18:14**MOT test number** 137525954953**Result** ✓ Passed**MOT #18** 2018-12-07 17:19**MOT test number** 624650456701**Result** ✓ Passed**Advice** Under side of vehicle corroded.**MOT #17** 2017-12-07 14:31**MOT test number** 707139280058**Result** ✓ Passed**Advice** Front to rear brake pipes corroded.**Advice** Offside Rear Inner Sill panel corroded.

**MOT #16**

2016-12-12 11:01

MOT test number

191814841920

Result

✓ Passed

Advice

Offside Front Lower Suspension arm has slight play in a ball joint and boot slight split (2.4.G.2)

MOT #15

2016-12-05 11:47

MOT test number

749443440337

Result

✗ Failed

Advice

Offside Rear Subframe mounting prescribed area is corroded but not considered excessive inner seal (2.4.A.3)

Fail

Nearside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)

Fail

Nearside Seat belt anchorage prescribed area is excessively corroded seat mount (5.2.6)

Fail

Offside Front Lower Suspension arm has excessive play in a ball joint and the boot is split (2.4.G.2)

Advice

Offside Front hole in drivers floor pan

Fail

Offside Front Subframe mounting prescribed area is excessively corroded (2.4.A.3)

Fail

Nearside Rear wheel bearing has excessive play (2.6.2)

MOT #14

2015-12-14 12:02

MOT test number

497205518658

Result

✓ Passed

Advice

Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice

Brake pipe slightly corroded n/s front to rear (3.6.B.2c)

Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice

Brake pipe slightly corroded o/s front to rear (3.6.B.2c)

**MOT #13**

2014-12-16 15:38

MOT test number

447110554302

Result

✓ Passed

- Advice** Front Upper Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #12

2014-12-03 11:26

MOT test number

705457134347

Result

✗ Failed

- Fail** Offside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Front Upper Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Advice** Nearside Rear Vehicle structure has slight corrosion (6.1.A.1)
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)

**MOT #11** 2013-12-11 16:45**MOT test number** 838435943359**Result** ✓ Passed**MOT #10** 2013-12-11 16:45**MOT test number** 467435243428**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2013-01-07 10:02**MOT test number** 869297803042**Result** ✗ Failed**Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Body has slight corrosion (6.1.B.2)

**MOT #8** 2012-01-09 11:51**MOT test number** 746829802051**Result** ✓ Passed**Notice** Slight play in rear nearside drive shaft universal joint**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Body has slight corrosion (6.1.B.2)**Notice** Condensation in offside head light**Advice** Centre Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2010-06-11 14:28**MOT test number** 710812460119**Result** ✓ Passed**MOT #6** 2009-04-02 11:29**MOT test number** 493272599080**Result** ✓ Passed**MOT #5** 2009-03-31 10:53**MOT test number** 981900499021**Result** ✗ Failed**Fail** Front Direction indicators incorrect colour (1.4.A.2f)**Fail** Front Power steering pipe(s) or hose(s) leaking (2.3.3b)**Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)**Fail** Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)



MOT #4	2008-07-10 11:42
MOT test number	203392498181
Result	✗ Failed
<div>Pass with rectification</div> Offside Headlamp not working on dipped beam (1.7.5a)	

MOT #3	2008-07-10 11:42
MOT test number	272322298115
Result	✓ Passed

MOT #2	2007-05-16 12:18
MOT test number	884526937110
Result	✓ Passed

MOT #1	2006-05-09 11:09
MOT test number	161009026133
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	R173EJA
Plate since	2019-03-29
Current registration	R173EJA
Plate since	2019-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1997-08-01
Last registration	2024-03-15
Complete history	See info



Registration #1	1997-08-01	27 mi
Registration #2	2006-05-09	54.994 mi
Registration #3	2007-05-16	64.004 mi
Registration #4	2008-07-10	72.899 mi
Registration #5	2009-03-31	75.500 mi
Registration #6	2009-04-02	75.517 mi
Registration #7	2010-06-11	76.004 mi
Registration #8	2012-01-09	84.548 mi
Registration #9	2013-01-07	86.122 mi
Registration #10	2013-12-11	86.377 mi
Registration #11	2014-12-03	90.320 mi
Registration #12	2014-12-16	90.320 mi
Registration #13	2015-12-14	98.112 mi
Registration #14	2016-05-20	101.277 mi
Registration #15	2016-05-20	101.277 mi
Registration #16	2016-05-20	101.277 mi
Registration #17	2016-05-20	101.277 mi
Registration #18	2016-05-20	101.277 mi
Registration #19	2016-05-20	101.277 mi
Registration #20	2016-05-20	101.277 mi
Registration #21	2016-05-20	101.277 mi
Registration #22	2016-05-20	101.277 mi
Registration #23	2016-05-20	101.277 mi
Registration #24	2016-05-20	101.277 mi
Registration #25	2016-05-20	101.277 mi



Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	CE9701071248