





## General information

Make	HYUNDAI
Model	140 CRDI ACTIVE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С








### Internet history

Entry 2	
Date	2021-09-16
Pictures	27
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-01-30
Pictures	29
Listing price	<u>View report</u>



source: yesauto.com









# MOT history

MOT expiry date	2024-08-27
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #8	2023-08-25 07	7:44
MOT test number	183178345	141
Result	V Pas	sed
Next expiry date	2024-08	3-27
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		
Advice Rear Brake pad(s) w	earing thin (1.1.13 (a) (ii))	

MOT #7	2022-08-24 14:48
MOT test number	553794253452
Result	✓ Passed

МОТ #6	2022-08-24 10:04
MOT test number	928206363485
Result	🗙 Failed
Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))	
<b>Fail</b> Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #5	2021-08-28 12:47
MOT test number	914112026273
Result	✓ Passed





MOT #4	2021-01-07 15:24
MOT test number	318774219226
Result	✓ Passed
MOT #3	2021-01-06 14:51
MOT test number	920830360764
Result	🗙 Failed
<b>Fail</b> Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #2	20	)20-01-21 14:42
MOT test	number	358713726758
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #1	2018-03-05 13:54
MOT test number	869346636278
Result	✓ Passed



Tax & MOT check

	✓ Taxed		✓ МОТ
Tax due: 1 April 2025		<b>Expires:</b> 27 August 2024	
Tax status			Valid until 1 April
Days left			337
MOT expiry date			27 August 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K K
Damage 2	AMPL
	F Store
Date	 1. F
Category	 ant
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	
**********	
*******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	







#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-01
Last registration	2023-08-25
Complete history	See info



Registration #1	2014-03-01	8 mi
Registration #2	2018-03-05	81.674 mi
Registration #3	2020-01-21	99.876 mi
Registration #4	2021-01-06	105.299 mi
Registration #5	2021-01-07	105.299 mi
Registration #6		11.117 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles
-----------------

#### **Engine number**

### D4FDDU320153